

Date: 14.03.2020  
Vehicle No: SJQ1487P  
Model: TOYOTA ALITS 1.6  
Chassis: MR053ZEE106143300-2009  
Reg.Year: 2009

Third Party Insurer: AIG  
Third Party Veh No: GBH9262K  
Date of Accident: 11.03.2020

*Not Authorized*  
*11 Sep 87800h*  
*Running After Paint 12 days*

## ESTIMATE

| NO. | DESCRIPTION                                     | QTY | UNIT | SS            | AMOUNT       | SS         |
|-----|-------------------------------------------------|-----|------|---------------|--------------|------------|
| 1   | FRONT BUMPER <i>486.50</i>                      | 1   |      | <i>Bul/cm</i> | \$650.50     | —          |
| 2   | FRONT BUMPER REINFORCEMENT <i>315</i>           | 1   |      | <i>B</i>      | \$419.50     | —          |
| 3   | FRONT BUMPER CLIPS                              | 8   |      | \$5.50        | <i>na</i>    | \$44.00    |
| 4   | FRONT BUMPER SIDE BRACKET LH                    | 1   |      |               | <i>na</i>    | \$59.20    |
| 5   | FRONT BUMPER SIDE BRACKET RH                    | 1   |      |               | <i>na</i>    | \$59.20    |
| 6   | FRONT GRILLE ASSY <i>265.10</i>                 | 1   |      | <i>na/na</i>  | \$328.30     | —          |
| 7   | FRONT GRILLE EMBLEM                             | 1   |      |               | <i>na</i>    | \$55.30    |
| 8   | FRONT GRILLE CLIPS                              | 6   |      | \$6.20        | <i>na</i>    | \$37.20    |
| 9   | FRONT HEADLAMP LH <i>583.60</i>                 | 1   |      | <i>mg/cm</i>  | \$657.90     | —          |
| 10  | FRONT HEADLAMP RH <i>583.60</i>                 | 1   |      | <i>mg/cm</i>  | \$657.90     | —          |
| 11  | FRONT SUPPORT PANEL ASSY                        | 1   |      |               | <i>R</i>     | \$764.10   |
| 12  | FRONT BONNET LOCK                               | 1   |      |               | <i>na</i>    | \$94.30    |
| 13  | FRONT BONNET LOCK STAY PANEL                    | 1   |      |               | <i>B</i>     | \$121.60   |
| 14  | FRONT AIRCON CONDENSOR                          | 1   |      | <i>Bul/Pn</i> | \$1,121.70   | —          |
| 15  | FRONT RADIATOR                                  | 1   |      |               | <i>na</i>    | \$1,680.50 |
| 16  | REAR BOOT LID <i>794.40</i>                     | 1   |      |               | <i>B</i>     | \$859.70   |
| 17  | REAR BOOT LID EMBLEM                            | 1   |      |               | <i>na</i>    | \$46.40    |
| 18  | REAR BOOT LID "1.6" EMBLEM                      | 1   |      |               | <i>na</i>    | \$42.60    |
| 19  | REAR BOOT LID "COROLLA" EMBLEM                  | 1   |      |               | <i>na</i>    | \$47.60    |
| 20  | REAR BOOT LID "ALTIS" EMBLEM                    | 1   |      |               | <i>na</i>    | \$48.80    |
| 21  | REAR BOOT LID CHROME GARNISH <i>203.20</i>      | 1   |      |               | <i>CRA</i>   | \$437.80   |
| 22  | REAR BOOT LID INNER LOCK                        | 1   |      |               | <i>na</i>    | \$144.70   |
| 23  | REAR BOOT LID BACK UP LAMP LH                   | 1   |      |               | <i>CRA</i>   | \$218.10   |
| 24  | REAR BOOT LID BACK UP LAMP RH                   | 1   |      |               | <i>CM</i>    | \$218.10   |
| 25  | REAR BOOT LID RUBBER                            | 1   |      |               | <i>na/na</i> | \$231.10   |
| 26  | REAR END PANEL <i>691.40</i>                    | 1   |      |               | <i>B</i>     | \$793.60   |
| 27  | REAR END PANEL UPPER COVERING                   | 1   |      |               | <i>na</i>    | \$194.10   |
| 28  | REAR SPARE TYRE PANEL UPPER BOARD <i>276.60</i> | 1   |      |               | <i>CM</i>    | \$297.90   |
| 29  | REAR BOOT HINGE LH                              | 1   |      |               | <i>R</i>     | \$78.90    |
| 30  | REAR BOOT HINGE RH                              | 1   |      |               | <i>R</i>     | \$78.90    |
| 31  | REAR BUMPER <i>561.40</i>                       | 1   |      |               | <i>B</i>     | \$735.20   |
| 32  | REAR BUMPER IMPACT ABSORBER                     | 1   |      |               | <i>CM</i>    | \$152.60   |
| 33  | REAR BUMPER SIDE BRACKET LH                     | 1   |      |               | <i>B</i>     | \$93.90    |
| 34  | REAR BUMPER SIDE BRACKET RH                     | 1   |      |               | <i>B</i>     | \$93.90    |
| 35  | REAR BUMPER REINFORCEMENT SUPPORT BRACKET RH    | 1   |      |               | <i>R</i>     | \$51.30    |
| 36  | REAR BUMPER CLIPS                               | 8   |      | \$5.50        | <i>na</i>    | \$44.00    |

*8775.60*

### Head office

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

### Branch

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 Fax: (+65) 6481 1011

### Branch

551 Upper Thomson Road Singapore 574415  
Tel: (+65) 6452 8868 Fax: (+65) 6452 9223



Date: 14.03.2020  
Vehicle No: SJQ1487P  
Model: TOYOTA ALITS 1.6  
Chassis: MR053ZEE106143300-2009  
Reg. Year: 2009

Third Party Insurer: AIG  
Third Party Veh No: GBH9262K  
Date of Accident: 11.03.2020

|    |                         |     |   |    |          |   |
|----|-------------------------|-----|---|----|----------|---|
| 37 | REAR TAIL LAMP LH       | 342 | 1 | CM | \$566.30 | — |
| 38 | REAR TAIL LAMP RH       | 342 | 1 | CM | \$566.30 | — |
| 39 | FRONT FENDER LH         |     | 1 |    | REPAIR   |   |
| 40 | REAR TAIL LAMP PANEL LH |     | 1 |    | REPAIR   |   |
| 41 | REAR TAIL LAMP PANEL RH |     | 1 |    | REPAIR   |   |
| 42 | REAR QUARTER PANEL LH   |     | 1 |    | REPAIR   |   |
| 43 | REAR QUARTER PANEL RH   |     | 1 |    | REPAIR   |   |

Finalise: Parts: \$7431.15  
Nett: \$7425  
Labour: \$3190  
Jump Sum: \$11046.15 less 20% — \$8836.92 → \$8830 #

|             |             |           |
|-------------|-------------|-----------|
| SUB TOTAL   | \$12,793.00 | \$9908.20 |
| LESS 25%    | -\$3,198.25 | \$2477.05 |
| PARTS TOTAL | \$9,594.75  | \$7431.15 |

| NO.       | SPECIAL NETT                 | QTY | UNIT S\$ | AMOUNT S\$  |           |
|-----------|------------------------------|-----|----------|-------------|-----------|
| 1         | FRONT NUMBER PLATE           | 1   |          | RM \$40.00  | ✓         |
| 2         | FRONT NUMBER PLATE HOLDER    | 1   |          | RM \$40.00  | ✓         |
| 3         | FRONT RADIATOR COOLANT       | 1   |          | RM \$60.00  | X         |
| 4         | REAR BUMPER REVERSE SENSOR   | 1   |          | CM \$350.00 | 2001      |
| 5         | REAR END PANEL JOINT SEALANT | 1   |          | RM \$30.00  | ✓         |
| S/N TOTAL |                              |     |          | \$520.00    | \$445 310 |

## LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT & REAR ACCIDENT AREAS & ETC.

\$1,300.00 1200

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT FENDER RH, FRONT SUPPORT PANEL, REAR BOOT LID, REAR END PANEL, REAR TAIL LAMP PANEL LH, REAR TAIL LAMP RH, REAR QUARTER PANEL LH, REAR QUARTER PANEL RH & ETC.

\$2,200.00 1800

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

\$60.00 501

LABOUR CHARGES TO CHECK WIRING & ELKKA Auto-Consultants hence notify the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

\$60.00 401

TO REFILL AIR CON GAS & VACUUM.

\$100.00 ✓

TingAn

LABOUR TOTAL \$3,720.00 \$3190 ✓

TOTAL \$13,834.75

Head office

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Selegie Road Singapore 554500  
Tel: (+65) 6481 1019 Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415  
Tel: (+65) 6452 6868 Fax: (+65) 6452 9223

