



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2106034
INV Date 26/08/2021
Reference CC4/LPC20004075/Kea3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SJM 753Z
Insured Veh. GBA 6930Y
Claim No. 19/20/20/VC06/023201
Policy No. Z/19/VC06/104909
Accident Date 10/03/2020
Inspection Date 09/09/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CC4/LPC20004075/Kea3q2

Date: 26/08/2021

Code: LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 6930Y	Veh. Inspected	SJM 753Z
Policy No.	Z/19/VC06/104909	Coverage (\$)	0.00
Claim No.	19/20/20/VC06/023201	Excess (\$)	0.00
Assign From	GERALD	Assign Date	16/03/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA STREAM (A)	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JHMRN68408S205840	Colour	METALLIC SILVER
Odometer	144093 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/65 R15	WEST LAKE	9 mm
L/H Front Tyre	205/65 R15	WEST LAKE	9 mm
R/H Rear Tyre	205/65 R15	WEST LAKE	9 mm
L/H Rear Tyre	205/65 R15	WEST LAKE	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/03/2020	Inspection Date	09/09/2020
Survey held at	K KIM HIN AUTO PTE LTD 160 SIN MING DRIVE #02-20 SIN MING AUTO CITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJM 753Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (WCP)	DENTED / CRACKED	520.00	520.00
1	FRONT BUMPER REINFORCEMENT (BENT)(WCP)	BENT	185.00	185.00
2	FRONT BUMPER SIDE RETAINER (LH/RH) @\$16.00(WCP)	SERVICEABLE	32.00	-
10	FRONT BUMPER CLIPS @\$1.50 (WCP)	NECESSARY	15.00	15.00
2	HEADLAMP ASSY (NON-HID) (LH/RH) @\$380.00(WCP)	SERVICEABLE	760.00	-
2	HEADLAMP LOWER BRACKET (LH/RH) @\$50.00(WCP)	SERVICEABLE	100.00	-
1	FRONT GRILLE (WCP)	SERVICEABLE	170.00	-
1	FRONT GRILLE CHROME(WCP)	SERVICEABLE	140.00	-
1	FRONT GRILLE 'H' LOGO (WCP)	SERVICEABLE	25.00	-
	COST PLUS 15%		292.05	108.00
			2,239.05	828.00
<u>LABOUR</u>				
	TO REMOVE ,CUT OUT DAMAGED PARTS,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW AFFECTED PARTS.		450.00	200.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		400.00	200.00
	TO FOCUS HEADLAMPS. TO CHEKC FRONT WIRING AND LIGHTING OPERATION.		50.00	10.00
			900.00	410.00
GRAND TOTAL			3,139.05	1,238.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,000.00

Report Ref No. CC4/LPC20004075/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJM 753Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJM 753Z

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJM 753Z

RE-INSPECTION

