

TP Lompac

S&P

Appt: 8/4 (Wed)

Ke

CO. REG. NO: 199402370D
GST NO: M2-0123250-3



金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 31088

Vehicle Insured : GBA 6930 Y
Accident Date : 10-Mar-2020

Date : 16-Mar-2020

Our Ref : 020133 (LONPAC) / SANDRA

PAGE : 1

JESSICA HEATH QUANCE (MS)
Singapore

*Not Arranged
to Rep & Book
Resurvey After Paint 2 days*

ESTIMATED COST OF REPAIR FOR HONDA STREAM 1.8L A (2008) SJM753Z

1 pc front bumper	Delicom	520.00	c	✓
1 pc front bumper reinforcement bt	No Delicom	185.00	c	X ✓
2 pcs front bumper side retainer (LH/RH)	@ S\$ 16.00	32.00	c	X
10 pcs front bumper clips	@ S\$ 1.50	15.00	c	✓
2 pcs headlamp assy (non-HID)(LH/RH)	@ S\$ 380.00	760.00	c	X <i>2/15 X</i>
2 pcs headlamp lower bracket (LH/RH)	@ S\$ 50.00	100.00	c	X
1 pc front grille		170.00	c	X
1 pc front grille chrome		140.00	c	X
1 pc front grille 'H' logo		25.00	c	X
		1,947.00		
Add 15% :		292.05		
		2,239.05		

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.

*720
+ 15%

828 (18 parts)
+ 410 (Labour)

1238
- 20%

\$990.40*

2 cool 450.00
2 cool 400.00
1 cool 50.00

Total : S\$ 3,139.05
=====

To putty and respray on affected portions.

To focus headlamps. To check front wiring and lighting operation.

Singapore Dollars Three Thousand One Hundred and Thirty Nine and Cents Five Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants hereby certify that the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation.
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: