

22/03/2002

ASS. REC. BY:

REF: CS/MSG 20004097/Hwf3/12 Special Instruction: ✓

Surveyor: Hock An

ASSIGNMENT (Office)

From (Person): Jowyn King Mei Ling of MS14 Date/Time: 17.3.20 9:44AM

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGL 8229J Insured: SJA 1651Rat Workshop m/s Xin Yi Auto Tel: 98391555of BK 8 Premier @ 19M Bukt A1 P 115-23Policy No: 80314263 Claim No: 621837

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 15.3.200
(Client's Record)CA / REV / REP. / REV 24HRS hp

H.O.D. Endorsement: _____

Date/Time: 17/3/20 10:15AM Person Contacted: Xin Yi Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SGL 8229J - NA/INC 140.317/r3 D.O.A - 13/01/2018
	SJA 1651R - CS3 / FWD 190128/5/ Gcf352 D.O.A - 13/07/2019
18/3/20	Informed Jowyn pending workshop est by merimen
26/3/20	LS \$3550 confirmed by email (Ref 6660.80, 6510)
26/3/20	Send preli revised via merimen

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Mar 2020		17 Mar 2020 09:44 Assign				New Assignment Cancel Case

Main		Reference		Claim Details		Documents		Show All	
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	NG BOON HEON, ID: S1660971D								
Main Claimant:	CHIA LEE HUAT, ID: S1472799Z								
Vehicle Reg. No.:	SGL8229J			Date of Loss:	15/03/2020 13:00 - :59 [161 Months and 16 Days From LTA Reg Date (Man Yr)]				
Claim Type:	TP			Policy/Cover Note No.:	80314263 Coverage: 28/11/2019 - 27/11/2020				
Vehicle Reg. No. (Insured):	SJA1651R			Policy No. (Claimant):					
				Excess:					
Repairer:	Xin Yin Auto (HQ) BLK 8 PREMIER @ KAKI BUKIT AVE 4 #05-23, 415875 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 18/03/2020]								
Adj Asg. Remarks:	on WP, Liab: NR, Disagree on SJE, Contact: Ms Yi Xin @ 9839 1555. Please contact us ASAP if you cannot attend this assignment.								
ASSOCIATED MAIL RECEIVED								View All	Compose Case Mail
There are no mail for this case.									
ALL ASSOCIATED TASKS								View All	Search Tasks
								Create New Task	Complete
Due Date:	Priority	Type	Task Group:	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Jowyn Tay Mei Ling	Date: 26 Mar 2020

Preliminary Advice

Insured Vehicle No	: SJA1651R	Accident Date	: 15/03/2020
TP Vehicle No	: SGL8229J	Assignment Date	: 17/03/2020
Make	: TOYOTA CAMRY	Est. Duration of Repair	: 5
Date of Inspection	: 17/03/2020		
Inspection At	: XIN YIN AUTO (HQ) BLK 8 PREMIER @ KAKI BUKIT AVE 4 #05-23 SINGAPORE 415875		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,210.80
Revised Amount	:S\$	4,435.43
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,435.43
Lump Sum Repair	:S\$	3,550.00 (LUMP SUM)

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

View Sent Message

This mail is associated with :

***SGL8229J (621837)**

[SJA1651R]

TP

CHIA LEE HUAT

Mar 15 2020 1:00PM

[NG BOON HEON]

Xin Yin Auto

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **18/03/2020 09:38 AM**.

To SGSGJTML

Subject TP SURVEY SGL 8229J

Dear Jowyn,

Please be informed that we have inspected the vehicle SGL 8229J on 17/3/2020

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	799Z
Vehicle Details	
Vehicle No.:	SGL8229J
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Mar 2020
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.0 AUTO ABS AIRBAG
Primary Colour:	Beige
Manufacturing Year:	2006
Engine No.:	1AZE008826
Chassis No.:	MR053BK4107001835
Maximum Power Output:	108.0 kW (144 bhp)
Open Market Value:	\$28,129.00
Original Registration Date:	28 Sep 2006
First Registration Date:	28 Sep 2006
Transfer Count:	3
Actual ARF Paid:	\$30,942.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 May 2026
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$46,048.00
COE Rebate Amount:	\$28,569.00
Total Rebate Amount:	\$28,569.00

The information contained herein is correct as at 17 Mar 2020

OK

Lower Costs With Core Pricing

Learn to Trade, Practice With \$100,000 Virtual Money. Open A Demo Accto Today! OANDA

Connect with Facebook

HOME

NEW CARS

USED CARS

COMMERCIAL VEH

RENTAL CARS

SELL CARS

MOTOR DIRECTORY


Home > Used Cars > Toyota Camry 2.0A (COE till 05/2026)

TOYOTA CAMRY 2.0A (COE TILL 05/2026)

OVERVIEW

GALLERY

Share



Price	\$35,800
Registration Date	25-May-2006
COE Remaining	6yrs 2mths 7days
Manufactured	2006
Mileage	119,379 km
No. of Owners	3
Transmission	Auto
Engine Capacity	1,998 cc
COE	\$46,048
OMV	\$28,545
Paper Value	\$28,499
Depreciation	\$5,780 / year
Type	Luxury Sedan

Benefit from
first-class
execution

Switch to S

Trading in financial instruments car risks and may not be suitable for y



USED CAR SEARCH

Car Make / Car Model

Category	Car Type
Transmission	Engine Cap
Min Price	Max Price
Min Depreciation	Max Depre
From Reg Year	To Reg Year

VEHICLE TOOLS

Get expert assessment on the condi of this car with STA Evaluation

COE Results	Loan Calc
Post an Ad	Road Tax
Carpark Rates	Car Insur

Good Condition, Regular Serviced, Low Mileage, Low Depreciation, Low Fuel Consumption, Leather Seats, Sports Rims, Reverse Sensors And Camera, No Repairs Needed, Bank Or In House Loan Available.

Features: 2.0l 4 Cylinders 16 Valves Dohc Vvti Engine Automatic Transmission Srs Airbags Abs Multi Function Steering Rear Zircon Cruise Control.

Accessories: Sports Rims, Factory Fitted Audio System, Reverse Sensors, Leather Seats, Auto Headlight, Retractable Side Mirrors And Indicators.

More info on Toyota Camry(2001-2006) |

For full set of photos and payment break-down, <http://www.sgcarmart...=893160&DL=1350>

Status: Available | Category: COE Car

Date Posted: 12-Mar-2020 | Date Updated: 13-Mar-2020

WV - 35000
PV - 28569
NV - 6400

SELLER INFORMATION

Desmond Auto Trading

210 Turf Club Road Lot A46 (map)

64631556

LIM	98333308
ROY	86499000
JACKY	98309977

"SAY YOU SAW THIS AD ON STCARS.SG!"



RELATED DISCUSSION

+ View All "Camry" Discussion

Topic Title	Replies	Last Action
8th Gen Toyota Camry (XV70)	415	14-Mar-2020
Toyota Camry	750	18-Feb-2020
Anyone bought latest Camry Hybrid? Review ho bo?	64	02-Oct-2019
JDM Camry From P1 or Thai Camry from BM	49	02-Jun-2019
2.5 camry hybrid vs 2.5 mazda 6	94	28-Jan-2019

<https://www.stcars.sg/singapore-car/used-cars/toyota-camry-2-0a-coe-till-05-2026-a893160/overview>

Singles50 in Singapore

www.singles50.sg

LIFESTYLE

Food & Beverage	Health Cc
Home Needs	IT Produ

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/03/2020 15:48
Date Of Accident	15/03/2020 13:20
Exact Location Of Accident	ANG MO KIO AVE 3 TRAFFIC JUNCTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGL8229J
Insured/Policyholder	
Name Of Registered Owner	CHIA LEE HUAT
NRIC No	SXXXX799Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98190056
Alternative Phone No	OTHERS-98190056

Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY 2.0 AUTO ABS AIRBAG
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5073564972-04
Cover Note Number	

Driver

Name of Driver	CHIA LEE HUAT
NRIC No	SXXXX799Z
Date Of Birth	19/03/1961
Occupation	INDOOR
Date Of Driving Pass	30/10/1981
Driving Experience	38 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98190056
Fax Number	
Contact Number	OTHERS-98190056
Email Address	NOEMAIL

Address	BLK 909 #13-108 HOUGANG STREET 91
Postcode	530909
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CHUA BEE GEOK GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED;

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJA1651R
Vehicle Make/Model/Colour	TOYOTA / COROLLA ALTIS 1.6 AUTO
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:


IGAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vac@igac.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

16 MAR 2020

Accident Sketch Plan

SKETCH PLAN



A: S6L 8229J

B: SJA1651R

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was waiting to turn left at the traffic junction at Ang Mo Kio Avenue 3, when vehicle B: SJA1651R hit the rear of my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature

Date & Time:

[Signature]

Driver's Signature

(if driver is not the policyholder)

Date & Time:

IDAC KANBUKIT (VAC)

23 Kaki Bukit Ave 4 #02-02

Singapore 415933

Tel: 67416697 Fax: 67482305

E-mail: canb@idac.com.sg

Reporting Centre Personnel's Signature

Name:

NRIC/VIN No.:

16 MAR 2020

Accident Photo





Thank you

Kasturi D/o Devasahayam has successfully logged out.

Your last login date and time was 07 Feb 2020, 13:33:31.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please CLEAR YOUR CACHE after each session.

Session Transaction History

S.No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Trans.
1	Vehicle	SKZ6B9X	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SGL8229J TOYOTA Model CAMRY 2.0 AUTO ABS AIRBAG

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy ✓ CRU	\$ 850.00 560.80 ✓
2	1	Rear reinforcement ✓ BT	\$ 650.00 400.70 ✓
3	1	Rear bumper left bracket X (R)	\$ 85.00
4	1	Rear bumper right bracket X (R)	\$ 85.00
5	1	Rear bumper left retainer ✓ CRU	\$ 65.00 ✓
6	1	Rear bumper right retainer X (SVC)	\$ 65.00
6	1	Rear left bumper reflector ✓ CRU	\$ 88.00 ✓
7	1	Rear right bumper reflector X (SVC)	\$ 88.00
8	1	Rear tailgate assy Boot lid ✓ BT	\$ 1,200.00 1020.80 ✓
9	1	Rear tailgate centre logo ✓ CRU	\$ 125.00 68.80 ✓
10	1	Rear tailgate emblem ✓ CRU	\$ 85.00 65.80 ✓
11	1	Rear tailgate weatherstrip X (SVC)	\$ 275.00
12	1	Rear tailgate lock mechanism ✓ Jm	\$ 235.00 200.60 ✓
13	1	Rear tailgate inner trim board X (SVC)	\$ 285.00
14	1	Rear tailgate outer garnish X (SVC)	\$ 250.00
15	1	Rear tailgate no plate lamp X (SVC)	\$ 95.00
16	1	Rear left taillamp ✓ CRU	\$ 585.00 416.30 ✓
17	1	Rear right taillamp ✓ CRU	\$ 585.00 416.30 ✓
18	2	Rear tailgate damper holder X (SVC)	\$ 275.00
19	1	Rear end lower panel top cover ✓ CRU	\$ 285.00 210.80 ✓
20	1	Rear exhaust assy local Repair (SCR) ✓	\$ 850.00 150.00 ✓
21	1	Rear exhaust rubber mounting X (SVC)	\$ 45.00
			\$ 7,151.00
		Less 20% 250/0	\$ 1,430.20
		Parts	\$ 5,720.80

SN



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SGL8229J TOYOTA Model CAMRY 2.0 AUTO ABS AIRBAG

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	10	Rear bumper clips ✓ <i>acc</i>	\$ 80.00 25 ✓
2	6	Rear end lower panel top garnish clips ✓ <i>acc</i>	\$ 50.00 15 ✓
3	8	Rear tailgate inner trim board clips ✓ <i>acc</i>	\$ 50.00 15 ✓
4	6	Rear tailgate outer garnish clips X (suv)	\$ 30.00
5	8	Rear left fender inner side garnish clips X (suv)	\$ 30.00
6	8	Rear right fender inner side garnish clips X (suv)	\$ 30.00
7	6	Rear left fender inner cowling clips X (suv)	\$ 30.00
8	6	Rear right fender inner cowling clips X (suv)	\$ 30.00
9	1	Rear floor panel sealant X (suv)	\$ 120.00
10	2	Rear bumper reverse sensor ✓ <i>short</i>	\$ 250.00 200 ✓
11	1	Rear no plate with garnish } <i>son</i>	\$ 80.00
12	1	Number plate with casing }	\$ 50.00 30 ✓
			\$ 830.00
Total parts			\$ 6,550.80



Xin Yun Auto Private Limited
 辛运汽车服务有限公司
 Tel: 6634 0858 Email: xinyunautol@gmail.com
 Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SGL8229J TOYOTA Model CAMRY 2.0 AUTO ABS AIRBAG

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts, including rear end panel	\$ 1,400.00 650 ✓
2	To putty and spray painting damaged area, bumper, front end panel	\$ 1,200.00 600 ✓
3	To apply anti rust proofing to front affected area	\$ 120.00 25 ✓
4	To remove and install tailgate lock mechanism assy with labor	\$ 100.00
5	To check rear lighting and wiring	\$ 50.00 30 ✓
6	To apply anti rust proofing to rear affected area (R.P.T)	\$ 120.00
7	To remove and install rear bumper reverse sensor	\$ 50.00 20 ✓
8	To remove and install rear exhaust muffler assy.	\$ 120.00 40 ✓
9	To conduct chassis alignment. X	\$ 350.00
10	To conduct wheel alignment. X	\$ 120.00
Total labour :		\$ 3,660.00

Total parts : 6,550.80
 Total labour : 3,660.00
 Total repair cost : 10,210.80

L&K Auto Consultants hereby notify the Repairs of the following:

- To resolve the vehicle body damage
- To display damaged parts using pictures
- Parts prices are subject to change
- Third party survey must be done (if applicable)
- No illegal modification allowed
- Supplemental estimate must be done with and without third party survey (if applicable)

Authorised by Receiver
 Signature

L/S repair without pre-judgment
 Resurvey after paint
 S. day (11/11/17)
 H. ANN 67418434 / 85311883
 And ANN@lklauto.com
 17/3/20 2.40pm

Parts 3513.90
 Parts less 25%
 2635.42
 435
 1365
 4435.42
 20%
 3548.33
 L/S Amt
 \$ 3550.8

Veron Chen (LKKAuto)

From: Hock Ann (LKK Auto)
Sent: Thursday, 26 March 2020 4:54 PM
To: Xin Yun Auto
Cc: Veron Chen (LKKAuto); SUR
Subject: Re: SGL 8229J FINALIZED

Dear yi xin,

Good day, o.k will be process base on finalized total amount COR \$ 3550 L/SUMP REPAIR and DOR 5 days close.

Noted : All finalized document > LOA ,LOD,DV,LTA need direct send to (MSIG INSURANCE CLAIM DEPT)

Thanks.

Best Regards,
Hock Ann | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Xin Yun Auto <xinyunauto1@gmail.com>
Sent: Thursday, March 26, 2020 4:02 PM
To: Hock Ann (LKK Auto) <HockAnn@lkkauto.com>
Cc: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: Re: SGL 8229J FINALIZED

Thanks a lot Hock Ann,
We agree and will proceed to close the case.

Thank you and have a nice day,
Yi Xin
Xin Yun Auto
Tel/Fax: 6634 0858
Mobile: 9839 1555
Email: xinyunauto1@gmail.com

On Thu, Mar 26, 2020 at 2:16 PM Hock Ann (LKK Auto) <HockAnn@lkkauto.com> wrote:

Dear yi xin,

Good day, kindly refer vehicle SGL 8229J TOYOTA CAMRY finalized total L/SUMP amount
COR - \$ 3550

DOR - 5 DAYS

kindly refer, if agree total L/SUMP amount and repair days we be close case.

please reply update soon asap.

thanks.

Best Regards,

Hock Ann | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Xin Yun Auto <xinyunauto1@gmail.com>

Sent: Thursday, March 19, 2020 11:26 AM

To: Hock Ann (LKK Auto) <HockAnn@lkkauto.com>

Cc: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Subject: Re: SGL8229J Estimate

Hi Hock Ann,

Thanks for your email, vehicle will be ready by today, kindly arrange and come for final picture after 3pm.

Thank you and best regards,

Yi Xin

Xin Yun Auto

Tel/Fax: 6634 0858

Mobile: 9839 1555

Email: xinyunauto1@gmail.com

On Thu, Mar 19, 2020 at 9:21 AM Hock Ann (LKK Auto) <HockAnn@lkkauto.com> wrote:

Dear xin yun,

Good day, received I will refer back the resurvey photographs marking adjust to yours the estimate.

we be update soon.

Thanks.

Best Regards,

Hock Ann | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Xin Yun Auto <xinyunauto1@gmail.com>

Sent: Wednesday, March 18, 2020 5:02 PM

To: Hock Ann (LKK Auto) <HockAnn@lkkauto.com>

Subject: SGL8229J Estimate as Single-Joint

Dear Hock Ann,

Good afternoon, kindly refer to attached SGL8229J our estimate for your reference.
Please let us have your marking as single-joint expert. Thank you.

Thank you and best regards,

Yi Xin

Xin Yun Auto

Tel/Fax: 6634 0858

Mobile: 9839 1555

Email: xinyunauto1@gmail.com

Veron Chen (LKKAUTO)

From: Xin Yun Auto <xinyunauto1@gmail.com>
Sent: Thursday, 26 March 2020 4:03 PM
To: Hock Ann (LKK Auto)
Cc: Veron Chen (LKKAUTO); SUR
Subject: Re: SGL 8229J FINALIZED

Thanks a lot Hock Ann,
We agree and will proceed to close the case.

Thank you and have a nice day,
Yi Xin
Xin Yun Auto
Tel/Fax: 6634 0858
Mobile: 9839 1555
Email: xinyunauto1@gmail.com

On Thu, Mar 26, 2020 at 2:16 PM Hock Ann (LKK Auto) <HockAnn@lkkauto.com> wrote:

Dear yi xin,

Good day, kindly refer vehicle SGL 8229J TOYOTA CAMRY finalized total L/SUMP amount

COR - \$ 3550

DOR - 5 DAYS

kindly refer, if agree total L/SUMP amount and repair days we be close case.

please reply update soon asap.

thanks.

Best Regards,
Hock Ann | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Xin Yun Auto <xinyunauto1@gmail.com>
Sent: Thursday, March 19, 2020 11:26 AM
To: Hock Ann (LKK Auto) <HockAnn@lkkauto.com>
Cc: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Subject: Re: SGL8229J Estimate

Hi Hock Ann,

Thanks for your email, vehicle will be ready by today, kindly arrange and come for final picture after 3pm.
Thank you and best regards,
Yi Xin

Xin Yun Auto
Tel/Fax: 6634 0858
Mobile: 9839 1555
Email: xinyunauto1@gmail.com

On Thu, Mar 19, 2020 at 9:21 AM Hock Ann (LKK Auto) <HockAnn@lkkauto.com> wrote:

Dear xin yun,

Good day, received I will refer back the resurvey photographs marking adjust to yours the estimate.
we be update soon.

Thanks.

Best Regards,
Hock Ann | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Xin Yun Auto <xinyunauto1@gmail.com>
Sent: Wednesday, March 18, 2020 5:02 PM
To: Hock Ann (LKK Auto) <HockAnn@lkkauto.com>
Subject: SGL8229J Estimate as Single-Joint

Dear Hock Ann,

Good afternoon, kindly refer to attached SGL8229J our estimate for your reference.
Please let us have your marking as single-joint expert. Thank you.

Thank you and best regards,
Yi Xin
Xin Yun Auto
Tel/Fax: 6634 0858
Mobile: 9839 1555
Email: xinyunauto1@gmail.com

...CLAIM SUBFOLDER...(Pending for Survey Report)














































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Mar 2020		17 Mar 2020 09:44 Edit Adj Rpt	S\$3,550.00 Edit Estimates	S\$3,550.00 View Rpt		Pending for Survey Report Cancel Case




















Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	NG BOON HEON, ID: S1660971D								
Main Claimant:	CHIA LEE HUAT, ID: S1472799Z								
Vehicle Reg. No.:	SGL8229J	Date of Loss:	15/03/2020 13:00 - :59 [161 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 621837	Policy/Cover Note No.:	80314263QMX (Comprehensive) Coverage: 28/11/2019 - 27/11/2020						
Vehicle Reg. No. (Insured):	SJA1651R	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Xin Yin Auto (HQ) BLK 8 PREMIER @ KAKI BUKIT AVE 4 #05-23, 415875 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 16/04/2020]								
Adj Asg. Remarks:	on WP. Liab: NR. Disagree on SJE. Contact: Ms Yi Xin @ 9839 1555. Please contact us ASAP if you cannot attend this assignment.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents















*SGL8229J (621837)
[SJA1651R]
TP
CHIA LEE HUAT
Mar 15 2020 1:00PM
[NG BOON HEON]
Xin Yin Auto

Upload Documents			Upload Photos		Compose New Letter		View View in Browser	
Assessment Reports							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	26/03/20 16:51	Adjuster Immediate Advice		1 Load HTM				
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	17/03/20 19:22	Chassis Number		1 Load JPG	<input checked="" type="checkbox"/>			
2	17/03/20 19:22	Odometer Reading		1 Load JPG	<input checked="" type="checkbox"/>			
3	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
4	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
5	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
6	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
7	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
8	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
9	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
10	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
11	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
12	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
13	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
14	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
15	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
16	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
17	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
18	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
19	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
20	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
21	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
22	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
23	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
24	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
25	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
26	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
27	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
28	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
29	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
30	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
31	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
32	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
33	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			
34	17/03/20 19:23	General View		1 Load JPG	<input checked="" type="checkbox"/>			

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	17/03/20 19:23	General View	 Load JPG	<input checked="" type="checkbox"/>
36	17/03/20 19:23	General View	 Load JPG	<input checked="" type="checkbox"/>
37	17/03/20 19:24	General View	 Load JPG	<input checked="" type="checkbox"/>
38	17/03/20 19:24	General View	 Load JPG	<input checked="" type="checkbox"/>
39	17/03/20 19:24	General View	 Load JPG	<input checked="" type="checkbox"/>
40	17/03/20 19:24	General View	 Load JPG	<input checked="" type="checkbox"/>
41	17/03/20 19:24	General View	 Load JPG	<input checked="" type="checkbox"/>
42	17/03/20 19:24	General View	 Load JPG	<input checked="" type="checkbox"/>
43	17/03/20 19:24	General View	 Load JPG	<input checked="" type="checkbox"/>
44	17/03/20 19:24	General View	 Load JPG	<input checked="" type="checkbox"/>
45	17/03/20 19:24	General View	 Load JPG	<input checked="" type="checkbox"/>
46	17/03/20 19:24	General View	 Load JPG	<input checked="" type="checkbox"/>
47	17/03/20 19:24	General View	 Load JPG	<input checked="" type="checkbox"/>
48	17/03/20 19:24	General View	 Load JPG	<input checked="" type="checkbox"/>
49	17/03/20 19:24	General View	 Load JPG	<input checked="" type="checkbox"/>
50	17/03/20 19:24	General View	 Load JPG	<input checked="" type="checkbox"/>
51	17/03/20 19:24	General View	 Load JPG	<input checked="" type="checkbox"/>
52	17/03/20 19:24	General View	 Load JPG	<input checked="" type="checkbox"/>
53	17/03/20 19:24	General View	 Load JPG	<input checked="" type="checkbox"/>
54	17/03/20 19:24	General View	 Load JPG	<input checked="" type="checkbox"/>
55	17/03/20 19:24	General View	 Load JPG	<input checked="" type="checkbox"/>
56	17/03/20 19:24	General View	 Load JPG	<input checked="" type="checkbox"/>
57	17/03/20 19:24	General View	 Load JPG	<input checked="" type="checkbox"/>
58	17/03/20 19:24	General View	 Load JPG	<input checked="" type="checkbox"/>
59	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	26/03/20 16:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
81	26/03/20 16:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
82	26/03/20 16:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
83	26/03/20 16:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	26/03/20 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	27/03/20 07:42	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
95	27/03/20 07:42	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
96	27/03/20 07:42	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
97	27/03/20 07:42	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
98	27/03/20 07:42	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
99	27/03/20 07:42	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
100	27/03/20 07:42	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
101	27/03/20 07:42	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	17/03/20 09:24	Disagree on SJE	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	16/03/20 16:06	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	16/03/20 15:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	16/03/20 15:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	16/03/20 15:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	16/03/20 15:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	16/03/20 15:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	16/03/20 15:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	16/03/20 15:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	16/03/20 15:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	16/03/20 15:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	16/03/20 16:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	16/03/20 16:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	16/03/20 16:06	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	16/03/20 16:06	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20004097/HVF3E2

Date: 01/04/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 80314263QMX

Claimant Vehicle No : SGL8229J

Insured Vehicle No : SJA1651R

Date of Loss: 15/03/2020

Nature of Claim: TP

Claim No: 621837

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGL8229J

Make & Model: TOYOTA CAMRY, 2.0 ABS AIRBAG (A)

Reg. Date: 28/09/2006 (Man. Year: 2006)

Colour: Beige

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 1AZE008826

Chassis No: MR053BK4107001835

Odometer: 310903 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Falken 5 mm

Rear Left Side: Michelin 4 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,550.80	3,070.42	3,480.38	53.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,660.00	1,365.00	2,295.00	62.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,210.80	4,435.42	5,775.38	56.56
Approved Total (Overridden) (S\$)		3,550.00		
Nett Amount (S\$)	10,210.80	3,550.00	6,660.80	65.23

INSPECTION

Date of Assignment: 17/03/2020

Date Inspected: 17/03/2020 Inspected At:

Xin Yin Auto (HQ)

BLK 8 PREMIER @ KAKI BUKIT AVE 4

#05-23

Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: LEE HOCK ANN

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Apr 2020)
Parts:	143	TOYOTA CAMRY 2.0 ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGL8229J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Crumpled	850.00 FL	*560.80 FL
2	1		*REAR REINFORCEMENT	Bent	650.00 FL	*400.70 FL
3	1		*REAR BUMPER LEFT BRACKET	Repair	85.00 FL	*- FL
4	1		*REAR BUMPER RIGHT BRACKET	Repair	85.00 FL	*- FL
5	1		*REAR BUMPER LEFT RETAINER	Necessary	65.00 FL	*65.00 FL
6	1		*REAR BUMPER RIGHT RETAINER	Serviceable	65.00 FL	*- FL
7	1		*REAR LEFT BUMPER REFLECTOR	Crumpled	88.00 FL	*88.00 FL
8	1		*REAR RIGHT BUMPER REFLECTOR	Serviceable	88.00 FL	*- FL
9	1		*REAR BOOTLID	Bent	1,200.00 FL	*1,020.80 FL
10	1		*REAR TAILGATE CENTRE LOGO	Necessary	125.00 FL	*68.80 FL
11	1		*REAR TAILGATE EMBLEM	Necessary	85.00 FL	*65.80 FL
12	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	275.00 FL	*- FL
13	1		*REAR TAILGATE LOCK MECHANISM	Jammed	235.00 FL	*200.60 FL
14	1		*REAR TAILGATE INNER TRIM BOARD	Serviceable	285.00 FL	*- FL
15	1		*REAR TAILGATE OUTER GARNISH	Serviceable	250.00 FL	*- FL
16	1		*REAR TAILGATE NO PLATE LAMP	Serviceable	95.00 FL	*- FL
17	1		*REAR LEFT TAILLAMP	Crumpled	585.00 FL	*416.30 FL
18	1		*REAR RIGHT TAILLAMP	Crumpled	585.00 FL	*416.30 FL
19	2		*REAR TAILGATE DAMPER HOLDER	Serviceable	275.00 FL	*- FL
20	1		*REAR END LOWER PANEL TOP COVER	Crumpled	285.00 FL	*210.80 FL
21	1		*REAR EXHAUST ASSY (LOCAL REPAIR)	Scratched	680.00 FS	*150.00 FS
22	1		*REAR EXHAUST RUBBER MOUNTING	Serviceable	45.00 FL	*- FL
23	10		*REAR BUMPER CLIPS	Necessary	80.00 FS	*25.00 FS
24	6		*REAR END LOWER PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*15.00 FS
25	1		*REAR BOOTLID INNER TRIM BOARD CLIPS (8PCS)	Necessary	50.00 FS	*15.00 FS
26	6		*REAR TAILGATE OUTER GARNISH CLIPS	Serviceable	30.00 FS	*- FS
27	8		*REAR LEFT FENDER INNER SIDE GARNISH CLIPS	Serviceable	30.00 FS	*- FS
28	8		*REAR RIGHT FENDER INNER SIDE GARNISH CLIPS	Serviceable	30.00 FS	*- FS
29	6		*REAR LEFT FENDER INNER COWLING CLIPS	Serviceable	30.00 FS	*- FS
30	6		*REAR RIGHT FENDER INNER COWLING CLIPS	Serviceable	30.00 FS	*- FS
31	1		*REAR FLOOR PANEL SEALANT	Serviceable	120.00 FS	*- FS
32	2		*REAR BUMPER REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
33	1		*REAR NO PLATE WITH GARNISH }	Scratched	80.00 FS	*30.00 FS
34	1		*NUMBER PLATE WITH CASING }		50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,811.00	3,948.90
- List Item Discount on L Items 20.00/25.00% (\$\$)	1,260.20	878.48
Total Parts (\$\$)	6,550.80	3,070.42

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN FRONT AFFECTED AREA AND REPLACE FRONT DAMAGED PARTS, INCLUDING REAR END PANEL }	New	1,400.00	650.00
2	TO REMOVE AND INSTALL TAILGATE LOCK MECHANISM ASSY }	New	100.00	0.00
3	TO PUTTY AND SPRAY PAINTING DAMAGED AREA, BUMPER, BONNET, END PANEL	New	1,200.00	600.00
4	TO APPLY ANTI RUST PROOFING TO FRONT AFFECTED AREA }	New	120.00	25.00
5	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA }	New	120.00	0.00
6	TO CHECK REAR LIGHTING AND WIRING	New	50.00	30.00
7	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	New	80.00	20.00
8	TO REMOVE AND INSTALL REAR EXHAUST MUFFLER ASSY	New	120.00	40.00
9	TO CONDUCT CHASSIS ALIGNMENT	New	350.00	0.00
10	TO CONDUCT WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (\$\$)			3,660.00	1,365.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >