

## ASSIGNMENT

From: Date: 23.3.2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLZ 3876R

at Workshop n/s Borneo Motors

of 2 Pandan Crescent

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: After 2pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

66K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

map

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SLZ 3876R Yr Regn: 2016 / DAC

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA COROLLA ALTIS 1.6 A c.c. 1598

Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 66793

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: NR053R64104550583

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/45R17

R:

22

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

13/03/2020

D.O.I.

28/03/2020

Survey held at

BORNEO MOTOR

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Preli. Report

1) 06/4 2020

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 12

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

220

Report Format:

MER-TP

Lump Sum / I.B.I. (\$)

17000



Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

## ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :  
www.toyota.com.sg

Toyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462  
Tel no.: 6631 1188

|                                                                                                                               |  |                  |                                                                                                    |
|-------------------------------------------------------------------------------------------------------------------------------|--|------------------|----------------------------------------------------------------------------------------------------|
| Account Detail                                                                                                                |  | Account No       | Customer Detail                                                                                    |
| China Taiping Insurance (S) Pte Ltd<br>3 Anson Road<br>#16-00 Springleaf Tower<br>Singapore 079909<br>Attn: Motor Claims Dept |  | S1000003 / ICCI1 | M/s Chew's Agriculture Pte Ltd<br>20 Murai Farmway<br><br>Singapore 709153<br><br>Mobile: 96679329 |
|                                                                                                                               |  | Document No      |                                                                                                    |
|                                                                                                                               |  | 0                |                                                                                                    |
|                                                                                                                               |  | Document Date    |                                                                                                    |
|                                                                                                                               |  | 14/03/2020       |                                                                                                    |

|                   |        |            |          |            |                  |            |                      |
|-------------------|--------|------------|----------|------------|------------------|------------|----------------------|
| Year              | Make   | Model      | Reg Date | Veh Reg No | Kilometers       | WIP No     | Order No/Remarks     |
| 16                | GEXGKZ | S3         | ZRE171R  | 28/12/2016 | SLZ3876R         | 0          | 54181 72/DS/SLZ3876R |
| Chassis No        |        | Engine No  | Terms    |            | Service Engineer | Vehicle In | Collected On         |
| MR053REH104550583 |        | 1ZRX572160 | 60       |            | Thomas Pang W T  | --/--/---- | 0.00 --/--/---- 0.00 |

| L  | Cd | Job/Parts Description                                                                     | Qty | Unit Price | Disc % | Amount     |
|----|----|-------------------------------------------------------------------------------------------|-----|------------|--------|------------|
| 1  | Z  | BP-SUNDRY TP INS: CHINA TAIPING INSURANCE<br>TP VEH: SFF 6987K<br>DATE OF ACC: 13.03.2020 |     |            | nec    | 50 180.00  |
| 2  | B  | BP-LAB2 REPLACE AND REFOCUS HEADLAMP - FRONT                                              |     |            |        | 122.40     |
| 3  | B  | BP-ECU2 TO RESET ECU AND REPROGRAMME                                                      |     |            |        | 180.00     |
| 4  | B  | BP-LAB2 REPLACE ACC DAMAGED PARTS<br>AND STRAIGHTEN/REALIGN<br>ACC AFFECTED AREAS - FRONT |     |            | 1440   | 2160.00    |
| 5  | B  | BP-RES2 RESPRAY ACC AFFECTED AREAS - FRONT                                                |     |            |        | 1770.00    |
| 6  | Z  | BP-SLANT SUPPLY SEALANT (NETT)                                                            |     |            | nec    | 100 200.00 |
| 7  | B  | BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR -<br>REAR                                   |     |            |        | 180.00     |
| 8  | B  | BP-LAB2 CHECK WIRING AND CONDUCT WATER TEST - RE<br>AR                                    |     |            |        | 122.40     |
| 9  | B  | BP-LAB2 REMOVE AND TRANSFER BOOTLID COMPONENTS<br>ONTO NEW BOOTLID - REAR                 |     |            |        | 360.00     |
| 10 | B  | BP-LAB2 R/I REAR REVERSE CAMERA TO FAC REPAIR -<br>REAR                                   |     |            |        | 180.00     |
| 11 | B  | BP-LAB2 REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR<br>- REAR                                |     |            |        | 360 720.00 |

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

|                                     |                                       |                                                             |            |
|-------------------------------------|---------------------------------------|-------------------------------------------------------------|------------|
| For & on behalf of<br>Borneo Motors | Customer's Signature                  | Change Summary                                              | Total      |
|                                     | Please acknowledge receipt of vehicle | Parts<br>Labour<br>Materials<br>Lubrication/Fluid<br>Others | 4274.80    |
|                                     |                                       |                                                             | Less       |
|                                     |                                       |                                                             | Amount Due |

PLEASE TEAR ALONG PERFORATED LINE

4214890

TO SECURITY GUARD

4214890

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 14/03/2020  
TIME 11:12

VEHICLE NO

SLZ3876R

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Inchcape

Borneo Motors



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyota.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9**ESTIMATE**

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account &amp; more!

| Account Detail                                                                                                                | Account No                  | Customer Detail                                                                            |
|-------------------------------------------------------------------------------------------------------------------------------|-----------------------------|--------------------------------------------------------------------------------------------|
| China Taiping Insurance (S) Pte Ltd<br>3 Anson Road<br>#16-00 Springleaf Tower<br>Singapore 079909<br>Attn: Motor Claims Dept | S1000003 / ICCI1            | M/s Chew's Agriculture Pte Ltd<br>20 Murai Farmway<br>Singapore 709153<br>Mobile: 96679329 |
|                                                                                                                               | Document No<br>0            |                                                                                            |
|                                                                                                                               | Document Date<br>14/03/2020 |                                                                                            |

| Year              | Make       | Model | Reg Date         | Veh Reg No | Kilometers   | WIP No     | Order No/Remarks     |
|-------------------|------------|-------|------------------|------------|--------------|------------|----------------------|
| 16                | GEXGKZ     | S3    | ZRE171R          | 28/12/2016 | SLZ3876R     | 0          | 54181 72/DS/SLZ3876R |
| Chassis No        | Engine No  | Terms | Service Engineer | Vehicle In | Collected On |            |                      |
| MRO53REH104550583 | 1ZRX572160 | 60    | Thomas Pang W T  | --/--/---- | 0.00         | --/--/---- | 0.00                 |

| L  | Cd | Job/Parts Description                                                                    | Qty   | Unit Price | Disc % | Amount       |
|----|----|------------------------------------------------------------------------------------------|-------|------------|--------|--------------|
| 12 | L  | BP-LPO SUPPLY REGN PLATE (PO# )<br>(FRT & BACK)                                          |       |            |        | 80 160.00    |
| 13 | B  | BP-LAB2 REPLACE ACC DAMAGED PARTS<br>AND STRAIGHTEN/REALIGN<br>ACC AFFECTED AREAS - REAR |       |            |        | 2160 3600.00 |
| 14 | B  | BP-RES2 RESPRAY ACC AFFECTED AREAS - REAR                                                |       |            |        | 1720 3540.00 |
| 15 | 1  | SPZ061-12021 17 BACK SENSOR 1D4 310A ? XSN                                               | 1.00  | 159.75     |        | X 159.75     |
| 16 | 2  | SPZ067-12006 BACK CAMERA ? XSN                                                           | 1.00  | 628.90     |        | X 628.90     |
| 17 | 3  | S52119-02955 COVER, FR BUMPER ? repair                                                   | 1.00  | 531.10     |        | X 531.10     |
| 18 | 4  | S52161-0K040 PIECE, RR BUMPER ne                                                         | 10.00 | 4.10       |        | 41.00        |
| 19 | 5  | S52115-02270 SUPPORT, FR BUMPER RH XSN                                                   | 1.00  | 85.50      |        | X 85.50      |
| 20 | 6  | S52116-02270 SUPPORT, FR BUMPER LH XSN                                                   | 1.00  | 85.50      |        | X 85.50      |
| 21 | 7  | S53112-02630 GRILLE, RADIATOR LWR ? XSN                                                  | 1.00  | 170.10     |        | X 170.10     |
| 22 | 8  | S52611-02310 ABSORBER, FR BUMPER ? XSN                                                   | 1.00  | 90.10      |        | X 90.10      |
| 23 | 9  | S52131-02190 REINFORCEMENT, FR ? XSN                                                     | 1.00  | 399.50     |        | X 399.50     |
| 24 | 0  | T90467-05170 CLIP ne                                                                     | 2.00  | 2.50       |        | 5.00         |
| 25 | 1  | S53879-0K010 F/FENDER LINER RETAINER, ne                                                 | 2.00  | 8.60       |        | 17.20        |
| 26 | 2  | S53100-02760 GRILLE, RADIATOR end                                                        | 1.00  | 643.00     |        | 643.00       |
| 27 | 3  | S53208-02210 SUPPORT SUB-ASSY, HO bt                                                     | 1.00  | 149.40     |        | 149.40       |
| 28 | 4  | S75311-02190 RADIATOR GRILLE EMBLEM, ne                                                  | 1.00  | 47.90      |        | 47.90        |

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

| For & on behalf of<br>Borneo Motors | Customer's Signature                  | Change Summary                                              | Total      |
|-------------------------------------|---------------------------------------|-------------------------------------------------------------|------------|
|                                     | Please acknowledge receipt of vehicle | Parts<br>Labour<br>Materials<br>Lubrication/Fluid<br>Others | Less       |
|                                     |                                       |                                                             | Amount Due |

PLEASE TEAR ALONG PERFORATED LINE

4214891

TO SECURITY GUARD

4214891

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 14/03/2020  
TIME 11:12

VEHICLE NO SLZ3876R

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Inchcape

**Borneo Motors**

Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9

# ESTIMATE

Online Service Booking :  
[www.toyota.com.sg](http://www.toyota.com.sg)  
**Toyota Bodycare Centre**  
No. 2 Pandan Crescent  
Singapore 128462  
Tel no.: 6631 1188

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account &amp; more!

| Account Detail                                                                                                                       | Account No                         | Customer Detail                                                                                       |
|--------------------------------------------------------------------------------------------------------------------------------------|------------------------------------|-------------------------------------------------------------------------------------------------------|
| <b>China Taiping Insurance (S) Pte Ltd</b><br>3 Anson Road<br>#16-00 Springleaf Tower<br>Singapore 079909<br>Attn: Motor Claims Dept | <b>S1000003 / ICCI1</b>            | <b>M/s Chew's Agriculture Pte Ltd</b><br>20 Murai Farmway<br>Singapore 709153<br><br>Mobile: 96679329 |
|                                                                                                                                      | Document No<br><b>0</b>            |                                                                                                       |
|                                                                                                                                      | Document Date<br><b>14/03/2020</b> |                                                                                                       |

| Year              | Make       | Model | Reg Date         | Veh Reg No | Kilometers   | WIP No     | Order No/Remarks     |
|-------------------|------------|-------|------------------|------------|--------------|------------|----------------------|
| 16                | GEXGKZ     | S3    | ZRE171R          | 28/12/2016 | SLZ3876R     | 0          | 54181 72/DS/SLZ3876R |
| Chassis No        | Engine No  | Terms | Service Engineer | Vehicle In | Collected On |            |                      |
| MRO53REH104550583 | 12RX572160 | 60    | Thomas Pang W T  | --/--/---- | 0.00         | --/--/---- | 0.00                 |

| L  | Cd | Job/Parts Description                           | Qty   | Unit Price | Disc % | Amount   |
|----|----|-------------------------------------------------|-------|------------|--------|----------|
| 29 | 5  | S81110-02F51 HEADLAMP ASSY, RH <i>cm</i>        | 1.00  | 2999.80    |        | 2999.80  |
| 30 | 6  | S81150-02F51 HEADLAMP ASSY, LH <i>cm</i>        | 1.00  | 2999.80    |        | 2999.80  |
| 31 | 7  | S52159-0Z904 COVER, RR BUMPER <i>de</i>         | 1.00  | 556.40     |        | 556.40   |
| 32 | 8  | S52161-0K040 PIECE, RR BUMPER <i>ae</i>         | 10.00 | 4.10       |        | 41.00    |
| 33 | 9  | S52575-02140 RETAINER, RR BUMPER <i>ra</i>      | 1.00  | 109.30     |        | 109.30   |
| 34 | 0  | S52562-02250 RETAINER, RR BUMPER <i>ra</i>      | 1.00  | 60.40      |        | 60.40    |
| 35 | 1  | S52576-02140 RETAINER, RR BUMPER <i>la</i>      | 1.00  | 109.30     |        | 109.30   |
| 36 | 2  | S52563-02250 RETAINER, RR BUMPER <i>la</i>      | 1.00  | 60.40      |        | 60.40    |
| 37 | 3  | S52023-02190 REINFORCEMENT, RR <i>bt</i>        | 1.00  | 399.50     |        | 399.50   |
| 38 | 4  | S52181-02190 ARM, RR BUMPER RH <i>? xsv</i>     | 1.00  | 68.20      |        | X 68.20  |
| 39 | 5  | S52182-02160 ARM, RR BUMPER LH <i>? xsv</i>     | 1.00  | 68.20      |        | X 68.20  |
| 40 | 6  | S58307-02380 PANEL, LAMP LOWER <i>? bt</i>      | 1.00  | 670.00     |        | X 670.00 |
| 41 | 7  | S64401-02B71 PANEL SUB-ASSY, LUGG <i>bt xsv</i> | 1.00  | 793.20     |        | X 793.20 |
| 42 | 8  | S64461-02220 WEATHERSTRIP, LUGGAGE <i>xsv</i>   | 1.00  | 175.80     |        | X 175.80 |
| 43 | 9  | S64503-02181 ARM SUB-ASSY, LUG CO <i>xsv</i>    | 1.00  | 69.90      |        | X 69.90  |
| 44 | 0  | S64503-02181 ARM SUB-ASSY, LUG CO <i>xsv</i>    | 1.00  | 69.90      |        | X 69.90  |
| 45 | 1  | S64600-02080 LOCK ASSY, LUGGAGE <i>xsv</i>      | 1.00  | 399.50     |        | X 399.50 |
| 46 | 2  | S58387-02240 PLATE, RR FLOOR <i>? xsv</i>       | 1.00  | 241.90     |        | X 241.90 |
| 47 | 3  | T90467-08186 CO CLIP <i>ae</i>                  | 2.00  | 2.80       |        | 5.60     |
| 48 | 4  | S81550-02780 LAMP ASSY, RR COMB RH <i>? xsv</i> | 1.00  | 379.80     |        | X 379.80 |

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

| For & on behalf of<br>Borneo Motors | Customer's Signature                  | Change Summary                                              | Total      |
|-------------------------------------|---------------------------------------|-------------------------------------------------------------|------------|
|                                     | Please acknowledge receipt of vehicle | Parts<br>Labour<br>Materials<br>Lubrication/Fluid<br>Others | Less       |
|                                     |                                       |                                                             | Amount Due |

PLEASE TEAR ALONG PERFORATED LINE

4214892

TO SECURITY GUARD

4214892

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 14/03/2020  
TIME 11:12

VEHICLE NO SLZ3876R

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD


Inchcape

**Borneo Motors**



Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9

## ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :  
www.toyota.com.sg

Toyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462  
Tel no.: 6631 1188

|                                                                                                                               |  |                  |                                                                                                    |
|-------------------------------------------------------------------------------------------------------------------------------|--|------------------|----------------------------------------------------------------------------------------------------|
| Account Detail                                                                                                                |  | Account No       | Customer Detail                                                                                    |
| China Taiping Insurance (S) Pte Ltd<br>3 Anson Road<br>#16-00 Springleaf Tower<br>Singapore 079909<br>Attn: Motor Claims Dept |  | S1000003 / ICCI1 | M/s Chew's Agriculture Pte Ltd<br>20 Murai Farmway<br><br>Singapore 709153<br><br>Mobile: 96679329 |
|                                                                                                                               |  | Document No      |                                                                                                    |
|                                                                                                                               |  | 0                |                                                                                                    |
|                                                                                                                               |  | Document Date    |                                                                                                    |
|                                                                                                                               |  | 14/03/2020       |                                                                                                    |

|                   |            |       |                  |            |              |            |                      |
|-------------------|------------|-------|------------------|------------|--------------|------------|----------------------|
| Year              | Make       | Model | Reg Date         | Veh Reg No | Kilometers   | WIP No     | Order No/Remarks     |
| 16                | GEXGKZ     | S3    | ZRE171R          | 28/12/2016 | SLZ3876R     | 0          | 54181 72/DS/SLZ3876R |
| Chassis No        | Engine No  | Terms | Service Engineer | Vehicle In | Collected On |            |                      |
| MR053REH104550583 | 1ZRX572160 | 60    | Thomas Pang W T  | --/--/---- | 0.00         | --/--/---- | 0.00                 |

| L  | Cd | Job/Parts Description                          | Qty  | Unit Price | Disc % | Amount   |
|----|----|------------------------------------------------|------|------------|--------|----------|
| 49 | 5  | S81560-02780 LAMP ASSY, RR COMBIN ? <i>Xsu</i> | 1.00 | 379.80     |        | X 379.80 |
| 50 | 6  | S81580-02551 LAMP ASSY, RR, RH ? <i>Xsu</i>    | 1.00 | 394.50     |        | X 394.50 |
| 51 | 7  | S81590-02551 LAMP ASSY, RR, LH ? <i>Xsu</i>    | 1.00 | 394.50     |        | X 394.50 |
| 52 | 8  | S81910-02170 REFLECTOR ASSY, REFL <i>Xsu</i>   | 1.00 | 59.80      |        | X 59.80  |
| 53 | 9  | S81920-02110 REFLECTOR ASSY, REFL <i>Xsu</i>   | 1.00 | 59.80      |        | X 59.80  |
| 54 | 0  | T89997-30070 ELECTRICAL ANTENNA, ? <i>Xsu</i>  | 1.00 | 192.20     |        | X 192.20 |
| 55 | 1  | S75431-02090 LUGGAGE COMP EMBLEM, <i>u</i>     | 1.00 | 61.60      |        | 61.60    |
| 56 | 2  | S75442-02330 PLATE, LUGGAGE COMPT <i>u</i>     | 1.00 | 41.00      |        | 41.00    |
| 57 | 3  | S75442-02340 PLATE, LUGGAGE COMPT <i>u</i>     | 1.00 | 45.60      |        | 45.60    |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

|                                            |            |                                       |                   |            |           |
|--------------------------------------------|------------|---------------------------------------|-------------------|------------|-----------|
| For & on behalf of<br><b>Borneo Motors</b> | Signature: | Customer's Signature                  | Change Summary    | Total      | 28,355.45 |
|                                            | Date:      | Please acknowledge receipt of vehicle | Parts             | GST 7.00%  | 1,984.88  |
|                                            |            |                                       | Labour            | Less       | 0.00      |
|                                            |            |                                       | Materials         |            |           |
|                                            |            |                                       | Lubrication/Fluid |            |           |
|                                            |            |                                       | Others            |            |           |
|                                            |            |                                       |                   | Amount Due | 30,340.33 |

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 14/03/2020  
TIME 11:12

VEHICLE NO SLZ3876R

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

4214893

4214893

*Handwritten notes:*  
Rasul  
Hp 90010068  
10 days + 2 = 12 days  
23/03/2020 @ 1530  
Reg before paint  
Repair list 17k  
Total 17,348  
148.20