

# AERO GARAGE PTE LTD

Blk 160, Sin Ming Drive, #08-07 Sin Ming AutoCity, Singapore 575722

Tel : 6266 9511 Fax : 6266 9512

Vehicle No : SMP1056U  
Vehicle Model : Opel Insignia

## Estimate Repair Cost

No.	Qty	Parts List Items		
1	1	Front bumper	\$	1,980.00
2	2	Front bumper retainers	\$	110.00
3	2	Front bumper brackets	\$	140.00
4	1 set	Front bumper clips	\$	40.00
5	1	Front fender RH	\$	760.00
6	1	Front fender inner shield RH	\$	230.00
7	1	Front fender reflector RH	\$	92.00
	1	Front lower arm RH	\$	470.00
8	1	Front shock absorber RH	\$	390.00
9	1	Front knuckle arm RH	\$	560.00
10	1	Front knuckle arm bearing RH	\$	310.00
11	1	Front wheel rim RH	\$	590.00
Total			\$	<u>5,672.00</u>

## Labour

1	Labour charge to remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	\$	800.00
2	To putty and respray painting on affected areas.	\$	700.00
3	To remove, replace front fender fittings to facilitate repair.	\$	300.00
4	To remove, replace front knuckle arm, shock absorber and lower arm.	\$	350.00
5	To remove, replace front tyre and wheel rim.	\$	100.00
6	To check wiring and lightings.	\$	80.00
Total Labour		\$	<u>2,330.00</u>
Total Parts and Labour		\$	<u>8,002.00</u>