

ASS. REC. BY:

REF: CS/CT1 20004104/Us-f3

Special Instruction:

Surveyor: MarcusASSIGNMENT (Office)From (Person): Pauline Thawof CT1Date/Time: 17.3.2020 9.10a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMD 1475G

Insured:

GBE 1558Bat Workshop m/s Automobil Integrated

Tel:

9119 98371of 23 Kaki Bukit Ave 4, Kaki Bukit

Policy No:

Claim No: SNM 2017 201316 / GBE 1558B / Pauline

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 13.3.2020

CA / REV / REP. / REV 24 HRS

Date/Time: 17.3.2020 9.40a.m

Person Contacted:

Jayne

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

17/3/2020 - 9.40a.m Jayne say wait for Marcus survey (Request from her boss).SMD 1475G - XGBE 1558B - X

ASSIGNMENT

From:

Date:

Estimated Cost:

OB / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMD 14756

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value:

80k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

131

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 47531

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMD 14756

Yr Regn:

11/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

Hyundai

IONIQ

EVSR

Electric

Colour:

orange

A/C:

Insured / Std / NI / NA

Sp. Reading

23322

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMHCB5/HUJU 01869

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

225/40ZR18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

P

mm

R/Bal.

P

mm

L/Bal.

P

mm

L/Bal.

P

mm

D.O.A.

13/3/20

D.O.I.

17/3/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

L1, O/S

The U/C / Chassis frame / Body structure affected due to collision.

Date / Time Action / Instruction

1/4/20 No 2018 model confirmed final fee \$6737.48
(\$ 7,362.76 red - 52%)

Date/Time, File Pass to?

01/04/20



: Prel. Report



: Final Report

1)

Type: F

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

3

Survey Fee:

Transportation:

) \$ + RS \$ SI

) Photos

) Others

)

TOTAL

220

Report Format :

Lump Sum / I.B.f (\$ 6,737.48)

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Nivitha (LKK Auto)

From: Pauline Tham <pauline.tham@sg.cntaiping.com>
Sent: Tuesday, 17 March 2020 9:10 AM
To: AIM PTE LTD
Cc: admin-a@lkkauto.com; sur@lkkauto.com; assignments@lkkauto.com
Subject: RE: OUR REF: SNM20D201316/GBE1558B/PAULINE - NOA- SMD1475G // TP claim 13.03.2020

Without Prejudice

Dear Jacyne

Thanks for reply

Dear LKK

Please conduct survey.

Thanks.

Pauline Tham
Senior Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6541 | F: (65) 6224 7175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

From: AIM PTE LTD <automim.claim@gmail.com>
Sent: Tuesday, March 17, 2020 8:59 AM
To: Pauline Tham <pauline.tham@sg.cntaiping.com>
Subject: Re: OUR REF: SNM20D201316/GBE1558B/PAULINE - NOA- SMD1475G // TP claim 13.03.2020

Hi,

We would like to appoint surveyor Marcus Chua from LKK to conduct survey.

Thank you.

Regards,
Jacyne

Automobile Integrated Management Pte Ltd (aim)

Office: 28 Sin Ming Lane #07-147 Midview City Singapore 573972

W/S: 23 Kaki Bukit Ave 4, Kaki Bukit Vicom #04-01 (South Wing) Singapore 415933

Tel: 91198371

On Tue, Mar 17, 2020 at 8:54 AM Pauline Tham <pauline.tham@sg.cntaiping.com> wrote:

Without Prejudice

Dear Sirs

We refer to your email of even date.

We intend to conduct a Pre-Repair Survey of your client's vehicle jointly with your client/your motor workshop.

We propose to use one of the following motor surveyors to conduct the survey as a single joint expert.

LKK / LBS / STA

| |
|-------------------------|
| Adrian Ling |
| Kelvin Ang |
| See Chew Seng |
| Mohd Fadhilah Bin Osman |
| Xing Quo Qiang |
| Kenneth Kong |
| Simon Ho |
| Chua Weijie |
| Marcus Chua |
| Henry Ng |

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.

Thank you.

Thanks.

Pauline Tham

Senior Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6541 | F: (65) 6224 7175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Monday, March 16, 2020 5:20 PM

To: Pauline Tham <pauline.tham@sg.cntaiping.com>; AIM PTE LTD <automim.claim@gmail.com>

Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: OUR REF: SNM20D201316/GBE1558B/PAULINE - NOA- SMD1475G // TP claim 13.03.2020

Dear Pauline,

Please conduct PRS for SMD1475G.

And our insured vehicle number GBE15588.

Note : officer in charge – Pauline 63896541

*** Kindly quote our reference number when replying.

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower

Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: AIM PTE LTD <automim.claim@gmail.com>

Sent: Monday, March 16, 2020 11:33 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: NOA- SMD1475G // TP claim 13.03.2020

Hi,

Please refer attached to advise further.

Thank you.

Regards,

Jacyne

Automobile Integrated Management Pte Ltd (aim)

Office: 28 Sin Ming Lane #07-147 Midview City Singapore 573972

W/S: 23 Kaki Bukit Ave 4, Kaki Bukit Vicom #04-01 (South Wing) Singapore 415933

Tel: 91198371

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Foru

Replay

Watch Your
Business Grow

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

BMW 4 Series 420i Gran Coupe M-Sport

1 Owner, Agent (PML) Units.
Well Maintained With
(PML)services Records.
Hamilton Autohub Pte StarAd

ABWIN

ONE STOP





Browse by Category ▼

Sort by Date Posted ▼

2 vehicles

Hyundai Ioniq

Advanced Search

| | Make | Model | Price | Depreciation | Reg Date | Eng Cap | Mileage | Veh Type |
|--|---------------|---------------------------------------|----------|--------------|-------------|----------|-----------|-----------|
| Search Selection | Hyundai Ioniq | | Any | Any | Any | Any | Any | Any |
|  | Hyundai Ioniq | Hyundai Ioniq Hybrid 1.6A GLS Sunroof | \$83,800 | \$10,660 /yr | 01-Nov-2017 | 1,580 cc | 41,300 km | Hatchback |
| Energy Saving Petrol Electric Car. 5 Years Warranty And 10 Years Battery Warranty By Komoco, Enjoy Exclusive Low Interest Rate At Only 2.28%! Please Call/SMS/Whatsapp For Viewing. | | | | | | | | |
| Republic Auto | | | | | | | | |
| Posted: 04-Mar-2020 Tags: 2017 Hyundai Ioniq, Hyundai Ioniq, Hyundai, Ioniq | | | | | | | | |
|  | Hyundai Ioniq | Hyundai Ioniq Hybrid 1.6A GLS Sunroof | \$80,800 | \$10,860 /yr | 02-Jun-2017 | 1,580 cc | 29,000 km | Hatchback |
| Fuel Type: Petrol-Electric | | | | | | | | |
| At Only A Bargain \$10k Depre, 5 Year Komoco Agent Warranty (Unlimited Mileage), 10 Year Hybrid Warranty! This Ioniq Is Hyundai's Top Of The Line Hatchback Jam Packed With The Best Technology They Have To Offer! Safety Features Such As Radar Cruise Control, Auton... | | | | | | | | |
| Car Buyers Automotive Pte Ltd | | | | | | | | |
| Posted: 18-Feb-2020 Tags: 2017 Hyundai Ioniq, Hyundai Ioniq, Hyundai, Ioniq | | | | | | | | |

Save this search criteria, to get email alerts whenever a match is found.

| Make | Model | Price | Depreciation | Reg Date | Eng Cap | Mileage | Veh Type |
|------|-------|-------|--------------|----------|---------|---------|----------|
|------|-------|-------|--------------|----------|---------|---------|----------|

For old advertisements, view Expired ads

20

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brand insurance. Find buy used Hyundai Ioniq, Hyundai Ioniq Singapore, used Hyundai Ioniq Singapore, used Hyundai Ioniq, used vehicles Singapore or even buy used Hyundai have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotion sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this

Follow sgCarMart.com

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|-------------------------------------|--------------------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 269F |
| Vehicle Details | |
| Vehicle No.: | SMD1475G |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 18 Mar 2020 |
| Vehicle Make: | HYUNDAI |
| Vehicle Model: | IONIQ EV SR |
| Primary Colour: | Orange |
| Manufacturing Year: | 2017 |
| Engine No.: | - |
| Chassis No.: | KMHC851HUJU018619 |
| Maximum Power Output: | 88.0 kW (118 bhp) |
| Open Market Value: | \$36,712.00 |
| Original Registration Date: | 25 Jan 2018 |
| First Registration Date: | 25 Jan 2018 |
| Transfer Count: | 1 |
| Actual ARF Paid: | \$23,397.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 24 Jan 2028 |
| PARF Rebate Amount: | \$17,547.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 24 Jan 2028 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$38,200.00 |
| COE Rebate Amount: | \$29,984.00 |
| Total Rebate Amount: | \$47,531.00 |

The information contained herein is correct as at 18 Mar 2020

OK

ESTIMATE

Our Ref: AC2020022/TP/SMD1475G-13.03.2020

Vehicle number: SMD1475G

Vehicle Made & Model: HYUNDAI IONIQ ELECTRIC

| Items | Qty | List Items | Amount \$ |
|------------|-----|---|-----------|
| 1 | 1 | Front bumper | 628.30 |
| 2 | 1 | Front bumper PDC sensor - RH 199.20 | 281.50 |
| 3 | 1 | Front bumper daylight - RH | 695.60 |
| 4 | 1 | Front bumper daylight cover | 110.20 |
| 5 | 1 | Front bumper daylight grille | 96.80 |
| 6 | 1 | Front bumper daylight bracket | 105.60 |
| 7 | 1 | Front bumper side bracket - RH | 89.60 |
| 8 | 1 | Front bumper side holder - RH | 86.60 |
| 9 | 2 | Front bumper side retainers - L/R @ 48.60 | 97.20 |
| 10 | 1 | Front bumper sponge | 120.30 |
| 11 | 1 | Front bumper CTR pad 418.20 | 643.50 |
| 12 | 1 | Front bumper logo 75.80 | 341.50 |
| 13 | 1 | Front bumper top seal | 68.60 |
| 14 | 1 | Front bonnet | 2,253.80 |
| 15 | 1 | Front fender - RH | 588.80 |
| 16 | 1 | Front fender top 1/4 garnish | 59.90 |
| 17 | 1 | Front fender inner shield | 137.70 |
| 18 | 1 | Front fender emblem | 86.60 |
| 19 | 1 | Front headlamp assy - RH 244.80 | 2,895.50 |
| 20 | 1 | Front support panel | 869.90 |
| 21 | 1 | Front shock absorber - RH | 561.60 |
| 22 | 1 | Front lower arm | 478.90 |
| 23 | 1 | Front knuckle arm | 599.50 |
| 24 | 1 | Front wheel bearing | 452.80 |
| Sub-total | | | 12,350.30 |
| Less 20% | | | 2,470.06 |
| Total List | | | 9,880.24 |

Special Nett Items

| | | | |
|--------------------|-------|--------------------------------|----------|
| 25 | 1 | Front sport wheel - RH | 650.00 |
| 26 | 1 | Front tyre - RH | 350.00 |
| 27 | 1 set | Front bumper clip | 45.00 |
| 28 | 1 set | Front fender inner shield clip | 45.00 |
| Total Special Nett | | | 1,090.00 |

Labour charges

| | | | |
|----|---|-----------------|-----|
| 29 | To check front electrical wiring | 50.00 | 20 |
| 30 | To remove, refix front undercarriage | 300.00 | X |
| 31 | To respray undercoating | 80.00 | 30 |
| 32 | To check wheel alignment | 120.00 | 60 |
| 33 | To remove, refix A/C condenser & refill A/C gas | 180.00 | 100 |
| 34 | To respray painting and etc | 1,200.00 | 700 |
| 35 | Panel beating, cut, weld remove & replacing above parts | 1,200.00 | 600 |
| | Total Labour | 3,130.00 | |

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

14,100.24

P- 6378.10
 20%
 P- 5102.48
 S- 125.00
 L- 1570.00
 6737.48

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20004104/USF3N2
Date: 03/04/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30622219000
 Claimant Vehicle No: SMD1475G Insured Vehicle No: GBE1558B
 Date of Loss: 13/03/2020 Nature of Claim: TP Claim No: SNM20D201316

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMD1475G
 Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) Engine No: HIDDEN
 Reg. Date: 25/01/2018 (Man. Year: 2017) Chassis No: KMHC851HUJU018619
 Colour: Orange Odometer: 23322 km
 Engine Capacity: 0 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40ZR18 Rear Tyre Size: 225/40ZR18
 Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm
 Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|------------------|-----------------|-----------------|--------------|
| Parts | 10,970.24 | 5,227.48 | 5,742.76 | 52.35 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,130.00 | 1,510.00 | 1,620.00 | 51.76 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 14,100.24 | 6,737.48 | 7,362.76 | 52.22 |
| + GST 7.00/7.00% (S\$) | 987.02 | 471.62 | 515.40 | 52.22 |
| Nett Amount (S\$) | 15,087.26 | 7,209.10 | 7,878.16 | 52.22 |

INSPECTION

Date of Assignment: 24/03/2020
 Date Inspected: 17/03/2020 Inspected At: Automobile Integrated Management Pte Ltd (HQ)
 23 Kaki Bukit Ave 4 #04-01, Kaki Bukit (South Wing)
 Singapore 415933
 Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Apr 2020)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMD1475G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--------------------------------------|----------------|-------------|--------------|
| 1 | 1 | | *FRONT BUMPER | Distorted/Torn | 628.30 FL | *628.30 FL |
| 2 | 1 | | *FRONT BUMPER PDC SENSOR-RH | Shorted | 281.50 FL | *199.20 FL |
| 3 | 1 | | *FRONT BUMPER DAYLIGHT-RH | Cracked | 695.60 FL | *695.60 FL |
| 4 | 1 | | *FRONT BUMPER DAYLIGHT COVER | Cut | 110.20 FL | *110.20 FL |
| 5 | 1 | | *FRONT BUMPER DAYLIGHT GRILLE | No such part | 96.80 FL | *- FL |
| 6 | 1 | | *FRONT BUMPER DAYLIGHT BRACKET | Not Necessary | 105.60 FL | *- FL |
| 7 | 1 | | *FRONT BUMPER SIDE BRACKET-RH | Not Necessary | 89.60 FL | *- FL |
| 8 | 1 | | *FRONT BUMPER SIDE HOLDER-RH | Cracked | 86.60 FL | *86.60 FL |
| 9 | 1 | | *FRONT BUMPER SIDE RETAINERS-L/R | O/s Bent | 97.20 FL | *48.60 FL |
| 10 | 1 | | *FRONT BUMPER SPONGE | Not Necessary | 120.30 FL | *- FL |
| 11 | 1 | | *FRONT BUMPER CTD PAD | Deformed/Cut | 643.50 FL | *418.20 FL |
| 12 | 1 | | *FRONT BUMPER LOGO | Necessary | 341.50 FL | *75.80 FL |
| 13 | 1 | | *FRONT BUMPER TOP SEAL | Necessary | 68.60 FL | *68.60 FL |
| 14 | 1 | | *FRONT BONNET | Not Necessary | 2,253.80 FL | *- FL |
| 15 | 1 | | *FRONT FENDER-RH | Buckled | 588.80 FL | *588.80 FL |
| 16 | 1 | | *FRONT FENDER TOP 1/4 GARNISH | Missing | 59.90 FL | *59.90 FL |
| 17 | 1 | | *FRONT FENDER INNER SHIELD | Not Necessary | 137.70 FL | *- FL |
| 18 | 1 | | *FRONT FENDER EMBLEM | Necessary | 86.60 FL | *86.60 FL |
| 19 | 1 | | *FRONT HEADLAMP ASSY-RH | Cracked | 2,895.50 FL | *2,441.80 FL |
| 20 | 1 | | *FRONT SUPPORT PANEL | Cracked | 869.90 FL | *869.90 FL |
| 21 | 1 | | *FRONT SHOCK ABSORBER-RH | Not Necessary | 561.60 FL | *- FL |
| 22 | 1 | | *FRONT LOWER ARM | Not Necessary | 478.90 FL | *- FL |
| 23 | 1 | | *FRONT KNUCKLE ARM | Not Necessary | 599.50 FL | *- FL |
| 24 | 1 | | *FRONT WHEEL BEARING | Not Necessary | 452.80 FL | *- FL |
| 25 | 1 | | *FRONT SPORT WHEEL-RH (LOCAL REPAIR) | Cut | 650.00 FS | *80.00 FS |
| 26 | 1 | | *FRONT TYRE-RH | Serviceable | 350.00 FS | *- FS |
| 27 | 1 | | *SET FRONT BUMPER CLIP | Necessary | 45.00 FS | *45.00 FS |
| 28 | 1 | | *SET FRONT FENDER INNER SHIELD CLIP | Not Necessary | 45.00 FS | *- FS |

F=Franchise part. S=SpcNeff. L=ListItemDisc.

| | | |
|---|------------------|-----------------|
| Sub Total (\$\$) | 13,440.30 | 6,503.10 |
| - List Item Discount on L Items 20.00/20.00% (\$\$) | 2,470.06 | 1,275.62 |
| Total Parts (\$\$) | 10,970.24 | 5,227.48 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO CHECK FRONT ELECTRICAL WIRING | New | 50.00 | 20.00 |
| 2 | TO REMOVE,REFIX FRONT UNDERCARRIAGE | New | 300.00 | 0.00 |
| 3 | TO RESPRAY UNDERCOATING | New | 80.00 | 30.00 |
| 4 | TO CHECK WHEEL ALIGNMENT | New | 120.00 | 60.00 |
| 5 | TO REMOVE,REFIX A/C CONDENSER & REFILL A/C GAS | New | 180.00 | 100.00 |
| 6 | TO RESPRAY PAINTING AND ETC | New | 1,200.00 | 700.00 |
| 7 | PANEL BEATING,CUT,WELD REMOVE & REPLACING ABOVE PARTS | New | 1,200.00 | 600.00 |
| Gross Labour Cost (S\$) | | | 3,130.00 | 1,510.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >