

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

17/03/2020 13:39

JOB-NO: 50112519

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHB3580S

TRANS: AUTO

CHASSIS: KMHLB41UMFU069310

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4FDFU529352

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREAS	1.00	800.00	500	0.00		Y	_____
2 RESPRAY REAR BUMPER	1.00	250.00	200	0.00		Y	_____
3 RESPRAY REAR LHS FENDER	1.00	250.00	200	0.00		Y	_____
4 RESPRAY REAR LHS DOOR	1.00	250.00	200	0.00		Y	_____
5 R&R REAR WINDSCREEN TO REPLACE FENDER	1.00	200.00	X	0.00		Y	_____
6 R&R REAR PASSENGER SEAT, SEAT BELT, BOOT COMPARTMENT TRIM COVERS, REAR LHS QUARTER GLASS TO REPLACE REAR LHS FENDER.	1.00	200.00	X	0.00		Y	_____
7 RUST PROOFING	1.00	120.00	X	0.00		Y	_____
8 RESPRAY LHS SIDE SKIRT	1.00	200.00	/	0.00		Y	_____
TOTAL:		2,270.00	0.00	2,270.00			_____
<u>MATERIALS</u>							
1 REAR LHS DOOR / OD	1.00	2201.43	0.00	1761.14	L	Y	_____
2 REAR BUMPER X CH R	1.00	599.60	119.92	479.68	L	Y	_____
3 REAR LHS FENDER X R	1.00	2,210.30	442.06	1,768.24	L	Y	_____
4 REAR LHS WHEEL CAP / CUT	1.00	186.30	37.26	149.04	L	Y	_____
5 LHS SIDE SKIRT (REPAIR) X R	1.00	0.00	0.00	0.00	L	Y	_____
6 REAR LHS DOOR STICKER- BOOK NOW, COMFORT DELGR0, GOOGLE PLAY APPS STORE / NK	1.00	150.00	80	0.00	S	Y	_____
7 REAR BUMPER CLIPS X	1.00	45.00	0.00	45.00	S	Y	_____
8 REAR LHS FENDER SEALANT X	1.00	100.00	0.00	100.00	S	Y	_____
9 WINDSCREEN DAMPER X	1.00	100.00	0.00	100.00	S	Y	_____
10 WINDSCREEN PRIMER X	1.00	100.00	0.00	100.00	S	Y	_____
11 WINDSCREEN SEALANT X	1.00	100.00	0.00	100.00	S	Y	_____
TOTAL:		3,591.20	599.24	2,991.96			_____
TOTAL PARTS & LABOUR :		5,861.20	599.24	5,261.96			_____

EXCESS/LOADING:\$S 0.00

No. Of Day: _____

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: \$S

P+L = 3290.18

L/S - 2632.14
= 2650

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
DATE OF SURVEY:	17, 03, 2019						
SURVEYED BY:	Steve (LKK)	Wtd PnL		L/S, R/L SK			
CONTACT NO:	83228813			4 dgs			
FAX NO:							

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: