

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9988K**AAD2003-075***Not Authen'd
Permy B4 pain*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHB 9988K

AYH300090081

TOYOTA

ALPHARD

11.3.2020

III

22/11/2019

PART	
1	BUMPER COVER REAR
1	REAR END PANEL
1	TAILGATE
1	SUPPORT, REAR BUMPER SIDE, RH
1	SUPPORT, REAR BUMPER SIDE, LH

LIST	
\$	<i>Bu</i> 2,078.20 ✓
\$	781.70 ?
\$	<i>BT</i> 2,040.50 ✓
\$	<i>Sn</i> 240.00 X
\$	<i>Sn</i> 240.00 X
TOTAL	\$ 5,380.40
25%	\$ 1,345.10
	\$ 4,035.30

Special Nett

1SET	PARKING AID
1 SET	PARKING AID, SENSOR RETAINER
1SET	REAR BUMPER CLIP
1SET	REAR LH SIDE BUMPER SUPPORT CLIP
1SET	REAR RH SIDE BUMPER SUPPORT CLIP
1	PLATE, BACK DOOR - Alphard
1	PLATE, BACK DOOR - E-FOUR
1	EMBLEM SUB-ASSY
1	PLATE, BACK DOOR - TOYOTA LOGO

\$	<i>Scr</i> 4,000.00 <i>Season</i>
\$	<i>Sn</i> 356.00 X
\$	<i>na</i> 80.00 ✓
\$	<i>na</i> 35.00 X
\$	<i>na</i> 35.00 X
\$	<i>na</i> 52.00 ✓
\$	<i>na</i> 41.00 ✓
\$	<i>na</i> 72.40 ✓
\$	<i>na</i> 68.20 X

TOTAL \$ 4,739.60**TOTAL PARTS \$ 8,774.90****LABOUR**

To transfer of bootlid fittings, attachments and perform water seepage test.

\$ 180.00 *60%*

Trans-cab Auto Services Pte Ltd**AAD2003-075**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9988K

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	?
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	bol
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	?
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	120/
To Check Electrical Lighting Concerned.	\$	170.00	bol
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
To reinstall rear bumper parking sensor.	\$	170.00	bol
Putty and spray painting of the affected portion.	\$	7,500.00	660/
Towing Fees	\$	nn 180.00	X

Trans-cab Auto Services Pte Ltd**AAD2003-075**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9988K

To supply and re-do rear luggage floor panel insulation padding.

	\$	<i>na</i> 380.00 X
TOTAL	\$	18,080.00

Over All Total	\$	26,854.90
-----------------------	----	------------------

PART BY PART (REPAIR DAY)~~25 DAYS~~*4-6 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey ~~before~~ after spray painting
- To display ~~damaged~~ part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: