

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9988K****AAD2003-075***Not Authen'd  
Permy B4 pain*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

**SHB 9988K**

AYH300090081

TOYOTA

ALPHARD

11.3.2020

**III**

22/11/2019

	<b>PART</b>
1	BUMPER COVER REAR
1	REAR END PANEL
1	TAILGATE
1	SUPPORT, REAR BUMPER SIDE, RH
1	SUPPORT, REAR BUMPER SIDE, LH

	<b>LIST</b>
	<i>Bu</i> 2,078.20 ✓
	<i>R</i> 781.70 ✗
	<i>Bt</i> 2,040.50 ✓
	<i>Sn</i> 240.00 ✗
	<i>Ln</i> 240.00 ✗
<b>TOTAL</b>	<b>\$ 5,380.40</b>
<b>25%</b>	<b>\$ 1,345.10</b>
	<b>\$ 4,035.30</b>

**Special Nett**

1SET	PARKING AID
1 SET	PARKING AID, SENSOR RETAINER
1SET	REAR BUMPER CLIP
1SET	REAR LH SIDE BUMPER SUPPORT CLIP
1SET	REAR RH SIDE BUMPER SUPPORT CLIP
1	PLATE, BACK DOOR - Alphard
1	PLATE, BACK DOOR - E-FOUR
1	EMBLEM SUB-ASSY
1	PLATE, BACK DOOR - TOYOTA LOGO

	<i>Scr</i> 4,000.00 <i>Season</i>
	<i>Sn</i> 356.00 ✗
	<i>na</i> 80.00 ✓
	<i>na</i> 35.00 ✗
	<i>na</i> 35.00 ✗
	<i>na</i> 52.00 ✓
	<i>na</i> 41.00 ✓
	<i>na</i> 72.40 ✓
	<i>na</i> 68.20 ✗

**TOTAL \$ 4,739.60****TOTAL PARTS \$ 8,774.90****LABOUR**

To transfer of bootlid fittings, attachments and perform water seepage test.

\$ 180.00 *60%*

**Trans-cab Auto Services Pte Ltd****AAD2003-075**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9988K**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	7 700.00
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	bol
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	120/
To Check Electrical Lighting Concerned.	\$	170.00	bol
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
To reinstall rear bumper parking sensor.	\$	170.00	bol
Putty and spray painting of the affected portion.	\$	7,500.00	660/
Towing Fees	\$	nn 180.00	X

**Trans-cab Auto Services Pte Ltd****AAD2003-075**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9988K**

To supply and re-do rear luggage floor panel insulation padding.

	\$	<i>na</i> 380.00 X
<b>TOTAL</b>	\$	<b>18,080.00</b>

<b>Over All Total</b>	\$	<b>26,854.90</b>
-----------------------	----	------------------

**PART BY PART ( REPAIR DAY)**~~25 DAYS~~*4-6 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey ~~before~~ after spray painting
- To display ~~damaged~~ part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: