

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : XE3606Y  
 Accident Date : 14-Mar-2020

No. : 06156

Date : 16-Mar-2020

Our Ref : 020036 (CHINA) / CHAN

PAGE : 1

LEE TECK SENG  
 BLK 112 BISHAN STREET 12  
 #06-163  
 Singapore 570112

*Not Authorized  
 U/Ring @ \$950/h  
 Recovery After Pasing  
 8 days*

ESTIMATED COST OF REPAIR FOR TOYOTA WISH 1.8A SJD4227Y

1 pc Tail gate	<i>Bu</i>	1,210.40	✓
1 pc Tail gate glass	<i>Shatter</i>	1,137.50	✓
1 pc Tail gate glass moulding	<i>na</i>	80.40	✓
1 pc Tail gate inner trim	<i>Bu</i>	348.80	✓
1 pc Tail gate wiper motor	<i>Tr</i>	757.10	✓
1 pc Tail gate wiper blade	<i>CV</i>	52.40	✓
1 pc Tail gate wiper arm	<i>na</i>	89.70	✓
2 pcs Tail gate damper	<i>o/sPu @ S\$224.60</i>	449.20	✓
1 pc Tail gate inner lock	<i>pu</i>	443.50	✓
1 pc Tail gate rubber	<i>Dis Int</i>	304.00	✓ <i>John #152 sn</i>
1 pc Tail gate outer chrome	<i>CM</i>	327.60	✓
1 pc Tail gate logo	<i>na</i>	50.80	✓
2 pcs Rear license plate lamp	<i>o/sCM @ S\$ 56.90</i>	113.80	✓
1 pc Rear bumper fascia	<i>Bu</i>	491.90	✓
1 pc Rear o/s bumper side retainer	<i>Di</i>	89.90	✓
1 pc O/s taillamp	<i>Bu</i>	472.60	✓
1 pc O/s taillamp corner panel	<i>na</i>	84.50	✓
1 pc Rear end panel	<i>Bu</i>	441.20	✓
1 pc Rear o/s fender	<i>Bu</i>	838.50	✓
1 pc Rear o/s fender inner trim	<i>Bu</i>	697.40	✓
1 pc Rear o/s fender quarter glass	<i>Shatter</i>	429.20	✓
1 pc Rear o/s fender inner shield	<i>na</i>	65.60	✓
		8,976.00	<i>8606.40</i>
	Less 25% :	2,244.00	<i>2151.60</i>
			<i>6454.80</i>
1 pc Rear bumper reverse sensor			<i>6,732.00</i>
			<i>shom 300.00 sn</i>
			<i>200JA ✓</i>

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : XE3606Y

Page : 2

- 1 pc Rear no. plate
- 1 pc Rear w/s glass sealant
- 1 pc Rear o/s quarter glass sealant

401N Ad 30.00 sn  
 401N Na 60.00 sn  
 301N Na 40.00 sn

To remove & renew rear windscreen glass and conduct water leak test.

1201  
 150.00

To remove roof lining, front and rear seats, trim board and carpet

1001  
 120.00

To apply undersealing

100.00 701

To putty and spray replaced parts

900.00 8001

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

9001  
 1,000.00

Total : S\$ 9,432.00

Singapore Dollars Nine Thousand Four Hundred and Thirty Two Only

L/SUM  
 6950.00  
 → KENNEDY PLS CONFIRM  
 TKS

P 6454.80  
 SN 247.00  
 L 2010.00  
 -----  
 8711.80  
 1742.36  
 -----  
 6969.44

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: