

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06156

Vehicle Insured : XE3606Y
Accident Date : 14-Mar-2020

Date : 16-Mar-2020

Our Ref : 020036 (CHINA) / CHAN

PAGE : 1

LEE TECK SENG
BLK 112 BISHAN STREET 12
#06-163
Singapore 570112

Not Authorized
U/Ring @ 7
Penalty After Party
8 days

ESTIMATED COST OF REPAIR FOR TOYOTA WISH 1.8A SJD4227Y

1 pc	Tail gate	<i>PA</i>	1,210.40	✓
1 pc	Tail gate glass	<i>Shatter</i>	1,137.50	✓
1 pc	Tail gate glass moulding	<i>na</i>	80.40	✓
1 pc	Tail gate inner trim	<i>Bu</i>	348.80	✓
1 pc	Tail gate wiper motor	<i>Tr</i>	757.10	✓
1 pc	Tail gate wiper blade	<i>CV</i>	52.40	✓
1 pc	Tail gate wiper arm		89.70	7
2 pcs	Tail gate damper	@ S\$224.60	449.20	7
1 pc	Tail gate inner lock	<i>PA</i>	443.50	✓
1 pc	Tail gate rubber	<i>Dis/Tr</i>	304.00	50/na
1 pc	Tail gate outer chrome	<i>CM</i>	327.60	✓
1 pc	Tail gate logo	<i>na</i>	50.80	✓
2 pcs	Rear license plate lamp	@ S\$ 56.90	113.80	7
1 pc	Rear bumper fascia	<i>Bu</i>	491.90	✓
1 pc	Rear o/s bumper side retainer	<i>Dis</i>	89.90	✓
1 pc	O/s taillamp	<i>Bu</i>	472.60	✓
1 pc	O/s taillamp corner panel	<i>PA</i>	84.50	✓
1 pc	Rear end panel	<i>PA</i>	441.20	✓
1 pc	Rear o/s fender	<i>Bu</i>	838.50	✓
1 pc	Rear o/s fender inner trim	<i>Bu</i>	697.40	✓
1 pc	Rear o/s fender quater glass	<i>Shatter</i>	429.20	✓
1 pc	Rear o/s fender inner shield	<i>Tr</i>	65.60	X
			8,976.00	
Less 25% :			2,244.00	
			6,732.00	
1 pc	Rear bumper reverse sensor		300.00	sn

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : XE3606Y

Page : 2

1 pc Rear no. plate
1 pc Rear w/s glass sealant
1 pc Rear o/s quater glass sealant

Ad 25m-
40m Na 30.00 sn
30m Na 60.00 sn
30m Na 40.00 sn

To remove & renew rear windscreen
glass and conduct water leak test.

1201
150.00

To remove roof lining, front and
rear seats, trim board and carpet

1001
120.00

To apply undersealing

100.00 *701*

To putty and spray replaced parts

900.00 *8001*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

9001
1,000.00

Total : S\$ 9,432.00
=====

Singapore Dollars Nine Thousand Four Hundred
and Thirty Two Only