



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SJR 872 L
KIA PICANTO

ATTN	NO.	DESCRIPTION - PARTS	QTY	PRICE
	1	REAR WINDSCREEN 435 <i>brw</i> ✓	1	\$841.00
	2	REAR WINDSCREEN MOULDING 135 <i>nei</i> ✓	1	\$361.00
	3	TAILGATE 754 <i>bt</i> ✓	1	\$1,170.00
	4	TAILGATE WIPER ARM <i>x</i> ✓	1	NIL.
	5	TAILGATE WIPER MOTOR <i>x</i> ✓	1	NIL
	6	TAILGATE WIPER MOTOR COVER <i>x</i> ✓	1	NIL.
	7	TAILGATE CENTER HANDLE <i>cm</i> ✓	1	\$267.00
	8	TAILGATE CENTER HANDLE LICENSE PLATE LAMP <i>3xnn</i>	2	\$244.00
	9	TAILGATE CENTER OPENER <i>xnn</i>	1	\$61.00.
	10	TAILGATE CENTER HANDLE LOGO <i>nei</i> ✓	1	\$144.00
	11	TAILGATE EMBLEM <i>nei</i> ✓	1	\$67.00
	12	TAILGATE CYLINDER LOCK <i>x</i> ✓	1	\$306.00
	13	TAILGATE INNER TRIM LOWER <i>nn</i> ✓	1	\$523.00.
	14	TAILGATE INNER TRIM TOP <i>nn</i> ✓	1	\$314.00
	15	TAILGATE WEATHERSTRIP <i>nn</i> ✓	1	\$341.00
	16	REAR TAILLAMP L+R 390 <i>LH-cm</i> ✓ <i>RH-8nn</i>	2	\$872.00.
	17	REAR TAILLAMP PANEL L+R <i>nn</i> ✓ <i>Ry</i>	2	\$639.00
	18	REAR BUMPER 490 <i>dei</i> ✓	1	\$648.00
	19	REAR BUMPER SIDE PROTECTOR L+R <i>nn</i> <i>x</i>	2	\$10.00.
	20	REAR BUMPER RETAINER L+R 192 <i>nei</i> ✓	2	\$304.00.
	21	REAR BUMPER REINFORCEMENT BAR <i>nn</i> <i>x</i>	1	NIL.
	22	REAR BUMPER SPONGE <i>nn</i> ✓	1	NIL.
	23	REAR FENDER L+R <i>Ry</i>	2	\$3450.00.
	24	REAR FENDER INNER TRIM TOP L+R <i>nn</i> <i>x</i>	2	\$12.00.
	25	REAR FENDER INNER TRIM BTM L+R <i>nn</i> <i>x</i>	2	\$1,240.00
	26	REAR FENDER COWLING L+R 262 <i>dei</i> ✓	2	\$524.00.
	27	END PANEL <i>plup</i> <i>R</i> ✓	1	\$1,319.00
	28	END PANEL TOP GARNISH <i>nn</i> ✓	1	\$919.00
	29	SPARE WHEEL PANEL <i>Ry</i>	1	\$1,657.00.
	30	SPARE WHEEL TOP BOARD <i>nn</i> ✓	1	\$457.00
	31	EXHUAUST PIPE <i>nn</i> ✓	1	\$464.00
	32	EXHUAUST GASKET <i>nn</i> ✓	1	\$72.00
	33	EXHUAUST HEAT SEAL <i>nn</i> ✓	1	\$421.00
	34	EXHUAUST MOUNTING <i>nn</i> ✓	1	\$146.00.
		3133		
		10% - 2819.70		
		SUBTOTAL	\$	-
		LESS 10%	\$	-
		PARTS TOTAL	\$	-

SPECIAL NETT			QTY	PRICE
1	REAR NUMBER PLATE	45 hr	1	\$ 120.00
2	REVERSE SENSOR	200 hr	1	\$ 300.00
3	REAR END PANEL SEALANT	nn 40X	1	\$ 120.00
4	SPARE WHEEL PANEL SEALANT	Xnn	1	\$ 120.00
5	REAR BUMPER CLIPS	30 hr	10	\$ 120.00
6	REAR FENDER COWLING CLIPS	20 hr	10	\$ 120.00
7	REAR FENDER INNER TRIM CLIPS	nn X	10	\$ 120.00
8	BOOTLID INNER TRIM CLIPS	20 hr	10	\$ 120.00
9	REAR END PANEL TOP GARNISH CLIPS	SIN = \$375 20 hr	10	\$ 120.00
			335	
SPECIAL NETT TOTAL				\$ 1,260.00
LABOUR			QTY	PRICE
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK & REALIGN	1000	1	\$ 3,600.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1000	1	\$ 3,600.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	50	1	\$ 120.00
4	TO RNR REAR WINDSCREEN	120	1	\$ 400.00
5	TO RNR REAR BOOT MECHANISM	60	1	\$ 120.00
6	TO RNR UPHOSTERY, GARNISH AND ATTACHMENT PARTS	60	1	\$ 120.00
7	TO RNR REVERSE SENSOR & CHECK FUNCTION.	30	1	\$ 300.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	X	1	\$ 250.00
9	TO RNR UNDERCARRIAGE SYSTEM	nn X	1	\$ 120.00
10	TO CHECK WHEEL ALIGNMENT	X	1	\$ 250.00
11	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION	30	1	\$ 120.00
12	TO RNR TYRE AND WHEEL BALANCING	X	1	\$ 250.00
13	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE.	nn X	1	\$ 300.00
14	TO DO WATER LEAK TEST.	X	1	\$ 120.00
15	TO RNR FUEL TANK TO ASSIST WORK LOAD	photo 150 Rm	1	\$ 500.00
16	TO CLEAN AND VACUUM GLASSES TO ASSIST WORK LOAD	60	1	\$ 300.00
			2410	
L \$2410			LABOUR TOTAL	\$ 10,470.00
			GRAND TOTAL COST	\$ 11,730.00
				27,919.20#

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey to forelater spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party supply on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2819.70
335
2410

5564.70
1/594450
Repair limit \$4000
07 days

Taylor 97495749
- WP
17/3/2021 1645
Lump sum 07 days
Resurvey after repair
To check repair limit.
Suekhawtawm.

PAGE 2 OF 3

30018