Individual Statement





Police Station Of Origin:

Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

1 of 3

Report No. T/20200316/2045

REPORT	OF A TRAFF	IC ACCIDENT				
	me Report 020 12:41	Station Diary No.:				
Informa	ant's Partic	ulars				
	of Informant MMAD AKB	: AR BIN PAIMIN	Address: APT BLK 130 MARSI 730130	LING RISE #03-338 SINGAPORE		
ID Type / ID No.: NRIC NO / \$8302743F			Contact No.: Home/Office: Mobile: 98525905			
Nationa SINGAP	lity: PORE CITIZ	ŒN	Email:			
Sex: Male	Age: 37	Date of Birth: 04/02/1983	Type of Informant: Driver			
Race: Malay			Language:	Institution / School Name:		
Occupation:			Driving Licence Inform	nation:		

Type of Accident:	Injury Conveyed By Ambula	nce Drive:	Date/Time of Accident: 13/03/2020 19:	Type of Location
Location: Along Road 1 LORNIE ROA LORNIE RD:	UPP THOMSON			
Weather:		Road Surface:		Dood Coood Limits
rreadict.		ricad Guilace.		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:

Details of Vehicle Involved							
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenge	
SJR872L	Car	KIA	PICANTO 1.1(M)	Silver		0	

Details of Vehicle Insurance							
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date			
SJR872L	NTUC Income Insurance Co-Operative Limited	5091087727-02	09/06/2019	08/06/2020			

Individual Statement





Police Station Of Origin: Traffic Police

Report No. T/20200316/2045

10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

CONTINUATION OF REPORT

Any Pedestrian I				A PERSONAL PROPERTY.				
No. of Pedestriar			Use of Pec	destriar	Cross	sing: NA		
Driver								
Name	MUHAMMAD AKBA	R BIN PAIMI	N	ID No	-	S8302743F		
Related Vehicle	NIL			Contact No.		98525905		
Hospital/Clinic	TAN TOCK SENG H	IOSPITAL		Class Drivin Licent Expiry	g	Class: NIL Date of Expiry: NIL		
Date Treatment	13/03/2020		Date Disch			/2020		
No. of Days grant	ted Medical Leave	02	Degree of	Injury	NIL			

Brief Details.

On stated date, time and location

I WAS CAUGHT IN A CONGESTION ALONG LORNIE RD. I WAS STATIONARY BEHIND A CAR. SUDDENLY A CAR HIT ME FROM THE REAR. I WAS THEN CONVEYED TO HOSPITAL

Individual Statement





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 3 of 3 Report No. T/20200316/2045

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

TP / MUHAMMAD SYUKRI BIN ZAINI	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 16/03/2020 12:41
Officer In Charge Of Case:	Classification Of Case:
Sgt 3 MARIAH BINTE ZAKARIA	6-V
Contact No.: 65476433	SINGAPORE POLICE FORCE
Authentication Stamp NP168	
	Signature:



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 ,#02-24 Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com Tel: 6286 6060 , FAX: 6286 7060

VECHICLE NUM: MAKE & MODEL: MILEAGE: TYRE: CHASSIS NUM:

,00		
	SJR 872 L	
	KIA PICANTO	

NO.	DESCRIPTION - PARTS		QTY	PR	HCE
	REAR WINDSCREEN	bro	1		
2	REAR WINDSCREEN MOULDING	ner be	1		
3	TAILGATE	b6-	1		
4	TAILGATE WIPER ARM	×	1		
5	TAILGATE WIPER MOTOR	×	1		
6	TAILGATE WIPER MOTOR COVER	×	1		
7	TAILGATE CENTER HANDLE	CV9 /	1		
8	TAILGATE CENTER HANDLE LICENSE PLATE LAMP	?	2		
9	TAILGATE CENTER OPENER	×	1		
	TAILGATE CENTER HANDLE LOGO	nle/	1		1000 1000
	TAILGATE EMBLEM	rec	1		
(TAILGATE CYLINDER LOCK	×	1		
No. Company	TAILGATE INNER TRIM LOWER	7	1		
	TAILGATE INNER TRIM TOP	?	1		
	TAILGATE WEATHERSTRIP	7	1		
	REAR TAILLAMP L+R	-cu/RM-7	2		
	REAR TAILLAMP PANEL L+R	der RH-?	2		
1000	REAR BUMPER	10/	1		
17 (200)	REAR BUMPER SIDE PROTECTOR L+R	×	2		
	REAR BUMPER RETAINER L+R	NU	2		
	REAR BUMPER REINFORCEMENT BAR	×	1		
	REAR BUMPER SPONGE	7	1		
	REAR FENDER L+R	R>	2		
500.00	REAR FENDER INNER TRIM TOP L+R	×	2		
	REAR FENDER INNER TRIM BTM L+R	×	2		
	REAR FENDER COWLING L+R	der	2		
		up 7	1		
1,000,000	END PANEL TOP GARNISH	7	1		
2000	SPARE WHEEL PANEL	R'γ	1		
227/88	SPARE WHEEL TOP BOARD	7	1		
	EXHUAST PIPE	×	1		
	EXHUAST GASKET		1		
	EXHUAST HEAT SEAL	X	1		
	EXHUAST MOUNTING	×	1		
		SUBTOTAL		S	-
		LESS 10%		\$	-
		PARTS TOTAL		S	-

	SPECIAL NETT	QTY		PRICE
1	REAR NUMBER PLATE 45 ht	1	S	120.00
2	REVERSE SENSOR 200 AWV	1	s	300.00
3	REAR END PANEL SEALANT 40 7	1	s	120.00
4	SPARE WHEEL PANEL SEALANT X	1	s	120.00
5	REAR BUMPER CLIPS 30 Net	10	\$	120.00
6	REAR FENDER COWLING CLIPS 20 me/	10	\$	120.00
7	REAR FENDER INNER TRIM CLIPS	10	\$	120.00
8	BOOTLID INNER TRIM CLIPS 20 Mg/	10	S	120.00
9	REAR END PANEL TOP GARNISH CLIPS 20 mg	10	s	120.00
	SPECIAL NETT TOTAL		\$	1,260.00
	LABOUR	QTY		PRICE
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD , KNOCK&REALIGN	1	\$	3,600.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA /000	1	\$	3,600.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA 50	1	\$	120.00
4	TO RNR REAR WINDSCREEN /20	1	\$	400.00
5	TO RNR REAR BOOT MECHANISM \mathcal{O}	1	\$	120.00
6	TO RNR UPHOSTERY, GARNISH AND ATTACHMENT PARTS $\mathcal{G} \mathcal{O}^-$	1	\$	120.00
7	TO RNR REVERSE SENSOR & CHECK FUNCTION.	1	\$	300.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	1	\$	250.00
9	TO RNR UNDERCARRAIGE SYSTEM ×	1	\$	120.00
10	TO CHECK WHEEL ALIGNMENT X	1	\$	250.00
11	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION 30.	1	\$	120.00
12	TO RNR TYRE AND WHEEL BALANCING X	1	\$	250.00
13	TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE. $\qquad \qquad \bowtie$	1	\$	300.00
14	TO DO WATER LEAK TEST . ×	1	\$	120.00
15	TO RNR FUEL TANK TO ASSIST WORK LOAD	1	\$	500.00
16	TO CLEAN AND VACUUM GLASSES TO ASSIST WORK LOAD ()	1	\$	300.00
	LABOUR TOTAL		\$	10,470.00
	GRAND TOTAL COST		\$	11,730.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

PAGE 2 OF 2

17/3/2001645

Crupsin 07 days
errary orthe report

mit.
Suvelikanters in