



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SJM 8879 C
MAZDA RX 8

ATTN:

NO.	DESCRIPTION - PARTS	QTY	PRICE
1	FRONT BONNET <i>Kp</i>	1	\$ 1292.00
2	FRONT HEADLAMP L+R <i>\$1402.10 L+R. crg/RH X nn</i>	2	\$ 3920.00
3	FRONT HEADLAMP BRACKET L+R <i>x nn</i>	2	\$ 240.00
4	FRONT BUMPER <i>870 de</i>	1	\$ 1087.00
5	FRONT BUMPER LOGO <i>ann</i>	1	\$ 87.00
6	FRONT BUMPER GRILLE <i>377 aut</i>	1	\$ 457.00
7	FRONT BUMPER GRILLE TOW COVER L+R <i>x nn</i>	2	\$ 12.00
8	FRONT BUMPER FOG LAMP GRILLE L+R <i>x nn</i>	2	\$ 446.00
9	FRONT BUMPER REINFORCEMENT BAR <i>\$465 crg ✓?</i>	1	\$ 621.00
10	FRONT BUMPER SPONGE <i>\$122.60 crg ✓?</i>	1	\$ 273.00
11	FRONT BUMPER RETAINER L+R <i>de ✓?</i>	2	\$ 178.00
12	FRONT BUMPER TOP SEAL <i>rel ✓?</i>	1	\$ 115.00
13	FRONT FENDER L+R <i>nn x</i>	2	\$ 1846.00
14	FRONT FENDER COWLING L+R <i>x</i>	2	\$ 422.00
15	FRONT FENDER INNER PANEL L+R <i>x</i>	2	\$ 1646.00
16	FRONT SUPPORT PANEL <i>x</i>	1	\$ 2055.00
17	FRONT SUPPORT PANEL TOP GARNISH <i>x</i>	1	\$ 412.00
18	AIR CON CONDENSER <i>x</i>	1	\$ 1134.00
19	HIGH PRESSURE HOSE <i>x</i>	1	\$ 401.00
20	LOW PRESSURE HOSE <i>x</i>	1	\$ 376.00
21	RADIATOR <i>x</i>	1	\$ 1877.00
22	SUCTION PIPE <i>x</i>	1	\$ 247.00
23	DISCHARGE PIPE <i>x</i>	1	\$ 240.00
24	AIR CON FAN COWLING <i>x</i>	1	\$ 487.00
25	AIR CON FAN BLADE <i>x</i>	1	\$ 422.00
26	AIR CON FAN MOTOR <i>x</i>	1	\$ 559.00
27	REAR BOOTLID <i>x</i>	1	\$ 1379.00
28	REAR BOOTLID LOGO <i>x</i>	1	\$ 95.00
29	REAR BOOTLID EMBLEM 'RX8' <i>x</i>	1	\$ 112.00
30	REAR BOOTLID EMBLEM 'MAZDA' <i>x</i>	1	\$ 78.00
31	REAR BOOTLID INNER TRIM <i>x</i>	1	\$ 293.00
32	REAR BOOTLID WEATHERSTRIP <i>x</i>	1	\$ 189.00
33	TAILLAMP L+R <i>x</i>	2	\$ 1256.00
34	TAILLAMP PANEL L+R <i>x</i>	2	\$ 862.00
35	REAR BUMPER <i>972.50 de ✓</i>	1	\$ 1051.00
36	REAR BUMPER RETAINER L+R <i>rel ✓ ?</i>	2	\$ 160.00
37	REAR BUMPER BRACKET L+R <i>x nn</i>	2	\$ 284.00
38	REAR BUMPER REINFORCEMENT <i>bt ✓?</i>	1	\$ 535.00
39	REAR BUMPER SPONGE <i>nn x</i>	1	\$ 297.00
40	REAR FENDER L+R <i>nn x</i>	2	\$ 5088.00

[illegible]

	LABOUR TOTAL	\$ 11,210.00
	GRAND TOTAL COST	\$ 14,850.00

PAGE 2 OF 2

5594

650

1810

8054

4) \$6400 #
7 days

Taufik 97495745

WP

17/3/20 @ 8pm - 4pm

Cum sum

Passing after report.

G-7 days

Taufik @ khant.com

guc @ khant.com