

DATE: 17/03/2020

QUOTATION - THIRD PARTY CLAIM

INDIA INTL. SINGAPORE

Attn: Motor Claim Department . Officer In Charge

Accident on : 14/03/2020

Not Authorised
11/1/2020

Resony After Rain

12 days

Claim : Third Party Claim
 Veh. No : GBD 3021A
 Model : NISSAN CABSTAR
 Insured Ins: LIBERTY INSURANCE
 GST Reg. No : 19 - 9603355 - R

QTY	PARTICULARS	NETT LESS 10 %	LISTS LESS 30 %	S/NETT
	YOUR INSURED SHC 8432Z			
1-2	FRONT W/SCREEN MOULDING BOTTOM	\$ 260.00	\$ -	\$ -
2	FRONT W/SCREEN SIDE MOULDINGS	\$ 180.00	\$ -	\$ -
1	FRONT W/SCREEN SEALANT	\$ -	\$ -	\$ 150.00
2	FRONT W/SCREEN PILLARS	\$ -	\$ 1,560.00	\$ -
1	FRONT W/SCREEN PILLAR INNER GARNISH LH	\$ -	\$ 280.00	\$ -
2	SIDE MIRROR LOWER COVERS	\$ 156.00	\$ -	\$ -
1	SIDE MIRROR LH	\$ 148.90	\$ -	\$ -
1	FRONT CENTRE PANEL	\$ -	\$ 1,783.60	\$ -
1	FRONT CABSTAR EMBLEM	\$ 61.00	\$ -	\$ -
1	FRONT GRILLE	\$ 520.00	\$ -	\$ -
1	FRONT GRILLE CENTRE LOGO	\$ 59.00	\$ -	\$ -
1	FRONT GRILLE LOWER PANEL	\$ 220.00	\$ -	\$ -
2	HEADLAMPS	\$ 991.20	\$ -	\$ -
1	HEADLAMP BRACKETS	\$ 80.00	\$ -	\$ -
2	HEADLAMP LOWER APRON PANELS	\$ 320.00	\$ -	\$ -
1	FRONT SIDE APRON PANEL LH	\$ -	\$ 454.70	\$ -
1	FRONT SIDE APRON PANEL RH	\$ -	\$ 454.70	\$ -
1	FRONT BUMPER	\$ -	\$ 1,125.00	\$ -
1	FRONT BUMPER BRACKETS	\$ 220.00	\$ -	\$ -
1	FRONT BUMPER REINFORCEMENT	\$ -	\$ 325.60	\$ -
1	FRONT No.PLATE	\$ -	\$ -	\$ 65.00
1	FRONT A/C CONDENSER	\$ -	\$ -	\$ 801.50
1	FRONT A/C BLOWER	\$ -	\$ -	\$ 980.00
1	FRONT A/C INLET HOSE	\$ -	\$ 380.50	\$ -
1	FRONT A/C OUTLET HOSE	\$ -	\$ 375.60	\$ -
1	AIRCON AUTO FAN MOTOR	\$ -	\$ -	\$ -
1	HORN	\$ 140.00	\$ -	\$ -
2	FRONT CHASSIS	\$ -	REPAIR	\$ -
2	FRONT CHASSIS TOP BRACKETS	\$ -	\$ 480.50	\$ -
1	FRONT CENTRE INNER BEAM	\$ -	\$ 980.56	\$ -
1	FRONT DOOR LH	\$ -	\$ 1,696.80	\$ -
1	FRONT DOOR TRIM BOARD LH	\$ -	\$ 785.50	\$ -
1	FRONT WHEEL ARCH PANEL	\$ -	\$ -	\$ -
1	FRONT DOOR REAR PILLAR	\$ -	\$ 2,050.00	\$ -
1	FRONT DOOR GLASS OUTER MOULDING	\$ 130.80	\$ -	\$ -
1	FRONT DOOR GLASS QUARTER GARNISH	\$ 121.00	\$ -	\$ -
1	FRONT DOOR LOCK LH	\$ 385.60	\$ -	\$ -
1	FRONT DOOR WEATHERSTRIP LH	\$ 138.00	\$ -	\$ -
1	FRONT DOOR PILLAR WEATHERSTRIP LH	\$ 121.00	\$ -	\$ -
1	FRONT DOOR PILLAR LOWER GARNISH	\$ 80.00	\$ -	\$ -
1	FRONT DOOR STICKER LH	\$ -	\$ -	\$ -
1	FRONT DOOR HINGES LH	\$ 112.80	\$ -	\$ -
1	FRONT DOOR CENTRE CHANNEL LH	\$ 148.00	\$ -	\$ -
1	FRONT DOOR LOCK LATCH LH	\$ 95.00	\$ -	\$ -

400.00

25.00

X SVC
 X SVC
 X SVC
 X SVC

SVC
 SVC

500.00

350.00

LABOUR CHARGE TO REPAIR ,REPLACE ACCIDENT AFFECTED AREA	\$	2,500.00
LABOUR TO DO BODY CHASSIS ALIGNMNET	\$	380.00
LABOUR TO REPLACE DASHBOARD PARTS	\$	280.00
TO REPLACE AIR CON CONDENSER, PIPE & BLOWER	\$	220.00
LABOUR TO REMOVE REFIT, REPLACE LORRY SEAT , SIDE TRIM , GARNISH UPHOLSTERY	\$	350.00
LABOUR TO REMOVE,REFIT W/SCREEN &DOOR GLASS	\$	140.00
TRANSFER DAMAGED PARTS TO ANOTHER DOOR	\$	100.00
TO CHECK ACCIDENT AFFECTED WIRIING SYSTEM , FORCUS HEADLAMP	\$	100.00
TO SPARY PAINTING ON AFFECTED AREA	\$	2,000.00
TO SPRAY ANIT-RUST ON AFFECTED AREA	\$	200.00
LABOUR TO REMOVE & REFIT FRONT UNDERCARRIAGE - LEFT SIDE AND ALIGN NECESSARY	\$	200.00
TO COMPUTER WHEEL ALIGNMENT	\$	80.00
TOTAL LABOUR :	\$	6,550.00
GRAND TOTAL PARTS & LABOUR :		