COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

MAKE

SHA4684A VEHICLE NO

DATE 13/03/2020

CHIANG/CHINA

Qty	Parts Description/ Labour	Туре	Unit Price	Amount
	1REAR BUMPER ×(R)			\$458.60
	1 REAR BUMPER SIDE RETAINER XAM			\$112.70
	1 REAR RH FENDER 800			\$836.70
	1 REAR RH DOOR PS			\$1,258.30
	1REAR FENDER SHIELD RHXXXX			\$134.20
	1 REAR DOOR HANDLE RH × (R)			\$95.30
	1 WHEEL HUB CAP RH SCV			\$177.70
	1 REAR BUMPER TOWING COVER ★ ㅆ^			\$82.70
	SUB TOTAL			\$3,156.20
	25.00%	-		\$789.05
	DISCOUNTED TOTAL			\$2,367.15
	1 REAR DOOR APP LOGO NEC			\$80.00
	1 FRONT DOOR COMFORT LOGO VCC			\$78.00
				\$285.70
	Labour Charge			
	Panel Beating			\$1,280.00
	Spray Painting Charge			\$800.00
	Tranfer Door Part to New Door			\$90.00
	Remove/refix Upholstery Rear			\$90.00
	Tuff Kote			\$60.00
	Check Lighting			\$60.00
	Remove/refix reverse sensor			\$60.00
	TOTAL LABOUR			\$2,440.00
	ESTIMATE TOTAL			\$5,092.85

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ram(LKK)
1430Ws
1430Ws
Paraseram Quexando com
88622778 (45)
Aft repair photo
Arepair Lays