

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

02 MAR 2020

ESTIMATE

Estimate No. : b1 54639
Date Estimated : 02/03/2020
Prepared By : Foong Shiuh Jye

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Chua Zhiqiang, Alvin (Cai ZhiQiang)
21 Pasir Ris Rise
#06-44

Singapore 518090

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKK415Z	WBA5A520X0D823554	27/05/2015	528ia	0

DESCRIPTION

VALUE

To replace bumper rear cover, boot lid, tail end panel,
luggage compartment floor end peice and crossmember trunk
floor

~~1700~~ 4,250.00 ✓

To spray paint bumper rear cover, boot lid,
tail end panel, luggage compartment floor end piece
and crossmember trunk floor

~~2076~~ 3,350.00 ✓

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct checks for
proper function.

150 ✓ 177.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 ✓ 177.00

Sundries.

150.00 ✓

Total Labour 1: 8,104.00

DESCRIPTION

QTY

PRIC

VALUE

CROSS MEMBER TRUNK FLOOR REAR ? X NN

1 329.10 329.10

END PIECE FOR CARGO AREA FLOOR ? X NN

1 84.95 84.95

TAIL END PANEL ✓ DD

1 821.40 821.40

BOOTLID

1 1,650.65 1,650.65

SET MOUNTS PDC SENSOR REAR ~~MC~~ X NN

1 58.90 58.90

Set of mount X NN

1 63.55 63.55

RR BUMPER BOTTOM CENTRE GUIDE ? ✓ MIS

1 58.25 58.25

REAR BUMPER CENTRE GUIDE ? ✓ BR

1 67.45 67.45

RR RH MOUNT X NN

1 193.15 193.15

REAR BUMPER PRIMED (PDC) / DD

1 1,571.95 1,571.95

EMBLEM GROMMET / MC

2 0.85 1.70

MODEL LETTERING 528I / MC

1 64.45 64.45

BMW EMBLEM 82MM / MC

1 71.60 71.60

REAR RIGHT COVERING ? ✓ BR

1 84.20 84.20

DECOUPLING RING PDC TORQUE CONVERTE ~~MC~~ X NN

4 5.10 20.40



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 54639
Date Estimated : 02/03/2020
Prepared By : Foong Shiuh Jye

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKK415Z	WBA5A520X0D823554	27/05/2015	528ia	0

DESCRIPTION	QTY	PRIC	VALUE
BLIND RIVET AVIBVLB <i>MC</i>	20 40	0.55	11✓ 22.00
SCREW (SF PLUS M5X15) <i>MC</i>	4 2	0.55	2.2✓ 1.10
(DG/SL) BODY ADHESIVE K5B (195ML) ? ✓ NEC	1	331.80	331.80
(DG) CLEANER R1 (100ML) ? ✓ NEC	1	26.15	26.15
PUNCH RIVET N4 ? ✓ NEC	1 8	0.55	0.55✓ 4.40
(S/L) SEAM SEAL 300ML ? ✓ NEC	1	33.80	33.80
Total Parts :			6,300.95

*Steve (LKK) WML April
17/3/20, 11.00 am
P/P
By Bel sy
9 5 days*

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

16,093.45

Acknowledged by Repairer
Signature:
Date:

Labour 1	:	7,679.00
Parts	:	6,300.95
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	978.60
Grand Total	:	14,958.55