

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 54639**
Date Estimated : **02/03/2020**
Prepared By : **Foong Shiuh Jye**

- ESTIMATE REPAIR FOR -
Chua Zhiqiang, Alvin (Cai ZhiQiang)
21 Pasir Ris Rise
#06-44

Singapore 518090

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKK415Z	WBA5A520X0D823554	27/05/2015	528iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To replace bootlid Smart Opener control unit including program and conduct checks for proper function.	451.00		451.00 ✓
# To carry out body cavity preservation. (For bootlid) (Per Panel).	200.00		200.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET ✓ NEC	1.35	9.00		12.15
# BLIND RIVET ✓ NEC	1.35	1.00		1.35
# EXPANDING NUT ✓ NEC	1.00	3.00		3.00
# EXPANDING NUT ✓ NEC	1.00	1.00		1.00
# RR BUMPER CARRIER ✓ BT	775.95	1.00		775.95
# ADAPTOR ✓ NEC	109.35	1.00		109.35
# EXPANDING RIVET D=8MM ✓ NEC	1.10	10.00		11.00
# RH GUTTER STRIP ✓ BR	41.05	1.00		41.05
# PLUG BLACK D=5MM ✓ NEC	0.95	10.00		9.50
# CONTROL UNIT SMART OPENER ✓ BR	497.05	1.00		497.05

SUPPLEMENTARY ITEMS

Total Labour :	651.00
Total Parts :	1,461.40
Total Labour & Parts :	2,112.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: