



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2005516
INV Date 12/08/2020
Reference CC4/EQI20004124/Apa3q2
Code EQI



PROFESSIONAL SERVICE FEE

Vehicle No. SCA 8388M
Insured Veh. SLM 5305C
Claim No. DM20HO00562/JT
Policy No. DMPPHQ19-002196
Accident Date 12/03/2020
Inspection Date 17/03/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC4/EQI20004124/Apa3q2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 12-08-2020		
		Code : EQI		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLM 5305C	Veh. Inspected	SCA 8388M
	Policy No.	DMPPHQ19-002196	Coverage (\$)	0.00
	Claim No.	DM20HO00562/JT	Excess (\$)	0.00
	Assign From	JAIME	Assign Date	17/03/2020
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA CAMRY	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	MR053BK4107054528	Colour	SILVER
	Odometer	114104	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	MICHELIN	6 mm
	L/H Front Tyre	215/60 R16	MICHELIN	6 mm
	R/H Rear Tyre	215/60 R16	MICHELIN	6 mm
	L/H Rear Tyre	215/60 R16	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	12/03/2020	Inspection Date	17/03/2020
	Survey held at	NO 1 KAKI BUKIT AVE 6		
	Repairer	PRECISE AUTO SERVICE		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCA 8388M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER FASCIA	TO REPAIR SEE LABOUR	590.00	-
10	REAR BUMPER CLIPS @\$12.90	NOT NECESSARY	129.00	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	980.00	-
1	REAR WHEEL BEARING HUP	NOT NECESSARY	380.00	-
	LESS 25% DISCOUNT		-519.75	-
			1,559.25	-
	<u>SPECIAL NETT ITEMS</u>			
1	SPARE RIM (SPORT)(SN)	CUT	780.00	400.00
			780.00	400.00
	<u>LABOUR</u>			
	TO TUFF COAT AFFECTED AREAS.		100.00	50.00
	TO RESPRAY AFFECTED AREAS.		700.00	400.00
	TO RENEW DAMAGED PARTS,STRAIGHTEN/REPAIR REAR BUMPER,REAR RH FENDER,REAR RH DOOR AND ALIGNED ALL PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER FASCIA AND REAR FENDER RH.		550.00	200.00
			1,350.00	650.00
GRAND TOTAL			3,689.25	1,050.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				800.00

Report Ref No. CC4/EQI20004124/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SCA 8388M

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

