

# PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34/36 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

17-03-20

Date Of Accident : 12-03-20

Adrian

OUR REF : SCA 8388M/T/20

TPEQ  
Xiao Tong.

STEVEN CHOO BOON AUN  
61 COWDRAY AVENUE  
SINGAPORE 558062

Fax 68416315  
on 17/03/20

**ESTIMATE BILL ON VEH. NO. : SCA 8388M**

**MODEL : TOYOTA CAMRY**

**CHASSIS NO. : MR053BK4107054528**

## LIST ITEM

Rear Bumper Fascia	Repair		X	590.00
Rear Bumper Clips	new	10pcs @ 12.90	X	129.00
Rear Fender RH	Repair		X	980.00
Rear Wheel Bearing Hup	new		X	380.00
				<hr/> 2,079.00
Less Discount 25%:				<hr/> 519.75
				<hr/> 1,559.25

## SPECIAL NETT ITEM

Spare Rim (Sport)	lit	400	400	<del>780.00</del>
-------------------	-----	-----	-----	-------------------

## LABOUR CHARGE

To tuff coat affected areas		650	50	<del>100.00</del>
To respray affected areas			400	<del>700.00</del>
To renew damaged parts, straighten/repair rear bumper, rear RH fender rear RH door and aligned all parts			900	<del>550.00</del>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 3,689.25  
GST 7%: 258.25  
**Amount Due: 3,947.50**

total: 1050  
4/2 800  
03Days