

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 32891

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0287/2020/NS
Date : 16-Mar-20

Vehicle IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Yip Soon Fatt James
Address : 32 Highland Close
Singapore 549245
Telephone : HP +65 96666930
Type of Claim : Own Damage Claims
Policy No. : 2100371940-05
Vehicle No : **SKM 9605 Y**
Model Code : Audi A4 1.8 TFSI MU 8K203
Model / Year : Apr-14
Engine No : CJE 070437
Chassis No : WAUZZZ8KXEA073897
Mileage : 73974
Date In : 15-Mar-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 15-Mar-20
Place of Accident : Lunos link

Premium Automobiles

11, Jalan Rajah 1, Singapore 408699
Tel: 0366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKM 9605 Y

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	360.00	✓
2	To remove and renew lhs front wheel suspension assy.	S/N \$	1,800.00	✗
3	To dismantle and renew front bumper, lhs front fender and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$	2,450.00	1250
4	To respray front bumper and lhs front fender.	\$	2,000.00	1100
5	To renew lhs front rim. To carry out pre-wheel alignment test and post-wheel alignment test.	S/N \$	520.00	260
6	To carry out diagnostic check.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	<u>\$ 7,322.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKM 9605 Y

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Distorted</i>	\$ 2,169.00	✓ 1735.20
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 244.00	+
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i> CRA	\$ 215.00	✓ 171.60
4	FRONT BUMPER GRILLE - LOWER CENTRE <i>new</i>	\$ 127.00	✓ 171.00
5	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE <i>new</i>	\$ 183.00	+
6	FRONT BUMPER SUPPORT ELEMENT - UPPER <i>new</i>	\$ 56.00	+
7	RADIATOR GRILLE <i>new</i>	\$ 1,026.00	+
8	FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	\$ 127.00	+
9	FRONT WHEEL SPOILER - LH <i>new</i>	\$ 48.00	✓ 38.16
10	FRONT BUMPER GUIDE SECTION - LH <i>Damaged</i>	\$ 34.00	✓ 27.12
11	FRONT FENDER - LH <i>Distorted</i>	\$ 932.00	✓ 745.2
12	FRONT FENDER ATTACHMENT PARTS <i>Not new</i>	\$ 54.00	✓ +
13	FRONT FENDER BRACKET - LH <i>Damaged</i>	\$ 50.00	✓ 39.44
14	DEFORMATION ELEMENT BRACKET - LH REAR	\$ 46.00	✓ 36.80
15	FRONT FENDER BRACE - LH LOWER <i>Best</i>	\$ 112.00	✓ 89.20
16	WHEEL HOUSING LINER <i>new</i>	\$ 226.00	✓ 180.40
17	WHEEL HOUSING LINER ATTACHMENT PARTS <i>Not Nec.</i>	\$ 42.00	✗
18	STONE CHIP GUARD <i>new</i>	\$ 69.00	✓ 54.64
19	ADHESIVE TAPE <i>new</i>	\$ 52.00	✓ 40.96
20	HEADLIGHT MOUNTING - LH <i>Not new</i>	\$ 112.00	+
SUB TOTAL SPARE PARTS CHARGES		\$	<u>5,924.00</u>

Premium Automobiles

55 Ubi Road J, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKM 9605 Y

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	HEADLAMP BRACKET - LH <i>nt</i>	\$ 100.00	+
22	HEADLIGHT - LH <i>ht</i>	\$ 2,208.00	✓ 1766.40
23	HALOGEN FOG LAMP - LH <i>ALP un</i>	\$ 247.00	+
24	LIFT CYLINDER - LH	\$ 198.00	+
25	FRONT ALUMINIUM RIM - LH <i>ht</i>	\$ 710.00	✓ 568.00
26	FRONT WISH BONE LINK - LH FRONT <i>nt ne</i>	\$ 507.00	X
27	SUSPENSION GUIDE <i>nt ne</i>	\$ 942.00	X
28	SUSPENSION GUIDE - LH FRONT UPPER <i>nt ne</i>	\$ 507.00	X
29	SUSPENSION GUIDE - LH REAR UPPER <i>nt ne</i>	\$ 507.00	X
30	WHEEL BEARING HOUSING - LH <i>nt ne</i>	\$ 912.00	X
31	SWIVEL JOINT <i>nt ne</i>	\$ 182.00	X
32	WHEEL HUB <i>nt ne</i>	\$ 441.00	X
33	WHEEL BEARING <i>nt ne</i>	\$ 542.00	X
34	COUPLING ROD <i>nt ne</i>	\$ 125.00	X
35	GAS SHOCK ABSORBER <i>nt ne</i>	\$ 286.00	X
36	TRACK ROD <i>nt ne</i>	\$ 93.00	X
37	TIE ROD END - LH <i>nt ne</i>	\$ 166.00	X
38	SUNDRIES <i>nt ne</i>	\$ 300.00	X
TOTAL SPARE PARTS CHARGES		: \$ 14,897.00	
TOTAL LABOUR CHARGES		: \$ 7,322.00	
GRAND TOTAL		: <u>\$ 22,219.00</u>	22,579.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ng
Surveyed Date : 17/03/2000
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised,

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

05 Days (Without Undercarriage)
07 Days (with Undercarriage)

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0287/2020/NS 31-Mar-20 Glory Tan 1 of 1 SKM 9605 Y Audi A4 1.8 TFSI MU 8K203
Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	Front Tyre LH <i>int.</i>	\$ 360.00	\$ 360.00 ✓
TOTAL		\$ 360.00	\$ 360.00

For Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



Authorised Signature