

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0287/2020/NS
23-Mar-20
Glory Tan
1 of 1
SLU 183 C
Audi A3 Sedan 1.4 TFSI CO

Quantity Description

Labours

1 To repair rear lid.

Unit Price Amount

~~\$60~~ 250 ~~700.00~~
\$ 700.00

TOTAL

\$ 700.00

For Premium Automobiles Pte Ltd

Perme

Authorised Signature

*Subject to
insurer approval*

add 1 more day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 32869

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0287/2020/NS
Date	:	16-Mar-20

Vehicle IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Lim Jim Siong Danny
Address	:	Blk 449 Sin Ming Avenue #10-521 Singapore 570449
Telephone	:	HP +65 92259009
Type of Claim	:	Own Damage Claims
Policy No.	:	1800129383
Vehicle No	:	SLU 183 C
Model Code	:	Audi A3 Sedan 1.4 TFSI CO
Model / Year	:	Oct-18
Engine No	:	CZE 836350
Chassis No	:	WAUZZZ8V8K1002221
Mileage	:	
Date In	:	16-Mar-20
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	14-Mar-20
Place of Accident	:	PIE To CTE Towards Bishan

Premium Automobiles

S.S. Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLU 183 C

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function.	S/N \$	280.00	✓
2	To remove and transfer rear lid's convenience lock system, and wire harness for tail lights.	S/N \$	280.00	✗
3	To renew rear windscreen.	S/N \$	480.00	✓
4	To install solar film for rear windscreen.	S/N \$	400.00	✓
5	To install wrapping for rear bumper and rear lid. (by owner)	S/N \$	550.00	✗
SUB TOTAL LABOUR CHARGES			: <u>\$ 1,990.00</u>	

?? To check if this item is insured

Premium Automobiles

101 Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLU 183 C

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
6	To clean up the rear windscreen shards.	S/N \$ 280.00 ✓	
7	To dismantle and renew rear bumper and rear lid. Re-organise rear crash management components. Reinstall all parts removed.	\$ 2,100.00 ✓	500
8	To respray rear bumper and rear lid. ✓	\$ 2,000.00 ✓	550 1100
9	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 6,562.00	

TOTAL LABOUR CHARGES

: \$ 6,562.00

Premium Automobiles

SS Up Road 1, Singapore 408699
Tel: 6366 2123 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLU 183 C

Damage Parts & Prices

S/Nett

Remarks

S/N	Parts Description			
1	REAR BUMPER <i>Del</i>	\$	1,851.00 ✓	
2	REAR BUMPER STICKY PAD <i>new</i>	4 \$	22.00 ✓	
3	REAR BUMPER FIXING PARTS	\$	182.00 +	
4	REAR BUMPER GUIDE SECTION - LH / RH <i>new</i>	2 \$	30.00 +	
5	REAR BUMPER LOCKING MECHANISM	2 \$	55.00 ✓	
6	REAR BUMPER SPOILER <i>gt</i>	\$	223.00 ✓	
7	REAR BUMPER SIDE REINFORCEMENT BEAM <i>new</i>	\$	538.00 +	
8	REAR BUMPER BRACKET - LH <i>new</i>	\$	26.00 +	
9	REAR BUMPER BRACKET - RH <i>new</i>	\$	27.00 +	
10	REAR LID <i>Regis</i>	\$	2,444.00 +	
11	REAR LID ATTACHMENT PARTS <i>new</i>	\$	278.00 +	
12	REAR LID HINGE - LH / RH <i>new</i>	2 \$	482.00 +	
13	REAR LID FLAP GASKET <i>new</i>	\$	193.00 +	
14	PACKING ADHESIVE <i>new</i>	\$	18.00 ✓	
15	AUDI EMBLEM <i>new</i>	\$	117.00 ✓	
16	A3 INSCRIPTION <i>new</i>	\$	90.00 ✓	
17	LED TAIL LIGHT - LH - INNER <i>new</i>	\$	826.00 X	
18	TAIL LIGHT TRIM - LH INNER <i>new</i>	\$	28.00 +	
19	LED TAIL LIGHT - RH INNER <i>new</i>	\$	826.00 +	
20	TAIL LIGHT TRIM - RH INNER <i>new</i>	\$	28.00 +	

SUB TOTAL SPARE PARTS CHARGES

: \$ 8,284.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLU 183 C

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	ADDITIONAL BRAKE LIGHT <i>XL</i>	\$ 221.00	<i>X</i>
22	REAR WINDSCREEN <i>shattered</i>	\$ 766.00	<i>✓</i>
23	PRIMER <i>mu</i>	\$ 19.00	<i>✓</i>
24	REAR NO PLATE <i>not there</i>	S/N \$ 60.00	<i>+</i>
25	REAR WINDSCREEN SEALANT <i>XL</i>	S/N \$ 200.00	<i>✓</i>
26	SUNDRIES <i>?</i>	\$ 300.00	<i>?</i>

TOTAL SPARE PARTS CHARGES
TOTAL LABOUR CHARGES
GRAND TOTAL

: \$ 9,850.00
: \$ 6,562.00
: \$ 16,412.00

All charges are not inclusive of GST.
Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Premium Automobiles

Jbi Road 1, Singapore 408699
6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ling
Surveyed Date : 17/03/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, ~~05 Days~~ 6 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

nnny Boo
dy Repair Manager

Allan Wu
Claims Consultant