

AGS. REC. BY:

REF:

ALG CC31A29 20004134/Asf3

ASSIGNMENT

From: Minim Date: 17/3/2020

Estimated Cost: OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLU 183C

at Workshop m/s Premium

of Upi

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: £0/-

(Client's Record)

Make of Veh: 100am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA (REV) REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLU 183C Yr Regn: 2018 10T

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Audi A3 Sedan c.c. 1395

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 28344 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZ8V8K1002221

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 205/55R16

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front 06 mm R/Bal. 06 mm

L/Bal. 06 mm

D.O.A. _____ D.O.I. 17/03/20

Survey held at Premium

Des. of Damages: Fr / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	OD ALG
	SLU 183C - NA / MSG 20004059/24 DOM - 14/04/2020
18/03/20 @ 10:04 am	revised AA to Syazanne U's minim.
	MV: 96k
	PV: 45.7k
	Nett: 50.3k
18/03/20 @ 10:07 am	market requested authorisation up to PEG
	via minim.

Date/Time, File Pass to?

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 5

1) Typ: 4

Date/Time, File Return to?

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

2)

Add Fee: ☐ : Site Insp (\$) S + RS SI

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Photos

Others

Rep. Format:

Lump Sum / LB / C: £6,698.00 r/p

TOTAL

19/03/20 @ 13:36 pm mandate approved by Victor
koh via messenger.

19/03/20 @ 14:57 pm informed Ch to Kee Siang
via email.

P/P \$6,698.00 @ 5 days, finalize with JB.
(\$10,414.00 Red - 61%)

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 32869

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0287/2020/NS
Date	:	16-Mar-20

Vehicle IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Lim Jim Siong Danny
Address	:	Blk 449 Sin Ming Avenue #10-521 Singapore 570449
Telephone	:	HP +65 92259009
Type of Claim	:	Own Damage Claims
Policy No.	:	1800129383
Vehicle No	:	SLU 183 C
Model Code	:	Audi A3 Sedan 1.4 TFSI CO
Model / Year	:	Oct-18
Engine No	:	CZE 836350
Chassis No	:	WAUZZZ8V8K1002221
Mileage	:	
Date In	:	16-Mar-20
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	14-Mar-20
Place of Accident	:	PIE To CTE Towards Bishan

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLU 183 C

S/N Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00	✓
2	To remove and transfer rear lid's convenience lock system, and wire harness for tail lights.	S/N \$ 280.00	✗
3	To renew rear windscreen.	S/N \$ 480.00	✓
4	To install solar film for rear windscreen.	S/N \$ 400.00	✓
5	To install wrapping for rear bumper and rear lid. (by owner)	S/N \$ 550.00	✗ ? ? To check ✓ if this item is insured.
SUB TOTAL LABOUR CHARGES		: <u>\$ 1,990.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLU 183 C

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
6	To clean up the rear windscreen shards.	S/N	\$ 280.00 ✓	
7	To dismantle and renew rear bumper and rear lid. Re-organise rear crash management components. Reinstall all parts removed.		\$ 2,100.00 500	
8	To respray rear bumper and rear lid. ✓		\$ 2,000.00 550	1,100/-
9	To carry out diagnostic check.	S/N	\$ 192.00 ✓	
TOTAL LABOUR CHARGES		:	<u>\$ 6.562.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLU 183 C

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER <i>del</i>	\$ 1,851.00 ✓	1480.80
2	REAR BUMPER STICKY PAD <i>neu</i> 16/09/20 @ 14:31pm Adrian Say Put N/A	\$ 22.00 ✓	X
3	REAR BUMPER FIXING PARTS	\$ 182.00 +	
4	REAR BUMPER GUIDE SECTION - LH / RH <i>neu</i>	2 \$ 30.00 +	
5	REAR BUMPER LOCKING MECHANISM	2 \$ 55.00 +	
6	REAR BUMPER SPOILER <i>ht</i>	\$ 223.00 ✓	178.40
7	REAR BUMPER SIDE REINFORCEMENT BEAM <i>neu</i>	\$ 538.00 +	
8	REAR BUMPER BRACKET - LH <i>neu</i>	\$ 26.00 +	
9	REAR BUMPER BRACKET - RH <i>neu</i>	\$ 27.00 +	
10	REAR LID <i>Regis</i>	\$ 2,444.00 +	
11	REAR LID ATTACHMENT PARTS <i>neu</i>	\$ 278.00 +	
12	REAR LID HINGE - LH / RH <i>neu</i>	2 \$ 482.00 +	
13	REAR LID FLAP GASKET	\$ 193.00 +	
14	PACKING ADHESIVE <i>neu</i>	\$ 18.00 ✓	14.24
15	AUDI EMBLEM <i>neu</i>	\$ 117.00 ✓	93.20
16	A3 INSCRIPTION <i>neu</i>	\$ 90.00 ✓	71.76
17	LED TAIL LIGHT - LH - INNER <i>neu</i>	\$ 826.00 X	
18	TAIL LIGHT TRIM - LH INNER <i>neu</i>	\$ 28.00 +	
19	LED TAIL LIGHT - RH INNER <i>neu</i>	\$ 826.00 +	
20	TAIL LIGHT TRIM - RH INNER <i>neu</i>	\$ 28.00 +	
SUB TOTAL SPARE PARTS CHARGES		: \$ 8,284.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLU 183 C

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/Nett	Remarks
21	ADDITIONAL BRAKE LIGHT <i>xlu</i>	\$ 221.00	<i>x</i>
22	REAR WINDSCREEN <i>shattered</i>	\$ 766.00	<i>✓ 612.80</i>
23	PRIMER <i>mu</i>	\$ 19.00	<i>✓ 14.80</i>
24	REAR NO PLATE <i>not nee</i>	S/N \$ 60.00	<i>+</i>
25	REAR WINDSCREEN SEALANT <i>xu</i>	S/N \$ 200.00	<i>✓</i>
26	SUNDRIES <i>Not nee</i>	\$ 300.00	<i>? X</i>
TOTAL SPARE PARTS CHARGES		: \$ 9,850.00	
TOTAL LABOUR CHARGES		: \$ 6,562.00	
GRAND TOTAL		: <u>\$ 16,412.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

17,112.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Adrian Ling
: 17/03/20.
:
:
:
:
: Not Authorised, 05 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0287/2020/NS

23-Mar-20

Glory Tan

1 of 1

SLU 183 C

Audi A3 Sedan 1.4 TFSI CO

Quantity	Description
----------	-------------

Labours

1	To repair rear lid.
---	---------------------

Unit Price	Amount
------------	--------

\$ 600	250 H.R.
\$ 700.00	

TOTAL

\$ 700.00

For Premium Automobiles Pte Ltd

Authorised Signature

Repaired
23/03/2020
Subject to
insurer approval
add 1 more day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: