



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2006210
INV Date 10/09/2020
Reference CC6/CTI20004136/Uea3q2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SKR 6283K
Insured Veh. XD 5421E
Claim No. SNM20D201367
Policy No. DMCVSN1394981900
Accident Date 16/03/2020
Inspection Date 16/03/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD	Ref : CC6/CTI20004136/Uea3q2
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909	Date : 10-09-2020
	Code : CTI



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 5421E	Veh. Inspected	SKR 6283K
Policy No.	DMCVSN1394981900	Coverage (\$)	0.00
Claim No.	SNM20D201367	Excess (\$)	0.00
Assign From		Assign Date	16/03/2020

2. Vehicle Particulars & Condition

Make & Model	MAZDA 6 (A)	c.c	2488
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JM6GJ1031F0147012	Colour	GREY
Odometer	120807	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	CONTINENTAL	6 mm
L/H Front Tyre	225/45 R17	CONTINENTAL	6 mm
R/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm
L/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/03/2020	Inspection Date	16/03/2020
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 6283K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOTLID	TO REPAIR SEE LABOUR	1,420.30	-
1	BOOTLID REAR LOGO	NECESSARY	85.20	85.20
1	BOOTLID REFLECTOR GARNISH N/S	CRACKED	166.20	166.20
1	BOOTLID OUTER GARNISH CENTRE	CRACKED	388.50	315.20
1	BOOTLID WEATHERSTRIP	TWISTED	215.30	215.30
1	BOOTLID REFLECTOR N/S	SERVICEABLE	655.20	-
1	REAR BUMPER	DENTED / DEFORMED	1,220.30	1,206.20
1	REAR BUMPER REFLECTOR N/S	CRACKED	66.50	50.40
1	REAR BUMPER REINFORCEMENT	BENT	715.00	512.60
1	REAR BUMPER SIDE RETAINER N/S	NECESSARY	66.50	39.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR END PANEL	DENTED	685.00	619.00
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	315.30	-
1	TAILLAMP N/S	CRACKED	1,250.60	751.00
1	REAR EXHAUST	TO REPAIR SEE LABOUR	1,280.50	-
	LESS 20% DISCOUNT		-	-802.02
			8,580.40	3,208.08
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER LOWER SKIRTING (SN)	DEFORMED / TORN	1,200.00	580.00
1	REAR EXHAUST CHROME (SN)	SERVICEABLE	180.00	-
1	SET REAR BUMPER TOP CARBON STICKER (SN)	NOT FITTED	300.00	-
1	BOOTLID TOP SPOILER (SN)	CRACKED	1,000.00	600.00
1	SET BOOTLID OUTERGARNISH CARBON STICKER (SN)	NECESSARY	300.00	100.00
1	SET REAR REVERSE SENSOR (SN)	SHORTED	380.00	200.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
			3,410.00	1,530.00
<u>LABOUR</u>				
	TO CHECK WIRING .		80.00	20.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE & REPLACING REVERSE SENSOR .		80.00	50.00
	TO TRANSFER BOOTLID COMPONENTS.	NOT NECESSARY	120.00	-
	TO SPRAY RUST PROOFING.		80.00	30.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	80.00
	TO DISMANTLE & REFIX REAR EXHAUST .	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR EXHAUST AND BOOTLID.		1,200.00	700.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	900.00
			3,280.00	1,780.00
	GRAND TOTAL		15,270.40	6,518.08
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,200.00

Report Ref No. CC6/CTI20004136/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKR 6283K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd





51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKR 6283K

RE-INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payco Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKR 6283K

RE-INSPECTION

