

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLE 6941 B

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	✓
2	To dismantle and renew front bumper and rhs headlight. Re-organise crash management components. Reinstall all parts removed.		\$ 1,400.00	\$250 750
3	To respray front bumper.		\$ 900.00	\$50 ✓
4	To carry out diagnostic check.	S/N	\$ 192.00	✓
TOTAL LABOUR CHARGES			:	<u>\$ 2,852.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLE 6941 B

		Damage Parts & Prices	
S/N	Parts Description	S/Nett	Remarks
1	FRONT BUMPER <i>Rehd</i>	\$ 1,894.00	✓ 1515.70
2	FRONT BUMPER FIXING PARTS <i>Neu</i>	\$ 176.00	+
3	FRONT BUMPER COVER TRIM - RH <i>Neu</i>	\$ 153.00	+
4	FRON BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Neu</i>	\$ 153.00	+
5	FRONT BUMPER PULL STRAP - LOWER <i>Neu</i>	4 \$ 194.00	+
6	FRONT BUMPER GUIDE SECTION - RH <i>Neu</i>	\$ 36.00	+
7	FRONT BUMPER AIR GUIDE GRILLE - RH <i>Neu</i>	\$ 103.00	+
8	RADIATOR GRILLE <i>Caused</i>	\$ 650.00	✓ 519.60
9	RADIATOR GRILLE COVER <i>Not Not</i>	\$ 92.00	? X
10	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>Neu</i>	\$ 681.00	+
11	FRONT BUMPER FOAM FILLER PIECE <i>Neu</i>	\$ 129.00	+
12	FOAM FILLER PIECE COVER <i>Neu</i>	\$ 53.00	+
13	CAUTION SIGN STICKER 2	NEC \$ 10.24	13.00 ✓ 536
14	AIRCON STICKER <i>1 Neu</i>	NEC \$ 5.36	7.00 ✓
15	SIGNAL HORN - RH HIGH TONE <i>Neu</i>	\$ 188.00	+
16	HEADLIGHT - RH <i>Not neu caused.</i>	\$ 1,847.00	✓ 1499.20
17	LIFT CYLINDER - RH <i>Not neu</i>	\$ 181.00	? X
18	RADIATOR AIR GUIDE - RH <i>Neu</i>	\$ 23.00	+
19	FRONT NO PLATE <i>Dehted</i>	S/N \$ 60.00	✓ 60
20	SUNDRIES <i>Not Neu</i>	\$ 200.00	? X
TOTAL SPARE PARTS CHARGES		: \$ 6,833.00	
TOTAL LABOUR CHARGES		: \$ 2,852.00	
GRAND TOTAL		: \$ 9,685.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 17/03/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- The survey help to alter spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- Any modification(s) is allowed
- Any repair item(s) must be approved and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant