

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9911G

AAD2003-044

*Not withair
Resony B4 paint*

Vehicle No.:	SHB 9911G
Chassis No.:	AYH300095317
Vehicle Make:	TOYOTA
Vehicle Model:	ALPHARD
Date of Accident :	5.3.2020
Third Party Insurer :	AIG
Date of Registration :	17/1/2020

PART	LIST
1 BUMPER COVER REAR	\$ <i>Rs</i> 2,078.20 ✓
1 REAR END PANEL	\$ 781.70 ✓
1 TAILGATE	\$ <i>Rs</i> 2,040.50 ✓
1 SUPPORT, REAR BUMPER SIDE, RH	\$ <i>Rs</i> 240.00 X
1 SUPPORT, REAR BUMPER SIDE, LH	\$ <i>Rs</i> 240.00 X
TOTAL	\$ 5,380.40
25%	\$ 1,345.10
	\$ 4,035.30

Special Nett

1SET PARKING AID	\$ 4,000.00 ?
1 SET PARKING AID, SENSOR RETAINER	\$ <i>Rs</i> 356.00 X
1SET REAR BUMPER CLIP	\$ <i>Rs</i> 80.00 ✓
1SET REAR LH SIDE BUMPER SUPPORT CLIP	\$ <i>Rs</i> 35.00 X
1SET REAR RH SIDE BUMPER SUPPORT CLIP	\$ <i>Rs</i> 35.00 X
1 PLATE, BACK DOOR - Alphard	\$ <i>Rs</i> 52.00 ✓
1 PLATE, BACK DOOR - E-FOUR	\$ <i>Rs</i> 41.00 ✓
1 EMBLEM SUB-ASSY	\$ <i>Rs</i> 72.40 ✓
1 PLATE, BACK DOOR - TOYOTA LOGO	\$ <i>Rs</i> 68.20 X
TOTAL	\$ 4,739.60
TOTAL PARTS	\$ 8,774.90

LABOUR

To transfer of bootlid fittings, attachments and perform water seepage test.

\$ 180.00 *60k*

Trans-cab Auto Services Pte Ltd

AAD2003-044

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9911G

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	?
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	} <i>bol</i>
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	?
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	<i>12ol</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>2ol</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00	X
To reinstall rear bumper parking sensor.	\$	170.00	<i>bol</i>
Putty and spray painting of the affected portion.	\$	7,500.00	<i>bol</i>
Towing Fees	\$	<i>nn</i> 180.00	X

Trans-cab Auto Services Pte Ltd

AAD2003-044

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9911G

To supply and re-do rear luggage floor panel insulation padding.

	\$	<i>nan</i> 380.00	X
TOTAL	\$	18,080.00	
Over All Total	\$	26,854.90	

PART BY PART (REPAIR DAY)

~~25~~ DAYS

4-6 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey ~~before~~ after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: