

4141/cb

cb

Trans-cab Auto Services Pte Ltd

AAD2003-044

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9911G

*Not Authorise
Resumy B4 paint*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

SHB 9911G
AYH300095317
TOYOTA
ALPHARD
5.3.2020
AIG
17/1/2020

P/P = \$4,814.43

PART	LIST
1 BUMPER COVER REAR	\$ <i>As</i> 2,078.20 <i>✓</i>
1 REAR END PANEL	\$ 781.70 <i>✓ R</i>
1 TAILGATE	\$ <i>As</i> 2,040.50 <i>✓</i>
1 SUPPORT, REAR BUMPER SIDE, RH	\$ <i>Sm</i> 240.00 <i>X</i>
1 SUPPORT, REAR BUMPER SIDE, LH	\$ <i>Sm</i> 240.00 <i>X</i>

TOTAL	\$ 5,380.40
25%	\$ 1,345.10
	\$ 4,035.30

Special Nett	
1SET PARKING AID	\$ 4,000.00 <i>7 X NN</i>
1 SET PARKING AID, SENSOR RETAINER	\$ <i>Sm</i> 356.00 <i>X</i>
1SET REAR BUMPER CLIP	\$ <i>Sm</i> 80.00 <i>✓</i>
1SET REAR LH SIDE BUMPER SUPPORT CLIP	\$ <i>nn</i> 35.00 <i>X</i>
1SET REAR RH SIDE BUMPER SUPPORT CLIP	\$ <i>nn</i> 35.00 <i>X</i>
1 PLATE, BACK DOOR - Alphard	\$ <i>Sm</i> 52.00 <i>—</i>
1 PLATE, BACK DOOR - E-FOUR	\$ <i>Sm</i> 41.00 <i>—</i>
1 EMBLEM SUB-ASSY	\$ <i>Sm</i> 72.40 <i>—</i>
1 PLATE, BACK DOOR - TOYOTA LOGO	\$ <i>nn</i> 68.20 <i>X</i>

TOTAL	\$ 4,739.60
--------------	--------------------

TOTAL PARTS	\$ 8,774.90
--------------------	--------------------

LABOUR

To transfer of bootlid fittings, attachments and perform water seepage test.

\$ 180.00 *6ch*

Trans-cab Auto Services Pte Ltd

AAD2003-044

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9911G

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	7 500/2
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	} 60
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	7 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	120/
To Check Electrical Lighting Concerned.	\$	170.00	20/
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00	X
To reinstall rear bumper parking sensor.	\$	170.00	60/
Putty and spray painting of the affected portion.	\$	7,500.00	660/
Towing Fees	\$	<i>nn</i> 180.00	X

Trans-cab Auto Services Pte Ltd

AAD2003-044

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9911G

To supply and re-do rear luggage floor panel insulation padding.

	\$	<i>now</i> 380.00	X
TOTAL	\$	18,080.00	
Over All Total	\$	26,854.90	

PART BY PART (REPAIR DAY)

~~25~~ **DAYS**

~~4~~ *6 days*

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey ~~before~~ after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: