



# REVO PERFORMANCE PTE LTD

BLK 1 KAKI BUKIT AVE 6 #02-51  
SINGAPORE 417883 (AUTOBAY@KAKI BUKIT)  
TEL : +65 6745 6706 FAX : +65 64843653  
EMAIL : contact@revoperformance.com.sg  
WEBSITE : www.revoperformance.com.sg  
GST REG NO : 201200256H

M/S : AIG Asia Pacific insurance Pte. Ltd.  
78 Shenton Way #07-16  
Singapore 079120  
TEL : 64193000  
ATTN : Motor Claim Department  
Your Ref No : GV 6622 S  
Claim Type : Third Party  
Accident Date : 12/03/2020  
TP Veh Reg No : SKN 136 M

Date : 18 March 2020  
Policy No : DMCPHQ19-005461  
Veh Reg No : GV 6622 S  
Make / Mode : Nissan / NV200 1.5 MT  
Chassis No : VSKYBAM20Z0172998  
Engine No : K9KE628D623006  
Reg Date : 23/11/2018

## ESTIMATE REPAIR COST TO VEHICLE NO : GV 6622 S

| NO | DESCRIPTION                                      | U/PRICE     | QUANTITY | LIST PRICE  | AMOUNT      |
|----|--------------------------------------------------|-------------|----------|-------------|-------------|
| 1  | Rear tail lamp right hand / <i>Scr</i>           | \$ 232.10   | 1        | \$ 232.10   |             |
| 2  | Rear fender right hand <i>X repair</i>           | \$ 1,791.60 | 1        | \$ 1,791.60 |             |
| 3  | Rear bumper / <i>CRA</i>                         | \$ 593.20   | 1        | \$ 593.20   |             |
| 4  | Rear bumper side retainer right hand / <i>22</i> | \$ 60.20    | 1        | \$ 60.20    |             |
| 5  | Rear bumper reinforcement ?                      | \$ 346.20   | 1        | \$ 346.20   |             |
| 6  | Rear bumper inner sponge ?                       | \$ 146.40   | 1        | \$ 146.40   |             |
|    |                                                  |             |          | \$ 3,169.70 | \$ 3,169.70 |
|    | <b>Labour</b>                                    |             |          |             |             |
| 22 | Panel beating                                    | \$ 850.00   | 1        | \$ 850.00   | <i>400</i>  |
| 23 | Check wiring                                     | \$ 60.00    | 1        | \$ 60.00    | <i>30</i>   |
| 24 | Rust proofing                                    | \$ 60.00    | 1        | \$ 60.00    | <i>x</i>    |
| 25 | Spray painting                                   | \$ 520.00   | 1        | \$ 520.00   | <i>200</i>  |
| 27 | To remove & refit bumper sensor                  | \$ 80.00    | 1        | \$ 80.00    | <i>40</i>   |
|    |                                                  |             |          | \$ 1,570.00 | \$ 1,570.00 |
|    |                                                  |             |          |             | \$ 4,739.70 |

TOTAL : SINGAPORE DOLLARS FOUR THOUSAND SEVEN HUNDRED THIRTY NINE AND CENTS SEVENTY ONLY.

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE



Block 1 Kaki Bukit Ave 6  
#02-51 Singapore 417883  
Tel: 6745 6706 Fax: 6484 3653  
contact@revoperformance.com.sg  
www.revoperformance.com.sg  
ROC No 201200256H

*47 days.*  
*4/5 bumper repair*  
*After repair photos.*  
*Quo Qian - 82880282*  
*18/3/2020.*