

Nett Value : 121K -

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

GRACE AUTO LEASING
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

TP Budget Direct.
Drive.

18th MARCH 2020

ZNE100418850

Accident date: 15th MARCH 2020

Estimated repair cost for vehicle no: SJM6550C TOYOTA WISH 1.8 A '09

S/n	Qty	Items	U/price	Amount
1	1	bonnet		\$1,250.00 X
2	1	Front head lamp -LH		\$958.00 ✓
3	1-2	Front head lamp lower bracket-LH		\$151.20 X
4	1	Front bumper		\$1,377.00 565
5	2	Front bumper side bracket	\$194.34	\$388.68 X
6	8	Front bumper clips	\$12.90	\$103.20 X 30.
7	2	Front bumper SIDE clips	\$22.90	\$45.80 X
8	1	front Bumper inner sponge		\$297.57 X
9	1	Front bumper reinforcement		\$534.90 X
10	1	Front bumper number plate		\$50.00 X
11	1	Front bumper lower center garnish		\$385.10 X
12	1	Front Bumper Fog lamp -LH		\$287.20 X
13	1	Front bumper fog lamp cover		\$182.20 X
14	1	Front bumper fog lamp chome		\$191.40 X
15	1	front fender- LH		\$854.10 650
16	1	Front fender signal lamp- LH		\$121.75 72
17	1	front fender cowling-LH		\$185.20 ✓
18	1	Front I/H fender side glass		\$561.40 ✓
19	8	front L/H fender cowling clips	\$12.90	\$103.20 30.
20	1	Front fender inner panel-LH		\$581.20 X
21	1	Front L/H door		\$1,069.40 ✓
22	1	Front LH door side mirror		\$652.10 ✓
23	1	Front L/H door top hinges		\$80.70 ✓
24	1	Front L/H door lower hinges		\$80.70 ✓
25	1	Front L/H door inner trim board		\$1,387.15 X
26	1	Front L/H door inner lock		\$380.80 X
27	1	Front L/H door outer handle		\$232.55 X
28	1	Front L/H door inner rubber		\$261.40 X
29	1	Front L/H door glass gear		\$120.00 X
30	1	front LH door film		\$387.75 X
31	1	Front L/H door glass gear motor		\$ 550 ✓
32	1	LH side rocker panel		\$1,217.80 X
33	1	Front I/H drive shaft		\$220.00 X
34	1	Front IH stabilizer valve		\$2,200.00 1885
35	1	Front steering rack		\$458.00 ✓
36	1	front shock absorber-LH		\$425.30 ✓
37	1	front lower arm-LH		\$365.20 ✓
38	1	front knuckle arm-LH		\$182.50 ✓
39	1	front knuckle arm bearing-LH		\$500.00 ✓
40	1	Front sport Rim-LH		\$350.00 X
41	1	front tyre -LH		

9320 50

6990 37

Subtotal :-

\$19,873.25

Labour charges

To remove & re-fix fender side glass

~~\$120.00~~ 40

Gum

~~\$50.00~~ 30

To Remove & refix front undercarriage

~~\$400.00~~ 320

To check wheel alignment computer

~~\$150.00~~ 80

to remove & Refix front door -LH

~~\$200.00~~ 80

Fittings

2470

~~\$120.00~~ 60

Tuff kote

~~\$100.00~~ 60

Towing charges

~~\$1,200.00~~ 1900

Panel beating

~~\$1,200.00~~ 300

Spray painting

subtotal:- \$3,540.00

Total:- \$23,413.25

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 9460.37

L/S: 7.5K

08 Days