

22/03/2002

REF: CS/SMO 20004146 / UY f3<sup>22</sup>

Special Instruction:

ASS. REC. BY:

Surveyor: marcus

ASSIGNMENT (Office)

From (Person): Grace Tio of Smo Date/Time: 17.3.2020 4.40p.m

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBH 4987K Insured: SKF 97875at Workshop m/s Hup motor Tel: 9815 4655of Btk 900 k Tampine st 93 A01-120Policy No: \_\_\_\_\_ Claim No: CMTD 200147

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 16.3.2020

(Client's Record)

CA / REV / REP. / REV 24 HRS map H.O.D. Endorsement: \_\_\_\_\_Date/Time: 17.3.2020 4.56p.m Person Contacted: David Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>GBH 4987K - X</u>
	<u>SKF 97875 - CC4/ ASM 1906 5293/ AP03 DCA- 21/03/2019</u>
<u>19/3/20</u>	<u>Email preli revised to Pau Loong</u>

Surrounding: m

## ASSIGNMENT

From:

Date:

18.3.2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

GBH 4987K

at Workshop m/s

Hup Motor Trading

of BIK 9004 Tampinuse St 93 #101-120

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh: After 10.30a.m

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

52k.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

e

Consistent? : Yes or No

Est. Repairs:

12

days

Res.: Yes or No

Lum Sum:

1.3.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

np'

314k

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBH 4987K

Yr Regn:

6 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make:

Toyota hiace

c.c.

2982

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

35947

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFHT02 P 500243119

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: (M) / S/Rim / STD A/Rim or

Tyre Size:

F:

195-215

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

6

mm

L/Bal.

mm

D.O.A.

16/3/20

D.O.I.

18/3/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear 6 Rear 8

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 24631 8 yrs 2 m.

25/3/20 P/P \$17800-50 confirmed with David. (Red \$6291-64, 26%)

RECEIVED 26 MAR 2020

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

25/3/20 Typist

Report Format :

Lump Sum / I.B.I. (\$) :

P/P \$17800-50

Days Of Repair:

12

Resurvey No. of Trip:

3

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

450

Transportation:

) \$ + RS. \$

) Photo

) Others

TOTAL

**Veron Chen (LKKAUTO)**

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Thursday, 19 March 2020 9:38 AM  
**To:** Teo, Grace; Gnoh, Pau Loong  
**Cc:** Admin-D (LKKAUTO); assignments; SUR  
**Subject:** RE: CMTD2001177/GPL - LKK(LIA)/ SKF9787S & GBH4987K ACCIDENT ON : 16/03/2020 ALONG NO :18, KHEAM HOCK RD  
**Attachments:** GBH 4987K PRELI ADVISED.pdf

Dear Pau Loong,

Enclosed preliminary revised of vehicle GBH 4987K  
Date of survey: 18/3/2020  
Number of days (estimated) : 12 days

Best Regards,

**Veron Chen** | Case Handler **ON BEHALF OF YVONNE**

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** David Ang <hupmotor@gmail.com>  
**Sent:** Wednesday, 18 March 2020 3:47 PM  
**To:** Teo, Grace <grace.teo@sompo.com.sg>  
**Cc:** Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** Re: CMTD2001177/GPL - LKK(LIA)/ SKF9787S & GBH4987K ACCIDENT ON : 16/03/2020 ALONG NO :18, KHEAM HOCK RD

Dear Sirs,

Please revert & confirm client's third party claims liability for direct settlement, as your panel surveyor had surveyed client's damaged vehicle & we have carry out the repair, Please let us hear from yours,

On Tue, 17 Mar 2020 at 16:40, Teo, Grace <grace.teo@sompo.com.sg> wrote:

Without Prejudice

Our Reference: CMTD2001177/GPL

Your Reference: GBH4987K

Hi David,

We acknowledged receipt of your claim documents.

Please be informed that **Mr. Gnoh Pau Loong** is the handler of this case who can be contacted at 63295 217/  
[PauLoong.Gnoh@sompo.com.sg](mailto:PauLoong.Gnoh@sompo.com.sg).

Please be informed, we will appoint **LKK AUTO** to survey the above vehicle.

Aside to **LKK AUTO**,

Please make arrangement to conduct the survey for **GBH4987K** on a without Prejudice and any admission of liability basis.

Please submit with your report upon completion of survey to my colleague, **Mr. Pau Loong**.

Thank you.

-----

Aside to Pau Loong,

Please assist on the liability request from **Hup Motor Trading & Service**.

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555

For motor claims survey request, please email to [motorsurvey@sompo.com.sg](mailto:motorsurvey@sompo.com.sg)



**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG**

Download now @  or 

<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** David Ang <[hupmotor@gmail.com](mailto:hupmotor@gmail.com)>

**Sent:** Tuesday, March 17, 2020 2:15 PM

**To:** Claims - Motor Survey <[MotorSurvey@sompo.com.sg](mailto:MotorSurvey@sompo.com.sg)>

**Subject:** RE : ACCIDENT ON : 16/03/2020, INVOLVING CLIENT'S (GBH 4987 K, PARKED) & YOUR INSURED (SKF 9787 S) ALONG NO :18, KHEAM HOCK RD

Dear Sirs,

Attach our estimate bill, GIA third party insurer search fee, your insured insurance certificate, client's GIA report, insurance certificate & log card for your reference & attention,

Kindly assign your panel surveyor LKK Auto consultants, (One of our insurer panel also) to survey client's damaged vehicle, as client's vehicle was towed & parked in our garage, after the accident, Please revert & confirm the survey assignment,

Kindly revert & confirm client's third party claims liability, reference & OIC, as we are looking for direct settlement, Your insured driver had admitted her fault in the phone record, Please let us hear from yours soonest,

Best Regards

David Ang

Tel : 6784 0039, Fax : 6784 0076, HP : 9815 4655

Mailing Address :

Hup Motor Trading & Service

Blk 9004 Tampines St 93

#01-120

Singapore 528838



Virus-free. [www.avg.com](http://www.avg.com)

--  
Best Regards

David Ang

Tel : 6784 0039, Fax : 6784 0076, HP : 9815 4655

Mailing Address :

Hup Motor Trading & Service

Blk 9004 Tampines St 93

#01-120

Singapore 528838



Auto  
Consultants  
Pte Ltd

Company Registration No. 19960719

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 625643

Your ref: CMTD2001177

Our ref: CS/SMO20004146/UyF3

DATE: 19/3/2020

The Motor Claims Department  
M/s SOMPO INSURANCE SINGAPORE PTE LTD

Dear Sir/Madam

**PRELIMINARY ADVICE OF VEHICLE NO. GBH 4987K**


We thank for your instruction on 17/3/2020

Please be informed that we had conducted the inspection of the above mentioned vehicle on 18/3/2020 at the premises of M/s HUP MOTOR TRADING & SERVICE and have the following to report:-

Workshop Estimate Amount	:S\$22,442.07
Revised Estimate Amount	:S\$16,193.92
"Check" Items Amount	:S\$
Market Value	:S\$
LTA Reimbursement Value	:S\$
Nett Value	:S\$

**Description of Damage:**

The vehicle sustained damages at the front portion, rear portion and rooftop



Comments/Present Status:  
Damages Consistent

Yours faithfully,

MARCUS CHUA  
Licensed Appraiser

**Summer Lee (LKK Auto)**

---

**From:** Teo, Grace <grace.teo@sompo.com.sg>  
**Sent:** Tuesday, 17 March, 2020 4:40 PM  
**To:** David Ang; Gnoh, Pau Loong; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'; sur@lkkauto.com  
**Subject:** CMTD2001177/GPL - LKK(LIA)/ SKF9787S & GBH4987K ACCIDENT ON : 16/03/2020 ALONG NO :18, KHEAM HOCK RD  
**Attachments:** GBH 4987 K).pdf

Without Prejudice

Our Reference: CMTD2001177/GPL  
Your Reference: GBH4987K

Hi David,

We acknowledged receipt of your claim documents.

Please be informed that **Mr. Gnoh Pau Loong** is the handler of this case who can be contacted at 63295 217/ [PauLoong.Gnoh@sompo.com.sg](mailto:PauLoong.Gnoh@sompo.com.sg).

Please be informed, we will appoint **LKK AUTO** to survey the above vehicle.

Aside to **LKK AUTO**,

Please make arrangement to conduct the survey for **GBH4987K** on a without Prejudice and any admission of liability basis.

Please submit with your report upon completion of survey to my colleague, **Mr. Pau Loong**.

Thank you.

-----  
Aside to Pau Loong,

Please assist on the liability request from **Hup Motor Trading & Service**.

Best Regards  
**Grace Teo**  
Claims Division  
D: 6329 5170 | T: 6461 6555

For motor claims survey request, please email to [motorsurvey@sompo.com.sg](mailto:motorsurvey@sompo.com.sg)



**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG**



<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** David Ang <hupmotor@gmail.com>

**Sent:** Tuesday, March 17, 2020 2:15 PM

**To:** Claims - Motor Survey <MotorSurvey@sompo.com.sg>

**Subject:** RE : ACCIDENT ON : 16/03/2020, INVOLVING CLIENT'S (GBH 4987 K, PARKED) & YOUR INSURED (SKF 9787 S) ALONG NO :18, KHEAM HOCK RD

Dear Sirs,

Attach our estimate bill, GIA third party insurer search fee, your insured insurance certificate, client's GIA report, insurance certificate & log card for your reference & attention,

Kindly assign your panel surveyor LKK Auto consultants, (One of our insurer panel also) to survey client's damaged vehicle, as client's vehicle was towed & parked in our garage, after the accident, Please revert & confirm the survey assignment,

Kindly revert & confirm client's third party claims liability, reference & OIC, as we are looking for direct settlement, Your insured driver had admitted her fault in the phone record, PLease let us hear from yours soonest,

Best Regards

David Ang

Tel : 6784 0039, Fax : 6784 0076, HP : 9815 4655

Mailing Address :

Hup Motor Trading & Service

Blk 9004 Tampines St 93

#01-120

Singapore 528838



Virus-free. [www.avg.com](http://www.avg.com)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	16/03/2020 15:41
Date Of Accident	16/03/2020 14:30
Exact Location Of Accident	18 KHEAM HOCK ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH4987K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	HARMONY FURNISHING PTE LTD
Co Reg No	2XXXXXX314K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96926336
Alternative Phone No	OFFICE-62436137

### Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE VAN TURBO 5DR MT
Exact Purpose for which vehicle was being used at time of accident	COMPANY USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D19MCV0002607
Cover Note Number	

### Driver

Name of Driver	LEE WEN KE
Passport No/FIN	GXXXXX237W
Date Of Birth	12/12/1990
Occupation	INDOOR
Date Of Driving Pass	15/06/2017
Driving Experience	2 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97258970
Fax Number	
Contact Number	OFFICE-62436137
EMail Address	NOEMAIL

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time: 16/3/20 4.30pm


Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## CERTIFICATE OF INSURANCE

Rt Ex = 13/6/20

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

All Accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

<b>CERTIFICATE NO.: D19MCV0002607</b>		<b>COVER: Comprehensive</b>
1. Index Mark and Registration Number of Vehicle	: GBH4987K	
Chassis No	: JTFHT02P500243119	
2. Name of Policyholder	: HARMONY FURNISHING PTE LTD	
3. Effective date of Insurance	: 19 Jun 2019	
4. Expiry date of Insurance	: 18 Jun 2020	
5. Persons or Classes of Persons entitled to drive*	<p>Any person who is driving on the Policyholder's order or with their permission. Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.</p>	
6. Limitations as to use*	<p>a) Use in connection with the Policyholder's business. b) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business. c) Use for social, domestic and pleasure purposes.</p> <p><b>The Policy does not cover</b></p> <p>a) Use for hire or reward or for racing, pace-making, reliability trial, or speed-testing. b) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.</p>	
<p>*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.</p>		
<p>Excess Sect I : SGD600.00 Windscreen Excess : SGD100.00 Hire Purchase Company : Maybank</p>		
<p>FOR DRIVERS BELOW 21 YEARS OR ABOVE 65 YEARS OF AGE &amp;/OR LESS THAN 2 YEARS SINGAPORE DRIVING LICENCE, ADDITIONAL EXCESS OF \$2500/- ON SECTION I WILL BE APPLICABLE.</p>		
<p>I/We HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).</p>		
Agent/Broker : A000038/M Plus Consultancy	For India International Insurance Pte Ltd	
Date of Issue : 17/05/2019 15:22:27		
MZ300C (GOODS CARRYING) COMPANY	 Authorised Signatory	





INVOICE NO. SC 5835

DATE: 16/3/20

M/s

M/s _____		DATE: _____	
VEHICLE NO: <u>GB11 4987 K</u>		MAKE/MODEL: <u>TOYOTA SPIRITS</u>	
TIME OF CALL:	FROM	<u>18 Kanythong Rd</u> <u>011120</u>	
TIME START:	TO		
TIME END:			

INDICATE DAMAGED AREA(S) ON VEHICLE



1.DAMAGED    2.DENTED    3.SCRATCHES    4.MISSING

- ☐ KING DOLLY   ☐ ACCIDENT   ☐ WAITING TIME   ☐ JUMP START  
☐ CHANGE/AMEND TYRE   ☐ VEHICLE LOCKSMITH SERVICE  
☐ MSCP/BASEMENT   ☐ CRANE UP   ☐ LOW BODYKIT  
☐ COLLECTION OF KEY/DOCUMENT   ☐ WINCH OUT

REMARKS \_\_\_\_\_

AMOUNT:

Note : 本公司对所拖之车辆, 在进行中如有任何损失或破坏, 一概由车主自行负责。  
Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicles whilst being towed.

CLIENT'S SIGNATURE \_\_\_\_\_

## WORKSHOP

TRUCK NO/OPERATOR

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	314K
<b>Vehicle Details</b>	
Vehicle No.:	GBH4987K
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Mar 2020
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE VAN TURBO 5DR MT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	1KD2806655
Chassis No.:	JTFHT02P500243119
Maximum Power Output:	-
Open Market Value:	\$28,138.00
Original Registration Date:	14 Jun 2018
First Registration Date:	14 Jun 2018
Transfer Count:	1
Actual ARF Paid:	\$1,407.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	13 Jun 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$29,901.00
COE Rebate Amount:	\$24,631.00
<b>Total Rebate Amount:</b>	<b>\$24,631.00</b>

The information contained herein is correct as at 18 Mar 2020

OK

20% off now, promo code: CAR20

Get a quote

## Post an Advertisement

Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

## Mazda 3 Sedan 1.5A Deluxe Sunroof.

1 Owner. Clean And Neat  
Interior, Well Maintained!  
Excellent Condition!  
Direct Owner - StarAd.

Think One Automobile

**NEW & USED  
COMMERCIAL VEHICLES**

Browse by Category

Sort by Date Posted








20 results/page

13 vehicles

hiace

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	hiace		Any	Any	2018	Any	Any	Any	Available
	Toyota	Hiace 3.0M	\$58,800	\$6,840 /yr	23-Oct-2018	2,982 cc	-	Van	Available
<b>Fuel Type:</b> Diesel One Of The Rarest Gem Ever. Lightly And Under Utilised. Upholstery In Original Condition. Don't Want To Fork Out Too Much? No Pro, H... Car (S) Pte Ltd Posted: 18-Mar-2020 Tags: 2018 Toyota Hiace, Toyota Hiace, Toyota, Hiace									
	Toyota	Hiace 3.0A	\$60,000	\$7,540 /yr	01-Mar-2018	2,982 cc	55,555 km	Van	Available
<b>Fuel Type:</b> Diesel Almost New Vehicle, Very Low Mileage, Consignment Unit! Trade In Welcome! Loan And Insurance Available! Call Now For Viewing App... Prem Roy Motoring Posted: 18-Mar-2020 Tags: 2018 Toyota Hiace, Toyota Hiace, Toyota, Hiace									
	Toyota	Hiace 3.0M	\$56,800	\$6,850 /yr	03-Jul-2018	2,982 cc	-	Van	Available
<b>Fuel Type:</b> Diesel Well Maintained And Regularly Serviced. Seldom Drive. Posted: 17-Mar-2020 Tags: 2018 Toyota Hiace, Toyota Hiace, Toyota, Hiace									
	Toyota	Hiace Commuter 2.8A	\$73,777	\$8,550 /yr	01-Nov-2018	2,754 cc	-	Bus	Available
<b>Fuel Type:</b> Diesel Hiace Commuter With Front Sensing. Lots Of Safety Features! Come With Lots Of Accessories, Full Loan With Low-Interest Rate, High Tr... Posted: 17-Mar-2020 Tags: 2018 Toyota Hiace, Toyota Hiace, Toyota, Hiace									
	<b>Convenience &amp; Safety Night Time Driving</b> Toyota Auto Dim Mirror More info about this product								
	Toyota	Hiace 3.0M	\$56,800	\$6,750 /yr	15-Aug-2018	2,982 cc	17,000 km	Van	Available
<b>Fuel Type:</b> Diesel New Arrival! Cheapest In Town! (Low Depre At \$18 Per Day!) Super Low Mileage Done At 17000km Only! 1st Owner! (Borneo Motors U... Posted: 16-Mar-2020 Tags: 2018 Toyota Hiace, Toyota Hiace, Toyota, Hiace									
	Toyota	Hiace Commuter 3.0A	\$69,800	\$8,430 /yr	28-Jun-2018	2,982 cc	288 km	Bus	Available
<b>Fuel Type:</b> Diesel Almost Brand New, View To Believe 14 Seaters Mini Bus For Sales! 100% Loan And High Trade-In. Can Register Excursion, Private Hire,... Tai Huat Automobile Posted: 14-Mar-2020 Tags: 2018 Toyota Hiace, Toyota Hiace, Toyota, Hiace									
Compare	Toyota	Hiace Commuter 3.0A	\$58,800	\$7,320 /yr	28-Mar-2018	2,982 cc	-	Bus	Available

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2989/03/20 Your Ref: Date: 17th MARCH 2020

M/S HARMONY FURNISHING PTE. LTD. 7/28  
15, SENANG CRESCENT, S (416588)

### Estimate cost of repair to TOYOTA HIACE VAN - GBH 4987 K

1 pc tail gate door	2035-20	\$ 2,162.00	
1 pc tail gate door 'Toyota' sticker emblems	rel	39.10	
1 pc tail gate door 'Hiace' sticker	rel	39.10	
1 pc tail gate door '70km/h' sticker	rel	20.00	105.00
1 pc tail gate door 'TOYOTA' logo emblems	rel	66.80	
1 pc rear number plate	rel	60.00	205.00
1 pc rear licence lamp garnish	CNA	119.10	
6 pcs rear licence lamp garnish clips	11	28.80	
2 pcs rear o/s & n/s licence lamp assy	11	130.20	
1 pc reverse camera	11	1,269.10	
1 pc tail gate door inner trim board cover	dis/waged	265.70	
18 pcs trim board clips	rel	73.80	
1 pc rear windscreen glass	sketch	1,191.40	
1 pc rear windscreen glass damper rubber	rel	65.00	
1 pc rear windscreen glass sealant	rel	60.00	40.00
1 pc third brake light comp	CNA	195.60	
1 pc rear wiper arm	rel	57.60	
1 pc rear wiper motor	rel/10m	686.50	
1 pc rear wiper nozzle	CNA	28.50	
1 pc rear wiper blade	rel	51.50	
1 pc rear wiper arm cover	M/S	18.70	
1 pc tail gate door inner top garnish	rel	212.70	
10 pcs inner top garnish clips	11	41.00	
2 pcs tail gate door top o/s & n/s hinge	7m	119.20	
2 pcs tail gate door o/s & n/s shock absorber	262-KS	524.90	
1 pc tail gate door inner lock & actuator	10/10m	249.60	
1 pc tail gate door lock cover	M/S	65.90	
1 pc tail gate door weatherstrip	7m	368.90	
1 pc o/s door pillar panel inner garnish cover	M/S	68.80	
1 pc front bonnet	10	756.60	
1 pc front bonnet lock	34	77.50	
2 pcs front bonnet o/s & n/s hinge	17	97.60	
1 pc front bonnet logo emblems	rel	66.20	
2 pcs front bonnet o/s & n/s rubber	11	25.80	
12 pcs front bonnet rubber clips	11	46.80	
1 pc front top grille garnish	CNA	191.50	
1 pc front lower grille garnish	CNA	330.80	
16 pcs front top & lower grille clips	rel	65.60	
2 pcs o/s & n/s head lamp assy	15/16/15cm	1,697.40	120
1 pc front bumper	rel	496.30	
1 pc front bumper reinforcement	rel	340.40	
16 pcs front bumper clips	11	62.40	
1 pc front bumper centre air scoop grille	7m	154.30	
1 pc front bumper o/s fog lamp garnish	10m	48.10	
1 pc front bumper o/s tow bar cover	CNA	25.80	
1 pc front number plate	rel	60.00	205.00
1 pc front inner grille	CNA	491.10	
12 pcs front inner grille clips & stopper	11	66.00	

\$ 13,383.70

Balance C/F.....

1049830

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TF 2989/03/20 Your Ref: \_\_\_\_\_ Date: 17th MARCH 2020

M/S HARMONY FURNISHING PTE. LTD.,

Balance B/P..... \$ 13,383.70

2 pcs front bumper o/s & n/s side bracket	\$ 193.10	17	386.20	X
1 pc front support panel		OP/S	383.60	
1 pc air cond condenser		REF/PUR	1,216.10	
1 pc <del>cooler</del> cooler		PUR	1,358.10	
1 pc radiator		PUR	2,317.20	
1 pc radiator coolant			88.20	30 S.W
2 pcs high & low horn	\$ 105.10	17	210.20	X
1 pc air cond liquide pipe		17	464.60	X
1 pc cooler fluid		17	88.20	X
			\$ 19,896.10	
	Less 25%		\$ 4,974.03	
			\$ 14,922.07	

Towing charge (enclose Bill)	70.00	✓
To remove & refix rear windscreen glass & necessary parts.	150.00	120
To transfer tail gate door inner trim board, shock absorber, hinge, third brake light, wiper motor, garnish & necessary parts.	300.00	60
To wiring check up & adjust headlight alignment, including transfer rear wiring system for affected parts into new tail gate door.	150.00	30
To remove & refix roof linings, garnish, seal & necessary parts, to enable repair roof panel. including upholstery transfer.	280.00	100
To remove & refix air cond, including top up air cond gas.	150.00	100
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out roof panel, rear o/s door pillar panel, front support panel & necessary parts, to weld, renew & align above parts.	3,200.00	1800
To respray Tuff-Kote on all affected accident parts.	220.00	120
To putty & respray painting on all affected accident parts.	3,000.00	180
	\$ 22,442.07	
Dollars : Twenty Two Thousand Four Hundred Forty Two And Cents Seven Only.	=====	

HUP MOTOR TRADING & SERVICE

*[Signature]*

LK's Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged car(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No line of modification(s) is allowed
- Excess survey item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

22439.07

24089.154

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2989/03/20 Your Ref: Date: 19th March 2020

M/S HARMONY FURNISHING PTE LTD.  
15, Senang Crescent, S (416588)

### Supplementary Bill for TOYOTA HIACE VAN - GBH 4987 K

- 1 pc radiator fan cowling
- 1 pc radiator spare tank
- 1 pc front top bar beam
- 1 pc front top bar o/s stay bracket
- 1 pc front top bar o/s bracket
- 1 pc air cleaner box
- 1 pc air cond pipe

Cre \$ 286.30  
Cre 509.70  
Bal 426.90  
Bal 193.10  
Bal 45.50  
Cre 637.40  
Bal 101.20

Less 25%

\$ 2,200.40  
\$ 550.03  
\$ 1,650.07  
=====

Dollars : One Thousand Six Hundred Fifty And Cents Seven Only.

HUP MOTOR TRADING & SERVICE



1-17974  
252  
P-13480.50  
S.N-120.00  
L-4200.00  
17800.50




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref : CS/SMO20004146/Uyf3s2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623			Date : 27-03-2020	
Code : SMO				
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKF 9787S	Veh. Inspected	GBH 4987K	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2001177	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	17/03/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA HIACE (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JTFHT02P500243119	Colour	SILVER	
Odometer	35947	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	195 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	195 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	195 R15	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION AND ROOFTOP. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	16/03/2020	Inspection Date	18/03/2020	
Survey held at	HUP MOTOR TRADING & SERVICE BLK 9004 TAMPINES ST 93 #01-120 SINGAPORE 528838			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 4987K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	TAIL GATE DOOR	BADLY DENTED	2,162.00	2,035.20
1	TAIL GATE DOOR 'TOYOTA' STICKER EMBLEMS	NECESSARY	39.10	39.10
1	TAIL GATE DOOR 'HIACE' STICKER	NECESSARY	39.10	39.10
1	TAIL GATE DOOR 'TOYOTA' LOGO EMBLEMS	NECESSARY	66.80	66.80
1	REAR LICENCE LAMP GARNISH	CRACKED	119.10	119.10
6	REAR LICENCE LAMP GARNISH CLIPS @ \$4.80	NOT NECESSARY	28.80	-
2	REAR O/S & N/S LICENCE LAMP ASSY @ \$65.10	NOT NECESSARY	130.20	-
1	REVERSE CAMERA	NOT NECESSARY	1,269.10	-
1	TAIL GATE DOOR INNER TRIM BOARD COVER	DISTORTED / WARPED	265.70	265.70
18	TRIM BOARD CLIPS @ \$4.10	NECESSARY	73.80	73.80
1	REAR WINDSCREEN GLASS	SHATTERED	1,191.40	1,191.40
1	REAR WINDSCREEN GLASS DAMPER RUBBER	NECESSARY	65.00	65.00
1	THIRD BRAKE LIGHT COMP	CRACKED	195.60	195.60
1	REAR WIPER ARM	BENT	57.60	57.60
1	REAR WIPER MOTOR	BENT / JAMMED	686.50	686.50
1	REAR WIPER NOZZLE	CUT	28.50	28.50
1	REAR WIPER BLADE	BENT	51.50	51.50
1	REAR WIPER ARM COVER	MISSING	18.70	18.70
1	TAIL GATE DOOR INNER TOP GARNISH	DEFORMED	212.70	212.70
10	INNER TOP GARNISH CLIPS @ \$4.10	NOT NECESSARY	41.00	-
2	TAIL GATE DOOR TOP O/S & N/S HINGE @ \$59.60	TWISTED	119.20	119.20
2	TAIL GATE DOOR O/S & N/S SHOCK ABSORBER @ \$262.45	BENT / TWISTED	524.90	524.90
1	TAIL GATE DOOR INNER LOCK & ACUATOR	DENTED / JAMMED	249.60	249.60
1	TAIL GATE DOOR LOCK COVER	MISSING	65.90	65.90
1	TAIL GATE DOOR WEATHERSTRIP	TWISTED	368.90	368.90
1	O/S DOOR PILLAR PANEL INNER GARNISH COVER	MISSING	68.80	68.80
1	FRONT BONNET	DENTED	756.60	756.60
1	FRONT BONNET LOCK	BENT	77.50	77.50
2	FRONT BONNET O/S & N/S HINGE @ \$48.80	NOT NECESSARY	97.60	-

Report Ref No. CS/SMO20004146/Uyf3s2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BONNET LOGO EMBLEM	NECESSARY	66.20	66.20
2	FRONT BONNET O/S & N/S RUBBER @ \$12.90	NOT NECESSARY	25.80	-
12	FRONT BONNET RUBBER CLIPS @ \$3.90	NOT NECESSARY	46.80	-
1	FRONT TOP GRILLE GARNISH	CRACKED	191.50	191.50
1	FRONT LOWER GRILLE GARNISH	CRACKED	330.80	330.80
16	FRONT TOP & LOWER GRILLE CLIPS @ \$4.10	NECESSARY	65.60	65.60
2	O/S & N/S HEAD LAMP ASSY @ \$848.70	N/S NOT NECESSARY / O/S CRACKED	1,697.40	848.70
1	FRONT BUMPER	TORN	496.30	496.30
1	FRONT BUMPER REINFORCEMENT	BENT	340.40	340.40
16	FRONT BUMPER CLIPS @\$3.90	NECESSARY	62.40	62.40
1	FRONT BUMPER CENTRE AIRSCOOP GRILLE @ \$3.90	TORN	154.30	154.30
1	FRONT BUMPER O/S FOG LAMP GARNISH	TWISTED	48.10	48.10
1	FRONT BUMPER O/S TOW BAR COVER	CUT	25.80	25.80
1	FRONT INNER GRILLE	CRACKED	491.10	491.10
12	FRONT INNER GRILLE CLIPS & STOPPER @ \$5.50	NOT NECESSARY	66.00	-
2	FRONT BUMPER O/S & N/S SIDE BRACKET @ \$193.10	NOT NECESSARY	386.20	-
1	FRONT SUPPORT PANEL	DENTED / BENT	383.60	383.60
1	AIR COND CONDENSER	BENT / PUNCTURE	1,216.10	1,216.10
1	COOLER	PUNCTURE	1,358.10	1,358.10
1	RADIATOR	PUNCTURE	2,317.20	2,317.20
2	HIGH & LOW HORN @ \$105.10	NOT NECESSARY	210.20	-
1	AIR COND LIQUID PIPE	NOT NECESSARY	464.60	-
1	COOLER FLUID	NOT NECESSARY	88.20	-
1	RADIATOR FAN COWLING (ADDITIONAL)	CRACKED	286.30	286.30
1	RADIATOR SPARE TANK (ADDITIONAL)	CRACKED	509.70	509.70
1	FRONT TOP BAR BEAM (ADDITIONAL)	BENT	426.90	426.90
1	FRONT TOP BAR O/S STAY BRACKET (ADDITIONAL)	BENT	193.10	193.10
1	FRONT TOP BAR O/S BRACKET (ADDITIONAL)	BENT	45.50	45.50
1	AIR CLEANER BOX (ADDITIONAL)	CRACKED	637.40	637.40
1	AIR COND PIPE (ADDITIONAL)	BENT	101.20	101.20

Report Ref No. CS/SMO20004146/Uyf3s2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-5,451.00	-4,493.50
			16,353.00	13,480.50
1	TAIL GATE DOOR '70KM/H' STICKER (SN)	NECESSARY	20.00	10.00
1	REAR NUMBER PLATE (SN)	BENT	60.00	20.00
1	REAR WINDSCREEN GLASS SEALANT (SN)	NECESSARY	60.00	40.00
1	FRONT NUMBER PLATE (SN)	BENT	60.00	20.00
1	RADIATOR COOLANT (SN)	NECESSARY	88.20	30.00
	LESS 25% DISCOUNT		-72.05	-
			216.15	120.00
	<b>LABOUR</b>			
	TOWING CHARGE.		70.00	70.00
	TO REMOVE & REFIX REAR WINDSCREEN GLASS & NECESSARY PARTS.		150.00	120.00
	TO TRANSFER TAIL GATE DOOR INNER TRIM BOARD, SHOCK ABSORBER, HINGE, THIRD BRAKE LIGHT, WIPER MOTOR, GARNISH & NECESSARY PARTS.		300.00	60.00
	TO WIRING CHECK UP & ADJUST HEADLIGHT ALIGNMENT, INCLUDING TRANSFER REAR WIRING SYSTEM FOR AFFECTED PARTS INTO NEW TAIL GATE DOOR.		150.00	30.00
	TO REMOVE & REFIX ROOF LINING, GARNISH, SEAL & NECESSARY PARTS, TO ENABLE REPAIR ROOF PANEL, INCLUDING UPHOLSTERY TRANSFER.		280.00	100.00
	TO REMOVE & REFIX AIR COND, INCLUDING TOP UP AIR COND GAS.		150.00	100.00
	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS, TO JACK, STRAIGHTEN & KNOCKING OUT ROOF PANEL, REAR O/S DOOR PILLAR PANEL, FRONT SUPPORT PANEL & NECESSARY PARTS, TO WELD, RENEW & ALIGN ABOVE PARTS.		3,200.00	1,800.00
	TO RESPRAY TUFF-KOTE ON ALL AFFECTED PARTS.		220.00	120.00
	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS.		3,000.00	1,800.00
			7,520.00	4,200.00
	<b>GRAND TOTAL</b>		<b>24,089.15</b>	<b>17,800.50</b>

Report Ref No. CS/SMO20004146/Uyf3s2



RECOMMENDED COST OF REPAIRS			17,800.50
-----------------------------	--	--	-----------

Report Ref No. CS/SMO20004146/Uyf3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.