

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 33087

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0299/2020/NS
Date : 18-Mar-20

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : **SKM 2696 E**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Andrew Ang Sheng Pei
Address : Blk 301A Anchorvale Drive
#07-03
Singapore 541301
Telephone : (HP) +65 92379654
Type of Claim : Third Party Claims
Policy No. : 1800129506-01
Vehicle No : **SGY 7740 L**
Model Code : A4 Sedan 2.0 TFSI 8W
Model / Year : 31/10/2018
Engine No : CVK 067329
Chassis No : WAUZZZF4XJA219763
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 16-Mar-20
Place of Accident : Lorong Chuan Junction

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SGY 7740 L

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	✓
2	To dismantle and renew front bumper, bonnet and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,450.00 1000	✓
3	To respray front bumper and bonnet.	\$ 2,000.00 550	✓
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 5,122.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGY 7740 L

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>new</i>	\$ 2,068.00	x
2	FRONT BUMPER FIXING PARTS	\$ 269.00	+
3	FRONT BUMPER GRILLE - CENTRE	\$ 185.00	✓
4	FRONT BUMPER SECURING STRIP <i>new</i>	2 \$ 67.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$ 198.00	+
6	RADIATOR GRILLE <i>lot</i>	\$ 1,254.00	✓ 1,003.20
7	FRONT BUMPER AIR GUIDE GRILLE - LH / RH ?	2 \$ 254.00	x
8	FRONT BUMPER FOAM FILLER PIECE	\$ 117.00	+
9	FRONT BUMPER CARRIER	\$ 757.00	+
10	FRONT BUMPER COVER	\$ 120.00	+
11	CAUTION SIGN STICKER	NEC \$ 13.00	+
12	AIRCON STICKER	NEC \$ 7.00	+
13	LOCK CARRIER BRACKET	\$ 129.00	+
14	FRONT BUMPER SUPPORT - LH / RH	2 \$ 54.00	+
15	BONNET <i>Dented</i>	\$ 2,634.00	✓ 2,107.20
16	BONNET ATTACHMENT PARTS <i>new</i>	\$ 116.00	+
17	BONNET LID HINGE - LH / RH <i>new</i>	2 \$ 574.00	+
18	BONNET IMPACT PROTECTION - CENTRE ?	\$ 26.00	✓ 20.80
19	BONNET IMPACT PROTECTION - LH / RH <i>new</i>	2 \$ 52.00	✓ 41.12
20	BONNET STRIKER - LH / RH <i>new</i>	2 \$ 94.00	+
SUB TOTAL SPARE PARTS		: \$ 8,988.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGY 7740 L

		<u>Damaged Parts & Prices</u>		
<u>S/N</u>	<u>Parts Description</u>		<u>S/Nett</u>	<u>Remarks</u>
21	BONNET LID LOCK	2	\$ 403.00	+
22	BONNET BOWDEN CABLE - CENTRE		\$ 54.00	+
23	BONNET RELEASE CABLE		\$ 54.00	+
24	BONNET RELEASE LEVER		\$ 13.00	+
25	LED HEADLIGHT - LH / RH		\$ 7,321.00	+
26	RADIATOR AIR GUIDE - UPPER		\$ 15.00	+
27	RADIATOR AIR GUIDE - LH		\$ 27.00	+
28	RADIATOR AIR GUIDE - LH		\$ 12.00	+
29	FRONT NO PLATE <i>new</i>	S/N	\$ 60.00	# ✓
30	SUNDRIES ?		\$ 300.00	X nn
TOTAL SPARE PARTS		:	\$ 17,247.00	
TOTAL LABOUR CHARGES		:	\$ 5,122.00	
GRAND TOTAL		:	\$ 22,369.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 27/03/20
Authorised Date :
Excess Cost :
Liability :
Remarks : not authorised, 03 days.

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant