

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 33088

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/TP/0294/2020/NS  
Date : 10-Feb-20

Vehicle IN workshop. Kindly arrange for survey.

Your insured veh no : **SFR 8910 E**

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Teoh Kian Heng Jason  
Address : 31 Sembawang Crescent  
#08-20  
Singapore 756983  
Telephone : (HP) +65 96231117  
Type of Claim : Third Party Claims  
Policy No. : 1800063713-01  
Vehicle No : **SMA 4799 T**  
Model Code : Audi A3 Sedan 1.0 TFSI 8V  
Model / Year : 9/6/2018  
Engine No : CHZ 940477  
Chassis No : WAUZZZ8V7J1066524  
Mileage : 45910  
Date In : 17-Mar-20  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 17-Mar-20  
Place of Accident : Along CTE (Near Hong Wen School)

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle. SMA 4799 T

| S/n                      | Nature of Jobs                                                                                                                       | Estimated Charges | Surveyor's Recommendations |
|--------------------------|--------------------------------------------------------------------------------------------------------------------------------------|-------------------|----------------------------|
| 1                        | To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.       | S/N \$ 360.00 /   |                            |
| 2                        | To dismantle and renew front bumper, bonnet and lhs headlight. Re-organise crash management components. Reinstall all parts removed. | \$ 2,450.00 /     | 500                        |
| 3                        | To respray front bumper and bonnet.                                                                                                  | \$ 2,000.00 /     | 550                        |
| 4                        | To remove and transfer rear parking aid. Check function.                                                                             | S/N \$ 280.00 /   |                            |
| 5                        | To remove and transfer rear lid's convenience lock system and wire harness for tail lights.                                          | S/N \$ 280.00 /   |                            |
| SUB TOTAL LABOUR CHARGES |                                                                                                                                      | : \$ 5,370.00     |                            |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle. SMA 4799 T

| S/n                  | Nature of Jobs                                                                                                                                                                          | Estimated Charges | Surveyor's Recommendations |
|----------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|----------------------------|
| 6                    | To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment. S/N \$<br>Inspect for damages and renew where necessary. | 480.00            | X✓                         |
| 7                    | To dismantle and renew rear bumper and rear lid. To cut out and weld end panelling. Re-organise rear crash management components. Reinstall all parts removed.                          | \$ 4,200.00       | 2250<br><del>1500</del>    |
| 8                    | To respray rear bumper, rear lid, hinges, rear end panelling and spare wheel housing.                                                                                                   | \$ 4,000.00       | 1650                       |
| 9                    | To renew lhs rear exhaust silencer and align to position.                                                                                                                               | S/N \$ 480.00     | ✓                          |
| 10                   | To carry out diagnostic check.                                                                                                                                                          | S/N \$ 192.00     | ✓                          |
| TOTAL LABOUR CHARGES |                                                                                                                                                                                         | : \$ 14,722.00    |                            |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SMA 4799 T

| S/N                   | Parts Description                                           | Damaged Parts & Prices |         |
|-----------------------|-------------------------------------------------------------|------------------------|---------|
|                       |                                                             | S/Nett                 | Remarks |
| 1                     | FRONT BUMPER <i>repair</i>                                  | \$ 1,894.00            |         |
| 2                     | FRONT BUMPER FIXING PARTS <del>X</del> NN                   | \$ 176.00              |         |
| 3                     | FRONT BUMPER GUIDE SECTION - LH <del>X</del> NN             | \$ 36.00               |         |
| 4                     | FRONT BUMPER GRILLE - CENTRE <del>X</del> NN                | \$ 151.00              |         |
| 5                     | FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <del>X</del> NN | \$ 505.00              |         |
| 6                     | FRONT BUMPER CLOSING ELEMENT - LH <del>X</del> NN           | \$ 280.00              |         |
| 7                     | FRONT BUMPER COVER TRIM - LH <del>X</del> NN                | \$ 153.00              |         |
| 8                     | WHEEL HOUSING LINER ADAPTER - LH <del>X</del> NN            | \$ 36.00               |         |
| 9                     | RADIATOR GRILLE <i>cm</i>                                   | \$ 1,338.00            | 1070.40 |
| 10                    | RADIATOR GRILLE CLOSING ELEMENT <del>X</del> ✓ Nec          | \$ 180.00              | 143.60  |
| 11                    | FRONT BUMPER AIR GUIDE GRILLE - LH <del>X</del> NN          | \$ 177.00              |         |
| 12                    | FRONT BUMPER SIDE REINFORCEMENT BEAM <del>X</del> ✓ Nec     | \$ 681.00              | 544.80  |
| 13                    | FRONT BUMPER FOAM FILLER PIECE <del>X</del> ✓ Nec           | \$ 178.00              | 142.40  |
| 14                    | FOAM FILLER PIECE COVER <del>X</del> ✓ Nec                  | \$ 115.00              | 91.60   |
| 15                    | AIRCON STICKER <del>X</del> ✓ Nec                           | NEC \$ 7.00            | 5.36    |
| 16                    | CAUTION SIGN STICKER <del>X</del> ✓ Nec                     | NEC \$ 13.00           | 10.24   |
| 17                    | SIGNAL HORN - LH HIGH TONE <del>X</del> NN                  | \$ 188.00              |         |
| 18                    | BONNET <del>X</del> NN                                      | \$ 2,988.00            |         |
| 19                    | BONNET ATTACHMENT PARTS <del>X</del> NN                     | \$ 155.00              |         |
| 20                    | BONNET EDGE PROTECTION <del>X</del> NN                      | \$ 26.00               |         |
| SUB TOTAL SPARE PARTS |                                                             | : <u>\$ 9,277.00</u>   |         |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SMA 4799 T

| S/N                   | Parts Description                                       | Damaged Parts & Prices |         |
|-----------------------|---------------------------------------------------------|------------------------|---------|
|                       |                                                         | S/Nett                 | Remarks |
| 21                    | BONNET CATCH HOOK <del>X</del> NN                       | \$ 60.00               |         |
| 22                    | LED HEADLIGHT - LH / RH <del>X</del> NN                 | \$ 5,193.00            |         |
| 23                    | LIFT CYLINDER - LH <del>X</del> NN                      | \$ 134.00              |         |
| 24                    | RADIATOR AIR GUIDE - LH <del>X</del> ✓ Nec              | \$ 23.00 18.46         |         |
| 25                    | RADIATOR AIR GUIDE - UPPER CENTRE <del>X</del> NN       | \$ 12.00               |         |
| 26                    | REAR BUMPER <i>de</i>                                   | \$ 1,851.00 1480.80    |         |
| 27                    | REAR BUMPER STICKY PAD <i>re</i> <del>X</del> NN        | 4 \$ 22.00             |         |
| 28                    | REAR BUMPER FIXING PARTS <i>re</i> <del>X</del> NN      | \$ 182.00              |         |
| 29                    | WHEEL HOUSING LINER ADAPTER - LH / RH <del>X</del> NN 2 | \$ 72.00               |         |
| 30                    | REAR BUMPER GUIDE SECTION - LH / RH <del>X</del> NN 2   | \$ 30.00               |         |
| 31                    | REAR BUMPER LOCKING MECHANISM <del>X</del> NN 2         | \$ 55.00               |         |
| 32                    | REAR BUMPER SPOILER <i>set</i>                          | \$ 223.00 178.40       |         |
| 33                    | REAR LIGHT REFLECTOR - LH / RH <del>X</del> NN 2        | \$ 78.00               |         |
| 34                    | REAR BUMPER SIDE REINFORCEMENT BEAM <del>X</del> NN     | \$ 538.00              |         |
| 35                    | REAR BUMPER BRACKET - LH <del>X</del> NN                | \$ 26.00               |         |
| 36                    | REAR BUMPER BRACKET - RH <del>X</del> NN                | \$ 27.00               |         |
| 37                    | REAR BUMPER GUIDE SECTION - LH / RH <del>X</del> NN 2   | \$ 124.00              |         |
| 38                    | REAR PARKING AID SENSOR - INNER / OUTER 2 <i>re</i>     | TBC 392.80             |         |
| 39                    | REAR PARKING AID SEAL RING <i>re</i> <del>X</del> NN 4  | \$ 14.00               |         |
| 40                    | REAR LID <i>lt</i>                                      | \$ 2,444.00 1955.20    |         |
| SUB TOTAL SPARE PARTS |                                                         | : <u>\$ 11,108.00</u>  |         |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SMA 4799 T

| S/N | Parts Description                                                                       | Damaged Parts & Prices |               |
|-----|-----------------------------------------------------------------------------------------|------------------------|---------------|
|     |                                                                                         | S/Nett                 | Remarks       |
| 41  | REAR LID ATTACHMENT PARTS <del>X</del> NN                                               | \$                     | 278.00        |
| 42  | REAR LID HINGE - LH / RH <del>X</del> NN                                                | 2 \$                   | 482.00        |
| 43  | REAR LID FLAP GASKET <del>X</del> NN                                                    | \$                     | 193.00        |
| 44  | REAR LID LOCK STRIKER <del>X</del> NN                                                   | \$                     | 47.00         |
| 45  | REAR LID LOCK STRIKER <del>X</del> NN                                                   | \$                     | 182.00        |
| 46  | PACKING ADHESIVE <del>ne</del>                                                          | \$                     | 18.00 14.24   |
| 47  | AUDI EMBLEM <del>ne</del>                                                               | \$                     | 117.00 93.20  |
| 48  | A3 INSCRIPTION <del>ne</del>                                                            | \$                     | 90.00 71.76   |
| 49  | TFSI INSCRIPTION <del>ne</del>                                                          | \$                     | 90.00 71.76   |
| 50  | REAR CROSS PANEL <del>repair</del> <del>X</del> <input checked="" type="checkbox"/> Nec | \$                     | 339.00 270.80 |
| 51  | CROSS PANEL REINFORCEMENT <del>repair</del>                                             | \$                     | 691.00        |
| 52  | REAR CROSS PANEL CONNECTING PLATE - LH <del>X</del> NN                                  | \$                     | 136.00        |
| 53  | REAR CROSS PANEL TRIM <del>X</del> NN                                                   | \$                     | 146.00        |
| 54  | REAR SILENCER <del>bt</del>                                                             | \$                     | 677.00 541.60 |
| 55  | REAR SILENCER DUAL CLIP <del>ne</del>                                                   | \$                     | 55.00 43.60   |
| 56  | EXHAUST SYSTEM RETAINER <del>ne</del> <del>X</del> NN                                   | 2 \$                   | 77.00         |
| 57  | REAR SILENCER HEAT SHIELD <del>X</del> NN                                               | \$                     | 157.00        |
| 58  | FRONT NO PLATE <del>bt</del>                                                            | S/N \$                 | 60.00         |
| 59  | REAR NO PLATE <del>X</del> NN                                                           | S/N \$                 | 60.00         |
| 60  | ACRYLIC SEALANT <del>repair</del> <del>X</del> <input checked="" type="checkbox"/> Nec  | S/N \$                 | 180.00        |
| 61  | CAVITY WAX <del>X</del> <input checked="" type="checkbox"/> Nec                         | S/N \$                 | 140.00        |
| 62  | STONE CHIP <del>X</del> <input checked="" type="checkbox"/> Nec                         | S/N \$                 | 180.00        |
| 63  | SUNDRIES <del>X</del> <input checked="" type="checkbox"/> Nec                           | \$                     | 500.00 58.58  |

|                      |   |                     |
|----------------------|---|---------------------|
| TOTAL SPARE PARTS    | : | \$ 25,280.00        |
| TOTAL LABOUR CHARGES | : | \$ 14,722.00        |
| GRAND TOTAL          | : | <u>\$ 40,002.00</u> |

All charges are not inclusive of GST.  
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : RASUL - Hp 90010068  
Surveyed Date : 18/03/2020 @ 1700  
Authorised Date :  
Excess Cost : 10 days  
Liability :  
Remarks : Reey before paint

## Please Note

- : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: [Nora.khai@premiumauto.com.sg](mailto:Nora.khai@premiumauto.com.sg) / [claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg)

**WIP : 33088**

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/0294/2020/NS  
**Date** : 10-Feb-20

**Vehicle IN workshop. Kindly arrange for survey.**

**Your insured veh no : SFR 8910 E**

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Hi Rasul**

**10 days exclude 2 Sundays - ok  
jb - 24 April 20**

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr Teoh Kian Heng Jason  
**Address** : 31 Sembawang Crescent  
#08-20  
Singapore 756983  
**Telephone** : (HP) +65 96231117  
**Type of Claim** : Third Party Claims  
**Policy No.** : 1800063713-01  
**Vehicle No** : **SMA 4799 T**  
**Model Code** : Audi A3 Sedan 1.0 TFSI 8V  
**Model / Year** : 9/6/2018  
**Engine No** : CHZ 940477  
**Chassis No** : WAUZZZ8V7J1066524  
**Mileage** : 45910  
**Date In** : 17-Mar-20  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 17-Mar-20  
**Place of Accident** : Along CTE (Near Hong Wen School)

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle. SMA 4799 T

| S/n                             | Nature of Jobs                                                                                                                          |        | Estimated<br>Charges | <i>Surveyor's<br/>Recommendations</i> |
|---------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------|--------|----------------------|---------------------------------------|
| 1                               | To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.          | S/N \$ | 360.00               | \$ 360.00                             |
| 2                               | To dismantle and renew front bumper, bonnet and lhs headlight.<br>Re-organise crash management components. Reinstall all parts removed. | \$     | 2,450.00             | \$ 500.00                             |
| 3                               | To respray front bumper and bonnet.                                                                                                     | \$     | 2,000.00             | \$ 550.00                             |
| 4                               | To remove and transfer rear parking aid. Check function.                                                                                | S/N \$ | 280.00               | \$ 280.00                             |
| 5                               | To remove and transfer rear lid's convenience lock system and wire harness for tail lights.                                             | S/N \$ | 280.00               | \$ 280.00                             |
| <b>SUB TOTAL LABOUR CHARGES</b> |                                                                                                                                         | :      | <b>\$ 5,370.00</b>   | <b>\$ 1,970.00</b>                    |

**Premium Automobiles**

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

**Telefax****Estimated Labour Charges for Accident Vehicle. SMA 4799 T**

| S/n                         | Nature of Jobs                                                                                                                                                                                                                               | Estimated Charges     | Surveyor's Recommendations |
|-----------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------|----------------------------|
|                             |                                                                                                                                                                                                                                              | <i>c/f</i>            | <i>\$ 1,970.00</i>         |
| 6                           | To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment. Inspect for damages and renew where necessary. <i>(Nec - rr panel changed)</i>                                | S/N \$ 480.00         | <i>\$ 480.00</i>           |
| 7                           | To dismantle and renew rear bumper and rear lid. To cut out and weld end panelling. Re-organise rear crash management components. Reinstall all parts removed. <i>(Added 1.5 days for rear panel and repair inner panel, s/tyre housing)</i> | \$ 4,200.00           | <i>\$ 2,250.00</i>         |
| 8                           | To respray rear bumper, rear lid, hinges, rear end panelling and spare wheel housing.                                                                                                                                                        | \$ 4,000.00           | <i>\$ 1,650.00</i>         |
| 9                           | To renew lhs rear exhaust silencer and align to position.                                                                                                                                                                                    | S/N \$ 480.00         | <i>\$ 480.00</i>           |
| 10                          | To carry out diagnostic check.                                                                                                                                                                                                               | S/N \$ 192.00         | <i>\$ 192.00</i>           |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                                                                              | <b>: \$ 14,722.00</b> | <b><i>\$ 7,022.00</i></b>  |



# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SMA 4799 T

| S/N                          | Parts Description                           | <u>Damaged Parts &amp; Prices</u> |                    |
|------------------------------|---------------------------------------------|-----------------------------------|--------------------|
|                              |                                             | S/Nett                            | Remarks            |
| 1                            | FRONT BUMPER                                | \$ 1,894.00                       |                    |
| 2                            | FRONT BUMPER FIXING PARTS                   | \$ 176.00                         |                    |
| 3                            | FRONT BUMPER GUIDE SECTION - LH             | \$ 36.00                          |                    |
| 4                            | FRONT BUMPER GRILLE - CENTRE                | \$ 151.00                         |                    |
| 5                            | FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE | \$ 505.00                         |                    |
| 6                            | FRONT BUMPER CLOSING ELEMENT - LH           | \$ 280.00                         |                    |
| 7                            | FRONT BUMPER COVER TRIM - LH                | \$ 153.00                         |                    |
| 8                            | WHEEL HOUSING LINER ADAPTER - LH            | \$ 36.00                          |                    |
| 9                            | RADIATOR GRILLE                             | \$ 1,338.00                       | \$ 1,070.40        |
| 10                           | RADIATOR GRILLE CLOSING ELEMENT             | \$ 180.00                         | \$ 143.60          |
| 11                           | FRONT BUMPER AIR GUIDE GRILLE - LH          | \$ 177.00                         |                    |
| 12                           | FRONT BUMPER SIDE REINFORCEMENT BEAM        | \$ 681.00                         | \$ 544.80          |
| 13                           | FRONT BUMPER FOAM FILLER PIECE              | \$ 178.00                         | \$ 142.40          |
| 14                           | FOAM FILLER PIECE COVER                     | \$ 115.00                         | \$ 91.60           |
| 15                           | AIRCON STICKER                              | NEC \$ 7.00                       | \$ 5.36            |
| 16                           | CAUTION SIGN STICKER                        | NEC \$ 13.00                      | \$ 10.24           |
| 17                           | SIGNAL HORN - LH HIGH TONE                  | \$ 188.00                         |                    |
| 18                           | BONNET                                      | \$ 2,988.00                       |                    |
| 19                           | BONNET ATTACHMENT PARTS                     | \$ 155.00                         |                    |
| 20                           | BONNET EDGE PROTECTION                      | \$ 26.00                          |                    |
| <b>SUB TOTAL SPARE PARTS</b> |                                             | <b>: \$ 9,277.00</b>              | <b>\$ 2,008.40</b> |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SMA 4799 T

| S/N                          | Parts Description                       | c/f | <u>Damaged Parts &amp; Prices</u> |                    |
|------------------------------|-----------------------------------------|-----|-----------------------------------|--------------------|
|                              |                                         |     | S/Nett                            | Remarks            |
|                              |                                         |     |                                   | <b>\$ 2,008.40</b> |
| 21                           | BONNET CATCH HOOK                       |     | \$ 60.00                          |                    |
| 22                           | LED HEADLIGHT - LH / RH                 |     | \$ 5,193.00                       |                    |
| 23                           | LIFT CYLINDER - LH                      |     | \$ 134.00                         |                    |
| 24                           | RADIATOR AIR GUIDE - LH                 |     | \$ 23.00                          | <b>\$ 18.46</b>    |
| 25                           | RADIATOR AIR GUIDE - UPPER CENTRE       |     | \$ 12.00                          |                    |
| 26                           | REAR BUMPER                             |     | \$ 1,851.00                       | <b>\$ 1,480.80</b> |
| 27                           | REAR BUMPER STICKY PAD                  | 4   | \$ 22.00                          |                    |
| 28                           | REAR BUMPER FIXING PARTS                |     | \$ 182.00                         |                    |
| 29                           | WHEEL HOUSING LINER ADAPTER - LH / RH   | 2   | \$ 72.00                          |                    |
| 30                           | REAR BUMPER GUIDE SECTION - LH / RH     | 2   | \$ 30.00                          |                    |
| 31                           | REAR BUMPER LOCKING MECHANISM           | 2   | \$ 55.00                          |                    |
| 32                           | REAR BUMPER SPOILER                     |     | \$ 223.00                         | <b>\$ 178.40</b>   |
| 33                           | REAR LIGHT REFLECTOR - LH / RH          | 2   | \$ 78.00                          |                    |
| 34                           | REAR BUMPER SIDE REINFORCEMENT BEAM     |     | \$ 538.00                         |                    |
| 35                           | REAR BUMPER BRACKET - LH                |     | \$ 26.00                          |                    |
| 36                           | REAR BUMPER BRACKET - RH                |     | \$ 27.00                          |                    |
| 37                           | REAR BUMPER GUIDE SECTION - LH / RH     | 2   | \$ 124.00                         |                    |
| 38                           | REAR PARKING AID SENSOR - INNER / OUTER | 2   | \$ 492.00                         | <b>\$ 392.80</b>   |
| 39                           | REAR PARKING AID SEAL RING              | 4   | \$ 14.00                          |                    |
| 40                           | REAR LID                                |     | \$ 2,444.00                       | <b>\$ 1,955.20</b> |
| <b>SUB TOTAL SPARE PARTS</b> |                                         | :   | <b>\$ 11,600.00</b>               | <b>\$ 6,034.06</b> |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SMA 4799 T

| S/N                         | Parts Description                      |     | Damaged Parts & Prices |                     | Remarks     |
|-----------------------------|----------------------------------------|-----|------------------------|---------------------|-------------|
|                             |                                        |     | S/Nett                 |                     |             |
|                             |                                        | c/f |                        |                     | \$ 6,034.06 |
| 41                          | REAR LID ATTACHMENT PARTS              |     | \$ 278.00              |                     |             |
| 42                          | REAR LID HINGE - LH / RH               | 2   | \$ 482.00              |                     |             |
| 43                          | REAR LID FLAP GASKET                   |     | \$ 193.00              |                     |             |
| 44                          | REAR LID LOCK STRIKER                  |     | \$ 47.00               |                     |             |
| 45                          | REAR LID LOCK STRIKER                  |     | \$ 182.00              |                     |             |
| 46                          | PACKING ADHESIVE                       |     | \$ 18.00               | \$ 14.24            |             |
| 47                          | AUDI EMBLEM                            |     | \$ 117.00              | \$ 93.20            |             |
| 48                          | A3 INSCRIPTION                         |     | \$ 90.00               | \$ 71.76            |             |
| 49                          | TFSI INSCRIPTION                       |     | \$ 90.00               | \$ 71.76            |             |
| 50                          | REAR CROSS PANEL                       |     | \$ 339.00              | \$ 270.80           |             |
| 51                          | CROSS PANEL REINFORCEMENT              |     | \$ 691.00              |                     |             |
| 52                          | REAR CROSS PANEL CONNECTING PLATE - LH |     | \$ 136.00              |                     |             |
| 53                          | REAR CROSS PANEL TRIM                  |     | \$ 146.00              |                     |             |
| 54                          | REAR SILENCER                          |     | \$ 677.00              | \$ 541.60           |             |
| 55                          | REAR SILENCER DUAL CLIP                |     | \$ 55.00               | \$ 43.60            |             |
| 56                          | EXHAUST SYSTEM RETAINER                | 2   | \$ 77.00               |                     |             |
| 57                          | REAR SILENCER HEAT SHIELD              |     | \$ 157.00              |                     |             |
| 58                          | FRONT NO PLATE                         | S/N | \$ 60.00               | \$ 60.00            |             |
| 59                          | REAR NO PLATE                          | S/N | \$ 60.00               |                     |             |
| 60                          | ACRYLIC SEALANT                        | S/N | \$ 180.00              | \$ 180.00           |             |
| 61                          | CAVITY WAX                             | S/N | \$ 140.00              | \$ 140.00           |             |
| 62                          | STONE CHIP                             | S/N | \$ 180.00              | \$ 180.00           |             |
| 62a                         | Added parts - see aattached            |     | \$ 470.00              | \$ 375.60           |             |
| 63                          | SUNDRIES                               |     | \$ 500.00              | \$ 58.58            |             |
| <b>TOTAL SPARE PARTS</b>    |                                        | :   | <b>\$ 26,242.00</b>    | <b>\$ 8,135.20</b>  |             |
| <b>TOTAL LABOUR CHARGES</b> |                                        | :   | <b>\$ 14,722.00</b>    | <b>\$ 7,022.00</b>  |             |
| <b>GRAND TOTAL</b>          |                                        | :   | <b>\$ 40,964.00</b>    | <b>\$ 15,157.20</b> |             |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

## Supplementary Estimate 1

GST Reg No. 19-9902271-W

| <b>AIG Asia Pacific Insurance Pte Ltd</b><br>78 Shenton Way<br>#07-16 AIG Building<br>Singapore 079120<br><b>Attn: Mr. Adrian Ling - Motor Claims Dept</b><br><b>Tel: 6841 0055 - Fax: 6256 4315</b> |                               | <b>Estimate No.</b><br><b>Date</b><br><b>Service Advisor</b><br><b>Pages</b><br><b>Regn No</b><br><b>Model No</b> | PA/TP/0294/2020/NS<br>22-Apr-20<br>Glory Tan<br>1 of 1<br>SMA 4799 T<br>Audi A3 Sedan 1.0 TFSI 8V |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------|-------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------|
| Quantity                                                                                                                                                                                             | Description                   | Unit Price                                                                                                        | Amount                                                                                            |
| <u>Parts</u><br>1                                                                                                                                                                                    | Centre exhaust silencer ✓ Nec | \$ 470.00                                                                                                         | \$ 375.60                                                                                         |
| <b>TOTAL</b>                                                                                                                                                                                         |                               | <b>\$ 470.00</b>                                                                                                  | <b>\$ 375.60</b>                                                                                  |

For Premium Automobiles Pte Ltd

\_\_\_\_\_  
Authorised Signature

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

**Name** :  
**Surveyed Date** :  
**Authorised Date** :  
**Excess Cost** :  
**Liability** :  
**Remarks** :

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant