

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 33088

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0294/2020/NS
Date : 10-Feb-20

Vehicle IN workshop. Kindly arrange for survey.

Your insured veh no : **SFR 8910 E**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Teoh Kian Heng Jason
Address : 31 Sembawang Crescent
#08-20
Singapore 756983
Telephone : (HP) +65 96231117
Type of Claim : Third Party Claims
Policy No. : 1800063713-01
Vehicle No : **SMA 4799 T**
Model Code : Audi A3 Sedan 1.0 TFSI 8V\
Model / Year : 9/6/2018
Engine No : CHZ 940477
Chassis No : WAUZZZ8V7J1066524
Mileage : 45910
Date In : 17-Mar-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 17-Mar-20
Place of Accident : Along CTE (Near Hong Wen School)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMA 4799 T

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	/
2	To dismantle and renew front bumper, bonnet and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,450.00	500
3	To respray front bumper and bonnet.	\$ 2,000.00	550
4	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00	/
5	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$ 280.00	/
SUB TOTAL LABOUR CHARGES		: \$ 5,370.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMA 4799 T

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
6	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment. S/N \$ Inspect for damages and renew where necessary.	480.00	X
7	To dismantle and renew rear bumper and rear lid. To cut out and weld end panelling. Re-organise rear crash management components. Reinstall all parts removed.	\$ 4,200.00	1500
8	To respray rear bumper, rear lid, hinges, rear end panelling and spare wheel housing.	\$ 4,000.00	1650
9	To renew lhs rear exhaust silencer and align to position.	S/N \$ 480.00	
10	To carry out diagnostic check.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 14,722.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 4799 T

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>repair</i>	\$ 1,894.00	
2	FRONT BUMPER FIXING PARTS X	\$ 176.00	
3	FRONT BUMPER GUIDE SECTION - LH X	\$ 36.00	
4	FRONT BUMPER GRILLE - CENTRE X	\$ 151.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE X	\$ 505.00	
6	FRONT BUMPER CLOSING ELEMENT - LH X	\$ 280.00	
7	FRONT BUMPER COVER TRIM - LH X	\$ 153.00	
8	WHEEL HOUSING LINER ADAPTER - LH X	\$ 36.00	
9	RADIATOR GRILLE <i>cm</i>	\$ 1,338.00	
10	RADIATOR GRILLE CLOSING ELEMENT X	\$ 180.00	
11	FRONT BUMPER AIR GUIDE GRILLE - LH X	\$ 177.00	
12	FRONT BUMPER SIDE REINFORCEMENT BEAM X	\$ 681.00	
13	FRONT BUMPER FOAM FILLER PIECE X	\$ 178.00	
14	FOAM FILLER PIECE COVER X	\$ 115.00	
15	AIRCON STICKER X	NEC \$ 7.00	
16	CAUTION SIGN STICKER X	NEC \$ 13.00	
17	SIGNAL HORN - LH HIGH TONE X	\$ 188.00	
18	BONNET X	\$ 2,988.00	
19	BONNET ATTACHMENT PARTS X	\$ 155.00	
20	BONNET EDGE PROTECTION X	\$ 26.00	
SUB TOTAL SPARE PARTS		: \$ 9,277.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 4799 T

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/	Nett	
21	BONNET CATCH HOOK X	\$	60.00	
22	LED HEADLIGHT - LH / RH X	\$	5,193.00	
23	LIFT CYLINDER - LH X	\$	134.00	
24	RADIATOR AIR GUIDE - LH X	\$	23.00	
25	RADIATOR AIR GUIDE - UPPER CENTRE X	\$	12.00	
26	REAR BUMPER de /	\$	1,851.00	
27	REAR BUMPER STICKY PAD ne /	4 \$	22.00	
28	REAR BUMPER FIXING PARTS ne /	\$	182.00	
29	WHEEL HOUSING LINER ADAPTER - LH / RH ?	2 \$	72.00	
30	REAR BUMPER GUIDE SECTION - LH / RH ?	2 \$	30.00	
31	REAR BUMPER LOCKING MECHANISM ?	2 \$	55.00	
32	REAR BUMPER SPOILER set /	\$	223.00	
33	REAR LIGHT REFLECTOR - LH / RH X	2 \$	78.00	
34	REAR BUMPER SIDE REINFORCEMENT BEAM ?	\$	538.00	
35	REAR BUMPER BRACKET - LH ?	\$	26.00	
36	REAR BUMPER BRACKET - RH ?	\$	27.00	
37	REAR BUMPER GUIDE SECTION - LH / RH ?	2 \$	124.00	
38	REAR PARKING AID SENSOR - INNER / OUTER	2 ne /	TBC	
39	REAR PARKING AID SEAL RING ne /	4 \$	14.00	
40	REAR LID bt /	\$	2,444.00	
SUB TOTAL SPARE PARTS		: <u>\$ 11,108.00</u>		

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 4799 T

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
41	REAR LID ATTACHMENT PARTS X	\$	278.00
42	REAR LID HINGE - LH / RH X	2 \$	482.00
43	REAR LID FLAP GASKET X	\$	193.00
44	REAR LID LOCK STRIKER X	\$	47.00
45	REAR LID LOCK STRIKER X	\$	182.00
46	PACKING ADHESIVE ne-	\$	18.00
47	AUDI EMBLEM ne-	\$	117.00
48	A3 INSCRIPTION ne-	\$	90.00
49	TFSI INSCRIPTION ne-	\$	90.00
50	REAR CROSS PANEL repair	\$	339.00
51	CROSS PANEL REINFORCEMENT repair	\$	691.00
52	REAR CROSS PANEL CONNECTING PLATE - LH ?	\$	136.00
53	REAR CROSS PANEL TRIM ?	\$	146.00
54	REAR SILENCER bt-	\$	677.00
55	REAR SILENCER DUAL CLIP ne-	\$	55.00
56	EXHAUST SYSTEM RETAINER ne-	2 \$	77.00
57	REAR SILENCER HEAT SHIELD X	\$	157.00
58	FRONT NO PLATE bt-	S/N \$	60.00
59	REAR NO PLATE X	S/N \$	60.00
60	ACRYLIC SEALANT repair ?	S/N \$	180.00
61	CAVITY WAX ?	S/N \$	140.00
62	STONE CHIP ?	S/N \$	180.00
63	SUNDRIES ?	\$	500.00
TOTAL SPARE PARTS		:	\$ 25,280.00
TOTAL LABOUR CHARGES		:	\$ 14,722.00
GRAND TOTAL		:	\$ 40,002.00

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : RASUL - Hp 90010068
Surveyed Date : 18/03/2020 @ 1700
Authorised Date :
Excess Cost : 10 days
Liability :
Remarks : Reey before paint

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant