

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVE 4 GATE 2
#03-21
SINGAPORE 415875

LINDA LIAO
STK AUTO (S) PTE LTD

Date: 16/03/2020
To: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
Attn: Motor Claim Department
Owner: LU BIN

AXA INSURANCE PTE LTD

Certificate Number: GA485419

Accident Date: 26/02/2020

Vehicle Number: SFW5325M

Make & Model: SUBARU FORESTER 2.0i

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
1	FRONT BUMPER <i>del</i>	\$ 640.50	✓
1	FRONT BUMPER RETAINER RH <i>free</i>	\$ 25.00	✓
1	FRONT BUMPER RETAINER LH	\$ 25.00	✓
1	FRONT BUMPER FOG LAMP RH <i>free</i>	\$ 300.00	✓
1	FRONT BUMPER FOG LAMP LH	\$ 300.00	✓
1	FRONT BUMPER REINFORCEMENT OUTER <i>beat</i>	\$ 215.00	✓
1	FRONT BUMPER REINFORCEMENT INNER <i>new</i>	\$ 350.00	✓
1	AIR CON CONDENSER <i>new</i>	\$ 1,850.00	✓
1	FRONT BUMPER LOWER SLIP <i>new</i>	\$ 1,560.00	✓
1	REAR BUMPER <i>del</i>	\$ 700.00	✓
1	REAR BUMPER TOP PLATE ALUMINIUM <i>beat</i>	\$ 350.00	✓
1	REAR BUMPER TOWING COVER <i>missy</i>	\$ 150.00	✓
1	REAR BUMPER LOWRE CHROME MOULDING <i>could</i>	\$ 450.00	✓
1	REAR BUMPER REINFORCEMENT <i>beat</i>	\$ 650.00	✓
1	REAR BUMPER REFLECTOR RH <i>free</i>	\$ 35.00	✓
1	REAR BUMPER REFLECTOR LH	\$ 35.00	✓
1	REAR BUMPER RETAINER RH <i>free</i>	\$ 45.00	✓
1	REAR BUMPER RETAINER LH <i>free</i>	\$ 45.00	✓
1	EXHAUST MUFFLER <i>new</i>	\$ 650.00	✓
1	TAILGATE <i>new</i>	\$ 1,200.80	✓
1	TAILGATE LOGO	\$ 96.00	✓
1	TAILGATE EMBLEM SUBARU	\$ 85.00	✓
1	TAILGATE EMBLEM "FORESTER" <i>new</i>	\$ 85.00	✓
1	TAILGATE EMBLEM "SPORT"	\$ 65.00	✓
1	TAILGATE EMBLEM "CAWD"	\$ 45.00	✓
1	REAR END PANEL <i>new</i>	\$ 385.00	✓
1	REAR END PANEL TOP GARNISH <i>new</i>	\$ 125.00	✓
	Sub Total	\$ 10,337.30	
	DISCOUNT 10% on Parts	\$ 1,033.73	
	Total	\$ 9,303.57	

Special Nett Item

10	FRONT BUMPER CLIPS <i>new</i>	\$ 80.00	✓
1	REAR NUMBER PLATE WITH GARNISH <i>new</i>	\$ 45.00	✓
10	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	\$ 65.00	✓
1	FRONT NUMBER PALTE WITH GARNISH <i>del</i>	\$ 45.00	✓
1	REAR BUMPER SENSOR <i>new</i>	\$ 450.00	✓
10	REAR BUMPER CLIPS <i>new</i>	\$ 95.00	✓
10	FRONT SUPPORT PANEL TOP GARNISH CLIPS <i>new</i>	\$ 120.00	✓
10	FRONT GRILLE CLIPS <i>new</i>	\$ 120.00	✓
	TOTAL:	\$ 1,020.00	

Labour & Misc

1	TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	\$ 1,500.00	700
1	TO SPRAY PAINT ON ACCIDENT AREAS	\$ 1,500.00	600
1	TO REMOVE AND REFIT AIR CON CONDENSER & TOP UP C	\$ 150.00	✓
1	TO REMOVE AND REFIT RADIATOR PRESSURE TEST	\$ 100.00	✓
1	TO RESET ECU AND WIRING	\$ 450.00	30
1	TO RUST PROOFING ACCIDENT AREAS	\$ 150.00	50
	Sub Total	\$ 3,850.00	
		\$ 14,173.57	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TP China

Shirley

JFISJ3KLSJG112468

380

3023.50

2420.40

305

Adrian Lj
P/P 18/03/20

06 Days

total: 4105.40

(P/P)