

ASSIGNMENT

From: _____ Date: 10.3.2020

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGP 22732

at Workshop m/s Yu AUTO

of 160 sin ming Drive # 02-17

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 8136

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 10/21 Person Contacted:

Vehicle: IN / OUT

Veh No: SGP 22737 Yr Regn: 12 / 06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy A175 C.C. 1598

Colour M. Green A/C: Insured / Std / NI / NA

Sp. Reading 332005 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRO 537 EC107137265

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD / Rim or _____

Tyre Size: F: 195/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or *Nexa*

Front		Rear	
R/Bal.	<u>7</u> mm	R/Bal.	<u>2</u> mm
L/Bal.	<u>7</u> mm	L/Bal.	<u>2</u> mm
D.O.A.	<u>13/3/20</u>	D.O.I.	<u>18/3/20</u>
Survey held at			

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]

Date/Time, File Pass to?

01/04/20

ii) Typ. St

Date/Time, File Return to?

2)

~~Report Format :~~

Lump Sum \$3,150/- 45

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

1	Site Insp (\$
---	---------------

□	Interview (\$
---	---------------

	Tech. Invs (\$)
--	-----------------

: Weekend (\$)

Survey Fee:


Transportation:

Photos

Others	1
--------	---

TOTAL

220



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

Estimate No: ES2000029

Date: 17 Mar 2020

Policy No:

Veh Reg No: SGP2273Z

Make/Model: TOYOTA COROLLA

ALTIS 1.6 AUTO

Chassis No: MR053ZEC107137265

Engine No: 3ZZ4620376

Reg. Date: 11/12/2006

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 13/03/2020

TP Veh Reg No: WC4650J

*Not with claim
11 days @ 3150p
Running After Police
6 days*

Estimate Repair Cost to Vehicle No :SGP2273Z

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 REAR WHEEL RIM - LH	800.00	1 PC	<i>Sm</i> 800.00	X
2 REAR TYRE 195/60/15	300.00	1 PC	<i>Sm</i> 300.00	X
			1,100.00	1,100.00
Spare Parts				
3 REAR DOOR - LH	869.30	1 PC	<i>B</i> 869.30	✓
4 REAR DOOR HINGE - LH (TOP)	71.50	1 PC	<i>R</i> 71.50	X
5 REAR DOOR HINGE - LH (LOWER)	71.50	1 PC	<i>R</i> 71.50	X
6 REAR DOOR PROTECTOR - LH	155.60	1 PC	<i>Net</i> 155.60	✓
7 REAR DOOR WEATHERSTRIP - LH	135.60	1 PC	<i>Sm</i> 135.60	X
8 REAR DOOR REGULATOR GEAR - LH	261.20	1 PC	<i>Sm</i> 261.20	X
9 REAR STEP GARNISH - LH	261.20	1 PC	<i>Sm</i> 261.20	X
10 REAR DOOR LOCK	361.20	1 PC	<i>Tr</i> 361.20	✓
11 REAR DOOR OUTER HANDLE - LH	183.90	1 PC	<i>Net</i> 183.90	✓
12 REAR DOOR OUTER HANDLE BRACKET - LH	102.30	1 PC	<i>Sm</i> 102.30	X
13 REAR DOOR OUTER MOULDING - LH	165.50	1 PC	<i>Net</i> 165.50	✓
14 REAR DOOR GLASS CHANNEL - LH	82.10	1 PC	<i>Sm</i> 82.10	X
15 REAR DOOR PROTECTOR MOULDING - LH	65.10	1 PC	<i>Net</i> 65.10	✓
16 REAR DOOR TRIM BOARD	568.20	1 PC	<i>Sm</i> 568.20	X
17 REAR DOOR TRIM BOARD CLIPS - LH	5.00	1 PC	<i>Sm</i> 5.00	X
18 REAR FENDER - LH	842.90	1 PC	<i>B</i> 842.90	✓
19 REAR FENDER INNER TRIM - LH	420.00	1 PC	<i>Sm</i> 420.00	X
20 REAR BUMPER	550.00	1 PC	<i>R</i> 550.00	X
21 REAR BUMPER SIDE RETAINER - LH	80.00	1 PC	<i>Sm</i> 80.00	X
22 REAR WHEEL BEARING - LH	220.00	1 PC	<i>Net</i> 220.00	X
23 REAR AXLE	980.00	1 PC	<i>Sm</i> 980.00	X
24 REAR TAILLAMP - LH	380.00	1 PC	<i>Sm</i> 380.00	X
25 REAR GLASS MOULDING	80.00	1 PC	<i>Net</i> 80.00	✓
26 SEALANT	50.00	1 PC	<i>Net</i> 50.00	405m
27 REAR DOOR OUTER HANDLE CHROME GARNISH - LH	183.90	1 PC	<i>Net</i> 183.90	✓
			7,146.00	7,146.00
Labour				
28 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,500.00	1 JOB	1,500.00	800l
29 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,300.00	1 JOB	1,300.00	600l



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 13/03/2020
TP Veh Reg No: WC4650J

Estimate No: ES2000029
Date: 17 Mar 2020
Policy No:
Veh Reg No: SGP2273Z
Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO
Chassis No: MR053ZEC107137265
Engine No: 3ZZ4620376
Reg. Date: 11/12/2006

Estimate Repair Cost to Vehicle No :SGP2273Z

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
30 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	250.00	1 JOB	250.00	601
31 TO REMOVE/TRANSFER LH REAR DOOR MECHANISMS.	150.00	1 JOB	150.00	601
32 TO CHECK WIRING FUNCTIONS.	80.00	1 JOB	80.00	201
33 WHEEL ALIGNMENT	120.00	1 T	120.00	x
34 TO REMOVE/RENEW REAR UNDERCARRIAGE	400.00	1 JOB	400.00	x
35 TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS.	180.00	1 JOB	180.00	1201
36 TO REMOVE/REFIT REAR CUSHION SEAT, SPEAKER BOARD, ROOF UPHOLSTERY TO FACILITATE REPAIRS.	300.00	1 PC	300.00	1001
			4,280.00	4,280.00

Total S\$ 12,526.00

Add GST @ 7% 876.82

Total Amount Payable S\$ 13,402.82

TOTAL: SINGAPORE DOLLAR THIRTEEN THOUSAND FOUR HUNDRED AND TWO AND CENTS EIGHTY TWO ONLY

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: