



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

transit
2ndly

FA11BAAC112004433

Vehicle No. SGT24231 NISSAN LATI0

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	REAR BOOTLID <i>orig</i>		1125.20	+
1	REAR BOOTLID " LATI0 " EMBLEM <i>free</i>		71.00	-
1	REAR BOOTLID LOGO		69.00	-
1	REAR BOOTLID WEATHERSTRIP <i>free</i>		211.00	+
1	REAR BOOTLID LOCK		195.20	+
1	REAR BUMPER <i>dent</i>		898.80	475
2	REAR BUMPER SIDE RETAINER LH & RH @\$115.50 <i>new</i>		231.00	90
2	REAR BUMPER SIDE BRACKET LH & RH @\$105.50 <i>new</i>		211.00	+
1	REAR BUMPER ANTENNA KEYLESS <i>included</i>		225.00	75
1	REAR END PANEL <i>dent</i>	1442	755.20	442.70
1	REAR END PANEL TOP GARNISH <i>new</i>		263.80	+
2	REAR TAILLAMP LH & RH @\$610.70 <i>attatched</i>	1297.80	1221.40	2930
1	REAR TAILLAMP PANEL LH <i>new</i>		379.20	+
		less	10	
			20%	
			5854.80	
			1756.44	30%
			4098.36	
<u>SPECIAL NETT ITEMS</u>				
1 SET	REVERSE SENSOR <i>changed</i>		280.00	200
1	REAR END PANEL SEALANT <i>new</i>		100.00	60
1 SET	REAR END PANEL TOP GARNISH CLIPS <i>new</i>		80.00	+
1 SET	TAILGATE INNER TRIM CLIPS <i>new</i>		60.00	+
1	REVERSE CAMERA <i>new</i>		430.00	+
1	REAR WINDSCREEN SEALANT <i>changed</i>	290	100.00	+
1	REAR WINDSCREEN INNER SHEILD <i>new</i>		120.00	+
1	REAR BUMPER CLIPS <i>new</i>		80.00	30
Total Parts			5348.36	



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

Page No. 2

Vehicle No. SGT2423L NISSAN LATIO

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1400.00	650
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1200.00	750
3	To remove and refix wiring at damaged areas	180.00	30
4	To perform anti rust treatment on affected areas	150.00	80
5	To remove / refix <i>upholstery</i>	150.00	80
6	To transfer bootlid mechanism	100.00	x
7	To <i>remove reverse sensors</i>	100.00	60
	Labour Total :	3280.00	
TOTAL (PARTS & LABOUR):		8628.36	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Gij
w/s 18/03/20
0402p.

total 3237.80

2/2 = 2.6

2.6K