

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 31 Aug 2020

Preliminary Advice

Insured Vehicle No : FBF8856P
TP Vehicle No : SGT2423L
Make : NISSAN LATIO
Date of Inspection : 18/03/2020
Inspection At : Ace Autolotion Pte Ltd (KAKI BUKIT)
13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre
Singapore 417807

Accident Date : 13/03/2020
Assignment Date : 17/03/2020
Est. Duration of Repair : 4 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,628.36
Revised Amount	:S\$	3,237.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,237.80
Lump Sum Repair	:S\$	2,600.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- The vehicle is economical for repair
 - The vehicle is not economical for repair
 - Part-by-Part repair
 - Lump Sum repair
- The above survey was conducted on a 'without prejudice' basis.