

YAP LEE MOTOR

Reg. No. 52910085A

1 Kaki Bukit Ave 6 #01-26 Autobay@Kaki Bukit Singapore 417883
Tel : 68441555 Fax: 68441311 Email : yap_lee_motor@singnet.com.sg

Vehicle No.: GBB 5365E
Make / Model: Toyota Dyna 150 Manual
Your Reference: GT 1515L China Taiping
20 March 2020
Ip Chian Shirley.
STFAT35Y80K200616.

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	LIST ITEM	
1	Front Side Mirror Assy LH <i>Repd</i>	677.27 \$
1	Front Side Mirror Cover LH <i>Repr</i>	507.95 \$
1	Panel Vane Garnish LH <i>Not cracked.</i>	95.97 \$
		942.97 \$
	Less 20% <i>25%</i>	188.59 \$
		754.38

LABOUR CHARGES

To replace & repair above parts.
To re-spray on the affected areas.

	\$	300.00 <i>200</i>
	\$	300.00 <i>100</i>
		600.00

GRAND TOTAL:

1,354.38

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
P/P 20/03/20
02 Reps.

total: 807.95

CP/P