

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 64528211 FAX: 64517420

ESTIMATE

VFM PTE LTD
c/o 46 Lentor Plain
Singapore 786548

Not Notarised
11 Days @ 3900k
Recovery After Pain

5 days

Date : 18/3/2020

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE : HONDA VEZEL / SLS 4871 J	
1 pc	rear boot lid <i>1100.90</i>	<i>Rs</i> 1,264.90 ✓
1 pc	rear boot lock <i>180</i>	<i>Rs</i> 316.20 ✓
1 pc	rear boot outer garnish	<i>Rs</i> 564.70 X
1 pc	rear boot weatherstrip	<i>Rs</i> 306.70 X
1 pc	rear boot inner trim	<i>Rs</i> 515.40 X
1 pc	rear boot emblem "VEZEL"	<i>Rs</i> 67.50 ✓
1 pc	rear boot emblem "LOGO"	<i>Rs</i> 62.80 X
1 pc	rear boot lamp <i>326.20</i>	<i>Rs</i> 497.50 ✓
1 pc	rear tail lamp <i>460.60</i>	<i>Rs</i> 528.60 ✓
1 pc	rear boot lock catch	<i>Rs</i> 48.10 X
1 pc	rear bumper <i>762.70</i>	<i>Rs</i> 895.70 ✓
1 pc	rear bumper side	<i>Rs</i> 318.00 X
2 pcs	rear bumper side retainer @ 64.40	<i>Rs</i> 128.80 X
2 pcs	rear bumper reflector @ 183.60	<i>Rs</i> 367.20 X
1 pc	rear end inner panel	<i>Rs</i> 577.60 X
1 pc	rear end outer panel <i>517.00</i>	<i>Rs</i> 549.70 ✓
1 pc	rear end panel top garnish <i>184</i>	<i>Rs</i> 327.80 ✓
1 pc	remote lock sensor	<i>Rs</i> 350.80 X
1 pc	rear bumper lower dust cover	<i>Rs</i> 315.60 X
1 pc	remote lock buzzer <i>85.20</i>	<i>Rs</i> 215.40 ✓
1 pc	tools box	<i>Rs</i> 397.40 X
1 pc	windscreen moulding <i>118.00</i>	<i>Rs</i> 215.20 ✓
1 pc	windscreen inner shield	<i>Rs</i> 157.90 X
	sub-total	8,989.50
	less 20%	1,797.90
	sub-total	7,191.60

	balance brought forward.		7,191.60	
1 pc	number plate	s.nett	50 35.00	X
1 pc	number plate housing	s.nett	50 35.00	X
1 pc	windscreen glass sealant	s.nett	na 60.00	4000
1 set	reverse sensor	s.nett	nd 250.00	2000
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.		800.00	door
	To check wiring system.		200 30.00	
	To apply putty & spray painting on affected areas.		700 1,000.00	
	To apply rust proofing on affected areas.		100.00	600
	To apply water proof sealant on affected areas.		80.00	300
	To remove rear windscreen glass to enable repair.		1200 150.00	
	To carry out exhaust works.		na 100.00	X
	To transfer door accessories.		600 100.00	
		total	9,931.60	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: