

Asker

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305387829

Date : 24/03/20

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : RAM RASIL

: SHD3350D

16/03/2020

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: CHINA YP5615M

2. The finalized amount shall be:

(a) Spare Parts after List discount _____

(b) Labour Charges _____

Total for Part-By-Part Repair Cost _____

(c.) Lumpsum Repair (if applicable) _____

Total for Lumpsum repair cost after Less: _____

Final Lumpsum Repair cost \$2,500.00


3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : 

Name : CHIANG

Name : RASIL

Tel : 62148314

Date : 24/03/2020

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHD3350D

MAKE :

MODEL I-40

DATE 16/03/2020

CHIANG/NTUC

LKK
LKK

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER repair			\$1,052.20 X
1	FRT BUMPERBUMPER BRACKET SIDE LH X SC			\$24.60 X
1	FRONT BUMPER RETAINER MTG LH X SC		2721	\$22.40 X
1	FRT FENDER SHIELD LH X SC		20%	\$174.90 X
1	WHEEL HUB -CAP LH add damage 12			\$107.10 X
1	LH REAR WING MIRROR SC		2176.80	\$670.00
1	FRT LH FENDER SC			\$663.00
1	LH HEADLAMP ASSY SC			\$1,388.00
				SUB TOTAL
				\$4,102.20
				20.00%
				\$820.44
				DISCOUNTED TOTAL
				\$3,281.76
	Labour Charge			
	Panel Beating		380	\$500.00
	Spray Painting Charge		950	\$600.00
	Tuff Kote		40	\$60.00
	Check Lighting		30	\$60.00
				TOTAL LABOUR
				\$1,220.00
				ESTIMATE TOTAL
				\$4,501.76

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2176.80
950.00

3126.80
20%

2501.44

45-2,500

3 days

Rasul
Hp 90010068
3 days
4/3
17/03/2020 @ 12ush
Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:


Team: ARC Repair TP (CLSO) **JOB CARD** Sales Order: 305387829 JC NO.:

CUSTOMER COMFORT TRANSPORTATION PTE LTD MS 7010015 CUSTOMER NO. 383 SIN MING DRIVE ADDRESS Singapore SINGAPORE 575717 65508755 (R) (O) (P) COUNT CARD NO.	REGN NO.: SHD3350D	MILEAGE
	MAKE: HYUNDAI	FUEL
	MODEL: I-40	DATE/TIME IN: 16.03.2020 13:25
	YR OF MANO.: 21.07.2016	TARGET DATE
	CHASSIS CODE: KMHLB41UMGU092192	COMPLETION DATE/TIME:

Accident Date: 16.03.2020
 ATTURE: 3P 16.03.2020

JOB DESCRIPTION

S/NO LABOR CODE DESCRIPTION



BOOKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedge Slip

Exit Pass

SHD3350D CHIANG

Vehicle No.: SHD3350D

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard