

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 32634

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0276/2020/NS
Date	:	13-Mar-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms Lim Bee Eng
Address	:	Blk 29 Chai Chee Avenue #09-90 Singapore 460029
Telephone	:	HP +65 96866393
Type of Claim	:	Own Damage Claims
Policy No.	:	1800001181-01
Vehicle No	:	SLV 6685 B
Model Code	:	Audi A3 Sedan 1.0 TFSI 8V
Model / Year	:	Jan-18
Engine No	:	CHZ 609810
Chassis No	:	WAUZZZ8V6J1033725
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	23-Feb-20
Place of Accident	:	Along Road 1 Bedok Reservoir Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6041 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLV 6685 B

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	NN
2	To dismantle front bumper and rhs front fender. To renew rhs front fender. Re-organise crash management components. Reinstall all parts removed.	\$ 2,100.00	250
3	To respray rhs front fender.	\$ 1,000.00	550
4	To carry out diagnostic check.	S/N \$ 192.00	NN
TOTAL LABOUR CHARGES		: \$ 3,652.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLV 6685 B

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
1	FRONT FENDER - RH <i>repair</i>	\$	802.00
2	FRONT FENDER BRACKET - RH X NN	\$	26.00
3	FRONT FENDER CENTRE BRACKET - RH X NN	\$	36.00
4	FRONT FENDER BRACE X NN	\$	90.00
5	WHEEL HOUSING LINER - RH X NN	\$	159.00
6	WHEEL HOUSING LINER ATTACHMENT PARTS X NN	\$	84.00
7	SUNDRIES X NN	\$	200.00
TOTAL SPARE PARTS CHARGES		:	\$ 1,397.00
TOTAL LABOUR CHARGES		:	\$ 3,652.00
GRAND TOTAL		:	\$ 5,049.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Rasm - Hp 90010068

: 18/02/2020 @ 1330 hrs

: 3 days

: EXCESS: TBA

: Reverser
Reg after repair

Please Note

: This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the

progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel: 6768 9828 for appointment.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature