ASS. REC. BY: Marcus REF: ASSIGNMENT Veh No: JHJ96M Yr Regn: Type: M.Carl M.Cycle / Bus Van / Lorry / Taxi / Prime Mover / OD TP / WS / TP RES / OD RES / EVA / INV / MV	(03	3/ MSG 20004183/ Ugfznz
ASSIGNMENT Veh No:	(08/11/13) WEI REF:	
To Infect Vehicle No: at Workshop mis of at Workshop mis of of Insured: STD 6 6 Policy No. Opt 1348 28 Colour Sp. Reading Sp. Readin	From: Date:	Veh No: SJH (96M Yr Regn: 3,09 Type: M.Carl M.Cycle / Bus Van / Lorry / Taxi / Prime Mover /
Tyre Size: F: R: 2 3 S	To Inspect Vehicle No: St. H/S at Workshop m/s of Insured: STD 6 61 61 61 61 61 61 61	Make: - 70.15 Ca Alphard cc 236 2 Colour Black A/C: Insured / Std / NI / NA Sp.Reading / S269 7 T/Radio: Insured / Std / NI / NA Eng/No: C/No: ANH 20 Sol 46/4 Gen. Cond Good / Fair / Poor / Burnt Steering: Inorder / Jammed / Leaked / Burnt or Brake: Inorder / Jammed / Leaked / Burnt or
Date / Time Action / Instruction COL 24-3-1019 LTA 29769 23/3/20 L/S # 3000 (onfined with Alm. (fool & 10755.80), 17/-) W/15/100 0 11. 08am on one of the continuation of the continuat	(Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No days Res.: Yes or No Lum Sum: CA / REV / REP. / 24 HRS 90 Vehicle	Tyre Size: F: R: 2 3 S GO C G BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Front R/Bal. mm R/Bal. mm L/Bal. 6 mm L/Bal. 6 mm D.O.A. 1713/20 D.O.I. / P/3/20 Survey held at Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Cote/Time, File Pass to? Prell. Report Days Of Repair:	Date / Time Action / Instruction	769 ud with Alm. (fod \$ 10555.80, 77%) wyn 7ay von Meximon.
Report Format: Resurvey No. of Trip: 2 Survey Fee: Transportation: 200 Add Fee: Site Insp (\$)_s+Rs_si Interview (\$) Photos Lump Sum / I.B.I: (\$ 7000) : Weekend (\$)		KECEIVED 2 4 MAR 2020
Date/Time, File Return to?	1 1 I I I I I I I I I I I I I I I I I I	
Lump Sum / I.B.t: (\$ 7,000) : Weekend (\$)	Date/Time, File Return to?	Add Fee: Site Insp (\$)_S+RS_SI
	and the same representation of the same of	: Weekend (\$

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Jowyn Tay Mei Ling

Date: 24 Mar 2020

Preliminary Advice

Insured Vehicle No : SJD6161P

TP Vehicle No

: SLH596M

Accident Date

: 17/03/2020

Make

: TOYOTA ALPHARD

Assignment Date

19/03/2020

Date of Inspection : 18/03/2020

Est. Duration of Repair

: 4.00

Inspection At

: FASTECH AUTO PTE LTD (HQ)

1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY

SINGAPORE 417883

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,255.80
Revised Amount	:S\$	3,773.48
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,773.48
Lump Sum Repair	:S\$	3,000.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:88

Remarks

() The	vehicle is	economical/not	economical	for repair.
---	-------	------------	----------------	------------	-------------

(X) The above survey was conducted on a 'without prejudice' basis.

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Thursday, 19 March 2020 9:38 AM

To:

Motor Survey

Cc:

SUR; KKLau; Accounts (LKKAuto)

Subject:

DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA:

17/03/2020, SLH 596M (TP VEHICLE), SJD 6161P (OI VEHICLE)

Attachments:

SLH596 GIA.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SLH 596M at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883.

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Toyota Alphard 2.4A Moonroof \$70,000 (CDE till 03/2028)

\$8,710 /vr

31-Mar-2008

2,362 cc

Available

(CONTRACTO)

Ideal For Long Distance And Pick Up Overseas Guest, Experience The Luxurious Feel And Comfort Through Out The Drive, Previous Own...

Posset: 67-Hair 2020 Tags: 2008 Toyota Alphant, Toyota Alphant, Toyota, Alphant



Toyota Alphard 3.55 Prime Selection (COE till 10/2029) \$93,800

\$9,740 /vr

30-Dec-2009

103,000 km 3,455 CE

Available

Bodykit Converted To New Facelift Model. No Regair Needed! Newly Overhaul Engine! New 19" Sports Rims, Tyres, Suspension, BrakePa.

38 Karz Station LLP

Power: 63-Mar-2020 Tags: 2009 Toyour Apriant, Toyour Alpharo, Toyour, Alphard



Toyota Alphard 2.4A 5 (COE till 04/2029)

\$73,775

\$8,090 /VF

20-Aug-2009

2,362 cc

Available

Smooth And Quiet Engine, Pristine Condition, 7 Seater. No Repairs Need! Seeing Is Believing! Flexible Loan Are Provided! Trade In Are...

Postest: U1-Mar-2020 - Tags: 2009 Toxicta Alphant, Toxicta Alphant, Toxicta Alphant



Toyota Alphard 2.4A 5 (COE till 05/2023)

\$37,800

\$11,890 /yr

23-May-2008

2,362 cc

MPV

Available

B Seater With Twin Moonroof, Well Maintained! Smooth Engine, Very Comfortable, Clean And Neat Interior, Trade In Welcome. Flexible...

Posted: 29-Feb-2000 Tags: 2008 Toyota Alphard, Toyota Alphard, Toyota, Alphard.



Audio Upgrade For Any Budget

Looking for a headunit upgrade but don't how to start? Choose from 150+ headunits to best suit your needs and budget. Price from just \$100! Find out more!



Toyota Alphard 2.4A XL (COE till 04/2028)

\$66,800

\$8,230 /yr

28-Apr-2008

2.362 cc 125,435 km MPV

Available

Max Loan Amount Available As Advertised! One Of The Most Luxunous Yet Affordable MPV You Can Find For Your Family Or Business Us.

Creative Auto

Posted: 2+ Feb 2020 Tags: 3008 Toyota Alphard, Toyota Alphard, Toyota, Alphard



Toyota Alphard 3.5A 5 (COE till 04/2029)

\$82,800

\$9,080 /vr

13-Aug-2009

3.456 cc

113,592 km MPV Available

Looking For A Afforable Family Car. Driver's Memory Seat And Passenger's Electric Seats With Factory Leather, Electric Sliding Doors And...

Motor-Way Credit Pte Ltd

Posted: 19-Feb-2020 Tags: 1009 Toyota Alphard, Toyota Alphard, Toyota, Alphard



Toyota Alphard 2.4A S (COE till 04/2029)

\$73,800

\$8,090 /yr

26-Aug-2009

2.362 cc

MPV

Available

CONTRACTOR OF THE PARTY OF THE

THE RESERVE

Elegant Alphard 2.4A, New COE, 7 Seaters, Pristine Condition.

Posted: 19-Feb-2020 Tags: 2009 Toyota Alphard, Toyota Alphard, Toyota, Alphard



Toyota Alphard 2.4A Welcab (COE till 09/2027)

\$62,068

\$8,270 /yr

18-Sep-2007

2.362 cc

MPV

Available

Well Maintained All Time Favorite Model, Well Maintained, Excellent Condition, Many Wear And Tear Parts Replaced With Receipt. Your...

Posted: 13-Feb-2020 Tags: 2007 Toyota Alphard, Toyota Alphard, Toyota, Alphard



Toyota Alphard 2.4A (COE till) 09/20291

\$76,800

\$8.060 /VT

28-Sep-2009

2,362 cc

130,000 km

Available

Drive Away With Excellent Conditioned, Well Maintained By The Ex Owner. Smooth And Quiet Engine. Leather Seats Are In Good Conditi...

Postest: 15-Feb-2020 Tags: 2009 Toyota Alphand, Toyota Alphant, Toyota, Alphand

Toyota Alphard 3.5A S Moonroof (COE till 06/2029) \$80,800

\$8,760 /yr

05-Jun-2009

3,456 cc

MPV

Available SECURITY OF STREET

Only \$720 Depreciation/month For This Luxurious MPV. Driver's Memory Seat And Passenger's Electric Seats With Factory Leather, Elect.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID:	909Z	
Vehicle Details		
Vehicle No.:	SLH596M	
Vehicle to be Exported:	No	
Intended Deregistration Date:	18 Mar 2020	
Vehicle Make:	TOYOTA	
Vehicle Model:	ALPHARD 2.4S A	
Primary Colour:	Black	
Manufacturing Year:	2008	
Engine No.:	2AZC473537	
Chassis No.:	ANH208014614	
Maximum Power Output:	125.0 kW (167 bhp)	
Open Market Value:	\$34,722.00	
Original Registration Date:	25 Mar 2009	
First Registration Date:	25 Mar 2009	
Transfer Count:	3	
Actual ARF Paid: Intended PARF Rebate Details	\$34,722.00	
PARF Eligibility:	Forfeited	
PARF Eligibility Expiry Date:		
PARF Rebate Amount: Intended COE Rebate Details	\$0.00	
COE Expiry Date:	24 Mar 2029	
COE Category:	B - Car (1601cc & above)	
COE Period(Years):	10	
PQP Paid:	\$33,018.00	
COE Rebate Amount:	\$29,769.00	
Total Rebate Amount:	\$29,769.00	

The information contained herein is correct as at 18 Mar 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver,
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ALL	 	ATEN	1 - 2

Date Of Report 18/03/2020 11:41
Date Of Accident 17/03/2020 18:25

Exact Location Of Accident NEW UPPER CHANGI RD TWRDS SINGAPORE EXPO

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLH596M

Insured/Policyholder

Name Of Registered Owner MA LI

NRIC No SXXXX909Z
Email Address NOEMAIL

 Mobile Phone No
 (LOCAL) +65-92059065

 Alternative Phone No
 OTHERS-92059065

Vehicle Particulars

Manufacturer TOYOTA

Model ALPHARD 2.4S A

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 5108165185

Cover Note Number

Driver

 Name of Driver
 MA LI

 NRIC No
 SXXXX909Z

 Date Of Birth
 11/12/1981

 Occupation
 INDOOR

 Date Of Driving Pass
 09/12/2008

Driving Experience: 11 YEARS AND 3 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-92059065

Fax Number

Contact Number OTHERS-92059065

EMail Address NOEMAIL

Address 40 CANBERRA DRIVE #01-01 YISHUN SAPPHIRE

Postcode 768433

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by

ambulance?

NO:

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO.

Number of Passengers (Including Driver)

Passenger 1

NAME:

: GUEST

GENDER:

MALE

Passenger 2

NAME:

GUEST

GENDER:

FEMALE

Passenger 3

NAME:

GUEST

GENDER:

FEMALE

Passenger 4

NAME:

GUEST

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED:

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJD6161P

Vehicle Make/Model/Colour

MERCEDES BENZ / E200 AVG (R18 LED)

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Date of Accident	: H- 03 2020 Accident Time: 6 25 PM (24-HR-Format)
Accident Place	. Hew Upper changi Road Towards Singapore Expo.
Vehicle. No. (Car Plate No.)	: SLH 596M Make/Model: Toyota Alphard 2.43
Insurace Company	: HTUC . Policy No: 5108165185 .
Owner or Company Name /IC No.	(SPOPZF182) if pM:
Owner or Company Contact No.	:Owner's Hp 9205 9065 Company Tel
DRIVER'S Name / IC No.	es above
DRIVER'S Date Of Birth	: 11-12- 1981 DRIVER'S License Pass Date 09-12 1008
Relationship of Owner & Driver	: Spouse \ Parents \ Children \ Sibling \ Employee\ Others:
DRIVER'S Address	: 40 Canhella Drive # 01-01. Singapore 768433.
DRIVER'S Contact No./ Alt No.	:1)
DRIVER'S Occupation	INDOOR OUTDOOR (e.g. working inside or outside office)
Email Address	:
Weather & Road Surface	: CLEAR & DRYARAINING & WET \ AFTER RAIN & WET
Reporting Type	: Reporting Only \ Claim Other Party \ Claim Own Insurance
Number of Passengers (Including Di	
Was there any video Captured by ca Exact purpose for which vehicle was Any Injury (If YES, Pls state): NO	being used at the time of accident Private use Work number
Other P	arty Driver's Particular (if any)
Vehicle, No:	Vehicle. No:
Vehicle Make\Model:	
Name Driver:	
IC No. Driver/Contact:	
* NEW - Passenger's name &	gender:
1	Unknown - Male
15	Unknown - Femole
	Unknown - Female
	Unknown - Femole

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:


NRIC/FIN No.:

SKETCH PLAN		
	as per attached	
	+ 1 42 let (0) toches	
PECOURE CIRCUMATERALICES	OF THE ACCIDENT	the training a finite or an all the first of
ESCRIBE CIRCUMSTANCES	OF THE ACCIDENT	
As 17th March	2020 01 1 (The tree of the t
On 17th March	2020 at around 6	25 pm , Iwas Travelling along
		3 6
Hew Opper change !	load Towards Singapore E	xpo. While I Was Waiting Of
	Supplier C	THE THE THE PROPERTY OF
the Lattie meeting	Jose Rodeb N. II A.	
THE THATTIC INICTION	near Bedot North Avenu	e I , I heard a loud bana
0 11 1		J
from behind and	I came out of the ca	then lealised that vehicle humber
- Pallinia	300	THE COURSE WAS ASSESSED.
530 6161 P had hit	som my sear. I have	4 parrengers inside My rar and
OGO DIOLF INO HIL	with mid text - 1 have	A handada made ma de dud
	4	N. C.
No dan in inimal		
HO DAR IS INJURED .		
		*1
	14	
ECLARATION		
We declare the foregoing particu	lars are true in every respect.	
0.4		
licyholder's Signature	Driver's Signature	Reporting Centre Personnel's Signature
ite & Time:	(If driver is not the policyholder)	Name:
	Date & Time:	NRIC/FIN No.:
	Late & Hiller	MARIE CHINE NO

GIARMC StetchPlanForm, V3.

2

NRIC/FIN No.:





FASTECH AUTO PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-,48, AUTO BAY SINGAPORE 417883

VEHICLE No: SLH 596M

1PC

1PC	REAR WINDSCREEN MOULDING	11 \$128.10 X
1PC	TAILGATE	
1PC	TAILGATE REAR LOGO	re \$68.50_
1PC	TAILGATE 'ALPHARD' EMBLEM	ru \$82.50
1PC	TAILGATE INNER LOCK	17 \$409.20 X
1PC	TAILGATE INNER TRIM	17 \$661.10 \$
1PC	TAILGATE WEATHERSTRIP 3/1-20	Tw1 \$398.50
1PC	REAR BUMPER SUSO	20/70 \$1,255.10
2PCS	REAR BUMPER SIDE RETAINERS @\$85.50	4 1 \$171.00/
1PC	REAR BUMPER TOW COVER	17 \$48.50X
1SET	REAR BUMPER CLIPS	ner \$50.00
1PC	REAR END PANEL OUTER 762-70	Bakon \$788.10
1PC	REAR END PANEL INNER	√ \$699.50 X
1PC	REAR END PANEL TOP GARNISH	11 \$388.10 X
1PC	REAR END PANEL LOCK SENSOR	Shops/cre \$385.10
2PCS	TAILLAMPS @\$525.10	1 \$1,050.20 X
2PCS	TAILLAMP LOWER GARNISHS @\$488.10	11 8/styn \$976.20 ×
		N/5 nn \$9,425.80
	S.NETT	
1PC	REAR WINDSCREEN SEALANT	\$50.00 ×
2PCS	REAR BUMPER PDC SENSORS @\$350.00	should 5700.00 350 S. N
100	TEAT THE CAME AND ADDRESS OF THE COMME	

TO CHECK WIRING AND SEA TO DISMANTLE & REPALCING PDC SENSOR TO DISMANTLE & REFIX REAR WINDSCREEN TO SPRAY RUST PROOFING TO DISMANTLE & REFIX CUSHION UPHOLSTERY TO TRANSFER TAILGATE MECHANISM PARTS TO PUTTY & SPRAY PAINTING

REAR END PANEL SEALANT

\$50.00 🗶 \$80.00 20 \$100.00 570 11 \$150.00 X \$80.00 30 \$120.00 80 \$880.00 X \$880.00 680 \$1,500.00 680 \$13,255.80

TOTAL X Airto Consultants hence notify n Repairer of the following:

Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/MSG20004183/UQF3N2

Date:

30/03/2020

REFERENCE

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

1001348128

Claimant Vehicle

SLH596M

Insured Vehicle No:

SJD6161P

No: Date of Loss:

17/03/2020

Nature of Claim:

TP

241014 Claim No:

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLH596M

Make & Model: Reg. Date:

TOYOTA ALPHARD, 2.4 S (A) 25/03/2009 (Man. Year: 2008)

Engine No: Chassis No: Odometer:

2AZC473537 ANH208014614

192697 km

Colour:

Black

Engine Capacity: Market Value/New Car Price: 2362 cc N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

235/50 R18

Rear Tyre Size:

235/50 R18

Front Left Side: Front Right Side: Bridgestone 6 mm Bridgestone 6 mm Rear Left Side: Rear Right Side: Bridgestone 6 mm Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		10,225.80	2,233.47	7,992.33	78.16
Miscellaneous Items		0.00	0.00	0.00	
Labour		3,030.00	1,540.00	1,490.00	49.17
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	13,255.80	3,773.47	9,482.33	71.53
	Approved Total (Overridden) (S\$)		3,000.00		
	(S\$)	13,255.80	3,000.00	10,255.80	77,37
	+ GST 7.00/7.00% (S\$)	927.91	210.00	717.91	77,37
	Nett Amount (S\$)	14,183.71	3,210.00	10,973.71	77.37

INSPECTION

Date of Assignment:

Date Inspected:

19/03/2020

18/03/2020 Inspected At:

Fastech Auto Pte Ltd (HQ)

1 Kaki Bukit Ave 6, #01-46/48/50 Autobay

Singapore 417883

Estimated Period of Repair:

4.0 days

Adjuster: MARCUS CHUA Manager:

SHIAU CHAN

NOTE. This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 30 Mar 2020)

Parts:

M1-MPV

TOYOTA ALPHARD 2.4 S (A) (Catalogue: Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLH596M)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

			404	Don	-
к	ecom	men	aea.	Pal	lS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	128.10 F	*-FL
2	1		*TAILGATE	Repair	1,866.10 F	*-FL
3	1		*TAILGATE REAR LOGO	Necessary	68.50 F	*68.50 FL
4	1		*TAILGATE ALPHARD EMBLEM	Necessary	82.50 F	*82.50 FL
5	1		*TAILGATE INNER LOCK	Not Necessary	409.20 F	*-FL
6	1		*TAILGATE INNER TRIM	Not Necessary	661,10 F	*-FL
7	1		*TAILGATE WEATHERSTRIP	Twisted	398.50 F	*312.20 FL
8	1		*REAR BUMPER	Deformed/Torn	1,255.10 F	*850.90 FL
9	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	171.00 F	*-FL
10	1		*REAR BUMPER TOW COVER	Not Necessary	48.50 F	*-FL
11	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
12	1		*REAR END PANEL OUTER	Badly Dented	788.10 F	*762.10 FL
13	1		*REAR END PANEL INNER	Repair	699.50 F	*-FL
14	1		*REAR END PANEL TOP GARNISH	Not Necessary	388.10 F	*-FL
15	1		*REAR END PANEL LOCK SENSOR	Shorted/Cracked	385.10 F	*385.10 FL
16	2		*TAILLAMPS	Not Necessary	1,050.20 F	*-FL
17	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*-FS
18	2		*REAR BUMPER PDC SENSORS	Shorted	700.00 FS	*350,00 FS
19	1		*REAR END PANEL SEALANT	Not Necessary	50,00 FS	*-FS
20	1		*TAILLAMP LOWER GARNISH O/S (TORN)	Not Consistent With The Impact	488.10 F	*-FL
21	1		*TAILLAMP LOWER GARNISH N/S	Not Necessary	488.10 F	*-FL
F=Fn	inchise	part. S≃Spc	Nett. L=ListItemDisc.			
				Sub Total (S\$)	10,225.80	2,861.30
			- List Item Di	scount on L Items 0.00/25.00% (S\$)	0.00	627.83

Report was unsubmitted during this print-out.

Total Parts (S\$) 10,225.80

2,233.47

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recom	mended	Labour
INCOULI		

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING	New	80.00	20.00
2	TO DISMANTLE & REPLACED PDC SENSOR	New	100.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
4	TO SPRAY RUST PROOFING	New	80.00	30.00
5	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
6	TO TRANSFER TAILGATE MECHANISM	New	120.00	0.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	880.00	680.00
8	TO PUTTY & SPRAY PAINTING	New	1,500.00	680.00
		Gross Labour Cost (S\$)	3,030.00	1,540.00
	Report was unsubm	itted during this print-out.		

< END OF ESTIMATES >