

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5458U**AAD2003-090***NOT AUTHORIZED
L/Smp & 4700:*

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model: 17 MAR 2020
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

SHC 5458U

VF1ABL15AUC280943

RENAULT

LATITUDE

16.3.2020

LONPAC

18/12/2014

	PART		LIST	
1	BUMPER COVER REAR	\$	<i>Bu</i> 561.70	—
1	BUMPER LOWER REAR	\$	<i>Ne</i> 411.90	—
1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 98.10	X
1	BUMPER BRACKET SIDE RH REAR	\$	<i>Sn</i> 82.10	X
1	BUMPER RETAINER RH REAR	\$	<i>Sn</i> 59.80	X
1	BUMPER REFLECTOR RH	\$	<i>Sn</i> 16.60	X
1	BUMPER BRACKET SIDE LH REAR	\$	<i>Sn</i> 80.80	X
1	BUMPER RETAINER LH REAR	\$	<i>Sn</i> 54.20	X
1	BUMPER REFLECTOR LH	\$	<i>Sn</i> 16.60	X
1	BUMPER BEAM REAR	\$	<i>Bu</i> 547.80	—
1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 114.50	X
1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 100.90	X
1	OUTER PANEL REAR (End Panel)	\$	<i>Bu</i> 745.80	—
1	OUTER PANEL REAR (End Panel) TRIM	\$	<i>Sn</i> 404.56	X
1	TAILLAMP RH	\$	<i>Sn</i> 313.10	X
1	TAILLAMP PANEL RH	\$	<i>R</i> 401.40	X
1	TAILLAMP LH	\$	<i>Sn</i> 401.40	X
1	TAILLAMP PANEL LH	\$	<i>R</i> 401.40	X
1	BOOT REAR	\$	<i>Bu</i> 1,677.20	—
1	BOOT FINISHER	\$	<i>Sn</i> 344.70	X
1	BOOT WHEATERSTRIP	\$	<i>Sn</i> 178.20	X
1	BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 277.70	X
1	BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 277.70	X
1	BOOT BADGE 'RENAULT'	\$	<i>Ne</i> 82.40	—
1	BOOT BADGE	\$	<i>Ne</i> 95.80	—
1	BOOT STRUT LH	\$	<i>Sn</i> 145.10	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5458U**AAD2003-090**

- 1 BOOT STRUT RH
- 1 BOOT HINGE LH
- 1 BOOT HINGE RH
- 1 BOOT INNER TRIM BOARD
- 1 BOOT LOCK
- 1 EXHAUST CAP REAR
- 1 SPARE TYRE BOARD

	\$	<i>Sm</i>	145.10	} X
	\$	<i>R</i>	254.20	
	\$	<i>R</i>	253.80	
	\$	<i>Sm</i>	611.00	
	\$	<i>R</i>	246.60	
	\$	<i>Sm</i>	125.40	
	\$	<i>Sm</i>	680.90	
TOTAL	\$		10,208.46	
10%	\$		1,020.85	
	\$		9,187.61	

Special Nett

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 1SET BUMPER BRACKET CTR CLIP
- 1SET BUMPER BRACKET SIDE CLIP RH RR
- 1SET BUMPER RETAINER RH CLIP RR
- 1SET BUMPER BRACKET SIDE CLIP LH RR
- 1SET BUMPER RETAINER CLIP LH RR
- 1SET BUMPER LOWER REAR RIVET
- 1SET BUMPER LOWER REAR CLIP
- 1 BOOT STICKER "Trans-cab"
- 1 BOOT STICKER "6555-3333"
- 1 BOOT INNER TRIM CLIP
- 1SET BOOT FINISHER CLIP
- 1 TAILLAMP CLIP LH
- 1 TAILLAMP CLIP RH
- 1 Rear Bumper Protector
- 1 REAR LICENCE PLATE WITH HOLDER

	\$	<i>Phon</i>	700.00	<i>400sm</i>
	\$	<i>na</i>	66.00	—
	\$	<i>na</i>	33.00	—
	\$	<i>na</i>	10.00	X
	\$	<i>na</i>	20.00	X
	\$	<i>na</i>	10.00	X
	\$	<i>na</i>	20.00	X
	\$	<i>na</i>	22.00	X
	\$	<i>na</i>	66.00	✓
	\$	<i>na</i>	30.00	—
	\$	<i>na</i>	30.00	—
	\$	<i>na</i>	45.00	X
	\$	<i>na</i>	24.20	X
	\$	<i>na</i>	5.00	X
	\$	<i>na</i>	5.00	X
	\$	<i>na</i>	100.00	X
	\$	<i>Sm</i>	80.00	X
TOTAL	\$		1,266.20	

TOTAL PARTS \$ 10,453.81**LABOUR**

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5458U**AAD2003-090**

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	602
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	602
To check steering geometry and computer wheel alignment	\$	220.00	nn X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	7 X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	170.00	7 X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	602
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	4 X
To Rust-Proofing Of The Affected Areas.	\$	170.00	602
To transfer of tire, rim and on wheel balancing.	\$	170.00	4 X
To reinstall rear bumper parking sensor.	\$	170.00	602
Putty and spray painting of the affected portion.	\$	6,000.00	662
To repair and realign rear exhaust pipe.	\$	170.00	7 X
To Check Electrical Lighting Concerned.	\$	170.00	202

Trans-cab Auto Services Pte Ltd

AAD2003-090

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5458U

TOTAL \$ 14,340.00

Over All Total \$ 24,793.81

LUMP SUM (REPAIR DAY)

~~20~~ **DAYS**
3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: