

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7822T

AAD2003-082

*Not Authorised
Repairing BY paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

17 MAR 2020

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHB 7822T

JTDKB3FU103083452

TOYOTA

PRIUS

14.3.2020

III

30/8/2019

	PART		LIST	
1	FRONT BUMPER	\$	CM 516.00	✓
1	BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	Sm 103.40	X
1	FRONT BUMPER SIDE RETAINER RH	\$	Sm 80.10	X
1	FRONT BUMPER SIDE RETAINER LH	\$	DII 82.30	✓
1	REINFORCEMENT, FRONT BUMPER	\$	R 716.60	X
1	REINFORCEMENT, FRONT BUMPER, NO.2	\$	Sm 246.10	X
1	ABSORBER, FRONT BUMPER ENERGY	\$	Sm 79.60	X
1	ABSORBER, FRONT BUMPER, LOWER	\$	Sm 132.70	X
1	COVER SUB-ASSY, ENGINE UNDER, NO.2	\$	Sm 241.90	X
1	COVER SUB-ASSY, ENGINE, NO.1	\$	Sm 472.40	X
1	COVER, FRONT BUMPER HOLE, LH	\$	Sm 29.30	X
1	EXTENSION, FRONT BUMPER, LH	\$	Sm 120.10	X
1	FRONT LED LAMP (LOWER) LH	\$	Sm 951.40	X
1	FRONT HEADLAMP LH	\$	CM 2,637.60	✓
1	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$	Sm 960.50	X
1	MOTOR, HEADLAMP LEVELING, LH	\$	Sm 487.50	X
1	FRONT FENDER LH	\$	R 977.80	X
1	LINER, FRONT FENDER, LH	\$	Sm 202.50	X
1	FRONT FENDER EMBLEM LH	\$	Sm 54.60	✓
1	GRILLE SUB-ASSY, RADIATOR	\$	Sm 346.00	X
1	GRILLE, RADIATOR, LOWER NO.1	\$	Sm 170.10	X
1	EMBLEM ASSY, RADIATOR GRILLE	\$	Sm 90.80	X
1	FRONT BONNET	\$	R 983.10	X
1	HINGE ASSY, HOOD, LH	\$	R 58.90	X
1	MOULDING ASSY, BODY ROCKER PANEL, LH	\$	Sm 594.80	X
1	COVER, RADIATOR SUPPORT OPENING	\$	Sm 235.30	X
TOTAL		\$	11,571.40	
25%		\$	2,892.85	
		\$	8,678.55	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7822T**AAD2003-082****Special Nett**

1 FRONT WHEEL RIM	\$	<i>Sm</i> 1,879.40	X
1 FRONT WHEEL RIM COVER	\$	<i>Sm</i> 211.50	X
1 FRONT TYRE 195/65/15	\$	<i>Sm</i> 350.00	X
1 CLIP, FRONT FENDER LINER	\$	<i>na</i> 35.00	X
1 FRONT NUMBER PLATE WITH MOULDING	\$	<i>Sm</i> 200.00	X
1 BUMPER CLIP FRT	\$	<i>me</i> 66.00	✓
1SET FRONT BUMPER RETAINER CLIP	\$	<i>na</i> 35.00	X
1SET ROCKER PANEL MOULDING CLIP	\$	<i>na</i> 35.00	X
TOTAL	\$	2,811.90	

TOTAL PARTS \$ 11,490.45**LABOUR**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>300d</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	<i>h</i> 170.00	X
To transfer of Front Bumper fittings, attachments and perform water seepage test.	\$	<i>h</i> 170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>h</i> 380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>h</i> 380.00	X
Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	<i>440g</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>h</i> 170.00	X

Trans-cab Auto Services Pte Ltd

AAD2003-082

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7822T

To Check Electrical Lighting Concerned.	\$	170.00	<i>20%</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>NA</i> 170.00	X
To transfer of Bonnet fittings, attachments and perform water seepage test.	\$	<i>NA</i> 170.00	X
TOTAL	\$	14,000.00	
Over All Total	\$	25,490.45	

(PART-BY-PART) Repair Days *20 days*
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: