

87

111 9

not Approved
 2hr
 1/5 @ 5250 /
 6 days



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring
 #08-1339 Singapore 470130
 Tel: 9450 7920
 zoomautowerks@gmail.com

Car Number: SLC8367G

Date: 16/03/2020

Model : MITSUBISHI ATTRAGE

Damaged Area: (Front RH Side Portion)

Repairer Estimation Cost of Repair :

MBSTA13

Supplementary may be included during the cost of repair :

Parts / Material :

1	Front Bumper	713.00
2	Front Bumper Fog Lamp RH	
3	Front Bumper Fog Lamp Garnish RH	
4	Front Bumper inner garnish	
5	Front Bumper Lower Centre Grille	166.00
6	Front Bumper Reinforcement	345.00
7	Front Bumper Retainer RH	48.00
8	Front Bumper Bracket RH	
9	Front Bumper Lower Engine Cover	
10	Front Bumper Tow Garnish	
11	Front Bumper Clips	39.00
12	Front Bonnet	
13	Front Wiper washer tank	
14	Front fender Quarter Garnish RH	
15	Front Wiper Panel Garnish Clips	
16	Front Radiator Grille Assy	410.50
17	Front support panel	
18	Front Radiator Grille Clips	
19	Front Fender RH	438.00
20	Front Fender Inner Shield RH	145.00
21	Front Fender Inner Shield Clips	39.00
22	Front Fender Bracket RH	
23	Front Headlamp RH	660.00
24	Front Headlamp Bracket RH	
25	Front sport rim 0.5	

DIS	\$	780.00	✓
CNE	\$	310.00	✓
CWT	\$	155.00	✓
CRA	\$	115.00	✓
Torn	\$	295.00	✓
Bul	\$	360.00	✓
CR	\$	78.00	✓
NS	\$	62.00	X
17	\$	290.00	X
Torn	\$	48.00	✓
REU	\$	60.00	✓
R		Repair	X
DIS	\$	295.00	✓
CR	\$	75.00	✓
17	\$	60.00	X
CRA	\$	668.00	✓
Bul/Torn	\$	695.00	✓
17	\$	60.00	X
SUC	\$	485.00	✓
Torn	\$	175.00	✓
REU	\$	60.00	✓
NS	\$	110.00	X
SRO	\$	725.00	✓
NS	\$	48.00	X
CWT		800.00	4005.00

Parts : \$

Less Parts 10% : \$

Total Parts : \$

4005.00
6809.00

Special Net Items :

Front Number Plate w/garnish
 Radiator Coolant

ALC Bul	\$	80.00	X
rec	\$	80.00	30
Total S/N Parts :	\$	160.00	

Labour :

To Remove, Repair & Renew Affected Accident Areas
 To Putty, Spray Paint on Affected Accident Areas
 To Check & Re-Connect all electrical wiring

\$	1,200.00	800
\$	1,400.00	900
\$	50.00	30

4896.00
 100
 4226.84

To Remove, Install & Conduct Radiator Pressure Leakage Test
 To Remove, Install AC Condenser & Top Up Gas
 To Conduct Wheel Alignment
 To Rust Proof Affected Areas

\$ 200.00
 \$ 200.00 } 100
 \$ 200.00 60
 \$ 150.00 60

Total Labour : \$ 3,400.00

TOTAL PARTS : \$.
TOTAL SPECIAL NET ITEM : \$ 160.00
TOTAL LABOUR : \$ 3,400.00
TOTAL REPAIR COST : \$

9688.10

P - 4226.85
 S.N - 430.00
 L - 1950.00

 6606.85
 202
 5285

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

9688.10

	P		SN		L	
\$	713.00	\$	400.00	\$	800.00	
\$	310.00	\$	30.00	\$	900.00	
\$	155.00			\$	30.00	
\$	115.00			\$	100.00	
\$	166.00			\$	60.00	
\$	345.00			\$	60.00	
\$	48.00					
\$	48.00					
\$	39.00					
\$	295.00					
\$	75.00					
\$	410.50					
\$	695.00					
\$	438.00					
\$	145.00					
\$	39.00					
\$	660.00					
\$	4,696.50					
	x90%					
\$	4,226.85	\$	430.00	\$	1,950.00	\$ 6,606.85
						x80%
						\$ 5,285.48
						L/sum \$ 5,250.00