

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

Direct Settlement

**CLAIM SUBFOLDER TRACKING**

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Mar 2020 <a href="#">Edit Reg</a>		17 Mar 2020 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$5,250.00</b> <a href="#">Edit Estimates</a>	<b>S\$5,250.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Main Claimant:	PRESTIGE KARZ LEASING PTE LTD		
Vehicle Reg. No.:	SLC8367G	Date of Loss:	12/03/2020 17:00 - :59 [45 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT20030215	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SHA4361G	Policy No. (Claimant):	
		Excess:	
Repairer:	Zoom Autowerkz Pte Ltd (HQ) Blk 15 Kaki Bukit Road 4, #01-53 Bartley Biz Centre, 417808 Kaki Bukit - Tel:		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 27/03/2020]		

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
<ul style="list-style-type: none"> <li>III_SG (06/05/2020): Alert - Adj Mandate Approved (S\$6266.45) - SLC8367G - Claim Handler: Zuhaidah Bt...</li> <li>III_SG (24/03/2020): Alert - Adj Mandate Approved (S\$0.00) - SLC8367G - Claim Handler: Zuhaidah Bte S...</li> </ul>		

ALL ASSOCIATED TASKS	<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SLC8367G (MCT20030215)**  
**[SHA4361G]**  
**TP**  
**PRESTIGE KARZ LEASING PTE LTD**  
**Mar 12 2020 5:00PM**  
**[COMFORT TRANSPORTATION PTE LTD]**  
**Zoom Autowerkz Pte Ltd**

View

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/04/20 15:19	<b>Odometer Reading</b>	Load JPG	<input checked="" type="checkbox"/>
2	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
15	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
16	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
17	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
18	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
19	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
20	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
21	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
22	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
23	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
24	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
25	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
26	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
27	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
28	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
29	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
30	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
31	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
32	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
33	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
34	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
35	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
36	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
37	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
38	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
39	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
40	06/04/20 15:19	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	06/04/20 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
42	06/04/20 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
43	06/04/20 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
44	06/04/20 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
45	06/04/20 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
46	06/04/20 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
47	06/04/20 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
48	06/04/20 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
49	06/04/20 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
50	06/04/20 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
51	06/04/20 15:20	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
52	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	06/04/20 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	06/04/20 15:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
94	06/04/20 15:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
95	06/04/20 15:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
96	06/04/20 15:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
97	06/04/20 15:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
98	06/04/20 15:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
99	06/04/20 15:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
100	06/04/20 15:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
101	06/04/20 15:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
102	06/04/20 15:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
103	06/04/20 15:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
104	24/04/20 10:36	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
105	24/04/20 10:36	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
106	24/04/20 10:36	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/03/20 15:04	ACKNOWLEDGEMENT EMAIL TO INDIA DD17032020	Load PDF	
2	18/03/20 15:04	EMAIL FROM INDIA DD17032020	Load PDF	
3	18/03/20 15:04	TP GIA REPORT	Load PDF	
4	03/04/20 09:52	TP ESTIMATE_MARKED.	Load PDF	
5	06/05/20 08:47	LOD	Load PDF	
6	06/05/20 08:47	Authorisation to Act	Load PDF	
7	06/05/20 08:47	Workshop Invoice	Load PDF	
8	06/05/20 08:47	Rental Agreement	Load PDF	
9	06/05/20 08:47	LTA Search Fee	Load PDF	
10	06/05/20 08:47	GIA Rpt Search Fee	Load PDF	
11	02/06/20 14:56	DISCHARGE VOUCHER	Load PDF	
12	02/06/20 14:56	TOWING FEE	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	19/03/20 09:20	Singapore Accident Statement	Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<input type="button" value="Reset"/> <input type="button" value="Save"/> <input type="button" value="Print"/>
There are no document checklists configured.	

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III20004187/UPS3S2**Date:** 02/06/2020REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant Vehicle No :</b>	SLC8367G	<b>Insured Vehicle No :</b>	SHA4361G
Date of Loss:	12/03/2020	Nature of Claim:	TP
		Claim No:	MCT20030215

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLC8367G</b>	Engine No:	3A92UDC1692
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AHH000409
Reg. Date:	27/05/2016 (Man. Year: 2016)	Odometer:	76816 km
Colour:	Grey		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,288.10	4,656.85	1,631.25	25.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,400.00	1,950.00	1,450.00	42.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,688.10</b>	<b>6,606.85</b>	<b>3,081.25</b>	<b>31.80</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,250.00</b>		
<b>Nett Amount (S\$)</b>	<b>9,688.10</b>	<b>5,250.00</b>	<b>4,438.10</b>	<b>45.81</b>
<b>+ Car Rental (8.0 x S\$100.00/day) (S\$)</b>		800.00		
<b>+ Doc/Search Fee (S\$)</b>		36.45		
<b>+ Other Costs (S\$)</b>		180.00		
<b>Nett Liability (S\$)</b>		<b>6,266.45</b>		

INSPECTION

Date of Assignment:	17/03/2020	Zoom Autowerkz Pte Ltd (HQ)
Date Inspected:	18/03/2020 Inspected At:	Blk 15 Kaki Bukit Road 4, #01-53 Bartley Biz Centre
Estimated Period of Repair:	6.0 days	Singapore 417808

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



**REPAIR DETAILS****Reference**

<b>Part Source:</b>	(Last Synchronised: 02 Jun 2020)	
<b>Parts:</b>	N/A	mitsubishi attrage 1.2 CVT (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLC8367G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	780.00 FL	*713.00 FL
2	1		*FRONT BUMPER FOG LAMP RH	Cracked	310.00 FL	*310.00 FL
3	1		*FRONT BUMPER FOG LAMP GARNISH RH	Cut	155.00 FL	*155.00 FL
4	1		*FRONT BUMPER INNER GARNISH	Cracked	115.00 FL	*115.00 FL
5	1		*FRONT BUMPER LOWER CENTRE GRILLE	Torn	295.00 FL	*166.00 FL
6	1		*FRONT BUMPER REINFORCEMENT	Bent	360.00 FL	*345.00 FL
7	1		*FRONT BUMPER RETAINER RH	Cracked	78.00 FL	*48.00 FL
8	1		*FRONT BUMPER BRACKET RH	No such part	62.00 FL	*- FL
9	1		*FRONT BUMPER LOWER ENGINE COVER	Not Necessary	290.00 FL	*- FL
10	1		*FRONT BUMPER TOW GARNISH	Torn	48.00 FL	*48.00 FL
11	1		*FRONT BUMPER CLIPS	Necessary	60.00 FL	*39.00 FL
12	1		*FRONT BONNET (NPA)	Repair	0.00 FL	*- FL
13	1		*FRONT WIPER WASHER TANK	Distorted	295.00 FL	*295.00 FL
14	1		*FRONT FENDER QUARTER GARNISH RH	Cracked	75.00 FL	*75.00 FL
15	1		*FRONT WIPER PANEL GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
16	1		*FRONT RADIATOR GRILLE ASSY	Cracked	668.00 FL	*410.50 FL
17	1		*FRONT SUPPORT PANEL	Bent / Twisted	695.00 FL	*695.00 FL
18	1		*FRONT RADIATOR GRILLE CLIPS	Not Necessary	60.00 FL	*- FL
19	1		*FRONT FENDER RH	Buckled	485.00 FL	*438.00 FL
20	1		*FRONT FENDER INNER SHIELD RH	Torn	175.00 FL	*145.00 FL
21	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	60.00 FL	*39.00 FL
22	1		*FRONT FENDER BRACKET RH	No such part	110.00 FL	*- FL
23	1		*FRONT HEADLAMP RH	Broken	725.00 FL	*660.00 FL
24	1		*FRONT HEADLAMP BRACKET RH	No such part	48.00 FL	*- FL
25	1		*FRONT SPORT RIM O/S	Cut	720.00 FS	*400.00 FS
26	1		*FRONT NUMBER PLATE W/GARNISH (BENT)	Not Consistent With The Impact	80.00 FS	*- FS
27	1		*RADIATOR COOLANT	Necessary	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,889.00</b>	<b>5,126.50</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	600.90	469.65
<b>Total Parts (\$\$)</b>	<b>6,288.10</b>	<b>4,656.85</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REPAIR & RENEW AFFECTED ACCIDENT AREAS.	New	1,200.00	800.00
2	TO PUTTY, SPRAY PAINT ON AFFECTED ACCIDENT AREAS.	New	1,400.00	900.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING.	New	50.00	30.00
4	TO REMOVE, INSTALL & CONDUCT RADIATOR PRESSURE LEAKAGE TEST. }	New	200.00	100.00
5	TO REMOVE, INSTALL AC CONDENSER & TOP UP GAS. }	New	200.00	0.00
6	TO CONDUCT WHEEL ALIGNMENT.	New	200.00	60.00
7	TO RUST PROOF AFFECTED AREAS.	New	150.00	60.00
			<b>Gross Labour Cost (\$)</b>	<b>1,950.00</b>
			<b>3,400.00</b>	<b>1,950.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >