

87

111 9

not Approved  
LHR  
1/5 @ 5250/

6 days



### ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring  
#08-1339 Singapore 470130  
Tel: 9450 7920  
zoomautowerks@gmail.com

Car Number: SLC8367G

Date: 16/03/2020

Model : MITSUBISHI ATTRAGE

Damaged Area: (Front RH Side Portion)

Repairer Estimation Cost of Repair :

MBSTA13

Supplementary may be included during the cost of repair :

#### Parts / Material :

- 1 Front Bumper 713.00
- 2 Front Bumper Fog Lamp RH
- 3 Front Bumper Fog Lamp Garnish RH
- 4 Front Bumper inner garnish
- 5 Front Bumper Lower Centre Grille 166.00
- 6 Front Bumper Reinforcement 345.00
- 7 Front Bumper Retainer RH 48.00
- 8 Front Bumper Bracket RH
- 9 Front Bumper Lower Engine Cover
- 10 Front Bumper Tow Garnish
- 11 Front Bumper Clips 39.00
- 12 Front Bonnet
- 13 Front Wiper washer tank
- 14 Front fender Quarter Garnish RH
- 15 Front Wiper Panel Garnish Clips
- 16 Front Radiator Grille Assy 410.50
- 17 Front support panel
- 18 Front Radiator Grille Clips
- 19 Front Fender RH 438.00
- 20 Front Fender Inner Shield RH 145.00
- 21 Front Fender Inner Shield Clips 39.00
- 22 Front Fender Bracket RH
- 23 Front Headlamp RH 600.00
- 24 Front Headlamp Bracket RH
- 25 Front sport rim o/s

- DIS \$ 780.00 ✓
- CNE \$ 310.00 ✓
- CWT \$ 155.00 ✓
- CRA \$ 115.00 ✓
- Twin \$ 295.00 ✓
- Bul \$ 360.00 ✓
- OR \$ 78.00 ✓
- NS \$ 62.00 X
- 11 \$ 290.00 X
- Torn \$ 48.00 ✓
- RE \$ 60.00 ✓
- Repair X
- DIS \$ 295.00 ✓
- CM \$ 75.00 ✓
- 11 \$ 60.00 X
- CRA \$ 668.00 ✓
- Bul/Twin \$ 695.00 ✓
- 11 \$ 60.00 X
- SUC \$ 485.00 ✓
- Twin \$ 175.00 ✓
- RE \$ 60.00 ✓
- NS \$ 110.00 X
- SRO \$ 725.00 ✓
- NS \$ 48.00 X
- CW 800.00 4005.00

Parts : \$  
 Less Parts 10% : \$  
 Total Parts : \$

4696.50  
 102  
 4226.84

#### Special Net Items :

- Front Number Plate w/garnish
- Radiator Coolant

A/C Bul \$ 80.00 X  
 Rec \$ 80.00 30  
 Total S/N Parts : \$ 160.00

#### Labour :

- To Remove, Repair & Renew Affected Accident Areas \$ 1,200.00 800
- To Putty, Spray Paint on Affected Accident Areas \$ 1,400.00 900
- To Check & Re-Connect all electrical-wiring \$ 50.00 30

To Remove, Install & Conduct Radiator Pressure Leakage Test	\$ 200.00
To Remove, Install AC Condenser & Top Up Gas	\$ 200.00
To Conduct Wheel Alignment	\$ 200.00
To Rust Proof Affected Areas	\$ 150.00
<b>Total Labour :</b>	<b>\$ 3,400.00</b>

<b>TOTAL PARTS :</b>	\$
<b>TOTAL SPECIAL NET ITEM :</b>	\$ 160.00
<b>TOTAL LABOUR :</b>	\$ 3,400.00
<b>TOTAL REPAIR COST :</b>	\$

P - 4226.85  
 S.N - 430.00  
 L - 1950.00  


---

 6606.85  


---

 202  


---

 5285

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: