

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MR.LIM JIAN ZHI, EDMOND
BLK 981D BUANGKOK CRESCENT #08-03
SINGAPORE 537981

Contact : 97407003

TP FWD

Xiao Tony

ESTIMATE

Repair Code : CLM14908

Date in : 17/03/2020

Vehicle Num. : SJH8315D

Model : TOYOTA WISH 1.8 AUTO

Chassis/Eng# : JTDER12WX03000573/1ZZ3126994

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Defend</i>	1	1277.10	✓ 1,277.10
REAR BUMPER BRACKET L/R <i>new</i>	2	132.20	+ 264.40
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	131.35	✓ 262.70
REAR END LOWER PANEL <i>Defend</i>	1	241.85	✓ 241.85
REAR END PANEL <i>Defend</i>	1	689.75	✓ 689.75
REAR END PANEL INNER TOP GARNISH <i>Defend</i>	1	374.55	✓ 374.55
REAR TAILGATE 'LOGO' EMBLEM <i>new</i>	1	132.25	✓ 132.25
REAR TAILGATE MECHANISM LOCK <i>3 new</i>	1	191.60	+ 191.60
REAR TAILGATE WEATHER STRIP <i>new</i>	1	182.10	+ 182.10
REAR TAILLAMP BACK RUBBER GASKET L/R <i>new</i>	2	42.75	+ 85.50
REAR TAILLAMP L/R <i>new</i>	2	631.30	818 + 1,262.60
REAR TAILLAMP LOWER BRACKET L/R <i>new</i>	2	122.10	✓ 244.20
Subtotal before discount			5,208.60
Percentage discount 25%			1,302.15
Sub-total 1			3,906.45
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	30 50.00
REAR BUMPER REVERSE SENSOR - SET <i>Defend</i>	1	250.00	200 250.00
REAR END PNAEL INNER TOP GARNISH CLIPS - SET <i>new</i>	1	20.00	10 20.00

*** This is a computer-generated document which requires no signature.***

WinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 #01-18 Heavy Vehicle #01-08 Spray Painting #02-27

Singapore 417921 Tel No : +65 6842 0031 Fax No : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg No : 200714616M

GSI Registration No : 200714616M

MR LIM JIAN ZHI, EDMOND

BLK 981D HUANGKOK CRESCENT #08-03

SINGAPORE 537981

Contact : 97407003

ESTIMATE

Repair Code : CLM14908

Date in : 17/03/2020

Vehicle Num : SJH8315D

Model : TOYOTA WISH 1.8 AUTO

Chassis/Eng# : JTDER12WX03000573/1ZZ3126994

REAR TAIL GATE INNER TRIM GARNISH CLIPS - SET	1	50.00	50.00
REAR TAIL LAMP CLIPS L/R - SET	2	20.00	40.00
Subtotal before discount			410.00
Percentage discount : 0%			0.00
Sub-total 2			410.00
Parts-total			4,316.45

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	2,400.00
Parts & Labour Total	6,716.45

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
4/5 18/03/20
05 days

total 4599.65
4/5 3.61K ✓