



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2206285

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 10/10/2022
Reference CC4/FCI20004196/Ea3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SGA 6488Z
Insured Veh. SHC 1637X
Claim No. D20001288MFSH/1
Policy No. D-20094922MFSH
Accident Date 01/03/2020
Inspection Date 19/03/2020

Description	Total
Survey Inspection	201.00
Digital Photographs	
Transportation	
Subtotal	201.00
GST (7%)	14.07
Grand Total	215.07

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20004196/Ea3q2 Date: 10/10/2022 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1637X	Veh. Inspected	SGA 6488Z	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20001288MFSH/1	Excess (\$)	0.00	
Assign From	KAREN TAN	Assign Date	19/03/2020	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 5	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JM6CW1071F0121966	Colour	RED	
Odometer	89409 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	YOKOHAMA	5 mm	
L/H Front Tyre	205/55 R16	YOKOHAMA	5 mm	
R/H Rear Tyre	205/55 R16	YOKOHAMA	5 mm	
L/H Rear Tyre	205/55 R16	YOKOHAMA	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/03/2020	Inspection Date	19/03/2020	
Survey held at	27A TANJONG PENJURU			
Repairer	TRANS EUROKARS PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGA 6488Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	CUT	961.20	961.20
4	GROMMET ,REAR BUMPER	NECESSARY	10.80	10.80
2	GROMMET ,REAR BUMPER	NECESSARY	9.40	9.40
2	GROMMET ,REAR BUMPER	NECESSARY	6.00	6.00
2	FASTENER ,REAR BUMPER	NECESSARY	6.40	6.40
2	FASTENER ,REAR BUMPER	NECESSARY	6.00	6.00
4	RIVET ,REAR BUMPER	NECESSARY	22.80	22.80
			1,022.60	1,022.60
	<u>SPECIAL NETT ITEMS</u>			
	SUNDRIES (SN)	NECESSARY	100.00	20.00
			100.00	20.00
	<u>LABOUR</u>			
	TO REPLACE REAR BUMPER ,REPAIR ALL AREAS AFFECTED BY THE ACCIDENT .		660.00	660.00
	TO RESPRAY REAR BUMPER .		630.00	630.00
	TO TRANSFER REVERSE SENSORS.		330.00	330.00
	TO CARRY -OUT BODY CAVITY PRESERVATION.	NOT NECESSARY	250.00	-
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING		250.00	150.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	180.00
			2,470.00	1,950.00
	GRAND TOTAL		3,592.60	2,992.60
	RECOMMENDED COST OF REPAIRS			2,992.60

Report Ref No. CC4/FCI20004196/Ea3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGA 6488Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

